

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/WZ/2023/ / 09

Dated: 16/03/2023

FIRE SAFETY CERTIFICATE

Certified that M/s. Xero Degree (a unit of G and S Hospitality), G-4, Ground Floor, Pushkar Enclave, Paschim Vihar, New Delhi- 110063, running at Ground Floor in a building comprised of basement, stilt, ground plus three upper floors, owned/occupied by M/s. G And S Hospitality. The premises was inspected by the officer concerned of this department on 10.03.2023 in the presence of Sh. Taranjot Singh (Owner) and observed that the management have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class-"Assembly" Group-D (Restaurant at Ground Floor only) with effect from 16/03/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 16/03/2023 at New Delhi by.

Copy to:-

- 1. The Owner / Occupier, M/s. Xero Degree, G-4, Ground Floor, Pushkar Enclave, Paschim Vihar, New Delhi- 110063.
- 2. The Dy. Health Officer, MCD, Keshavpuram Zone, Public Health Department, New Delhi.
- 3. The Joint Commissioner of Police (Lic.), Police Station Defence Colony, First floor, New Delhi.

INSPECTION REPORT

1. Name & address of the building: M/s. Xero Degree, G-4, Ground Floor, Pushkar Enclave, Paschim Vihar, New Delhi- 110063.

2. Type of Occupancy : Assembly (Restaurant)

3. Type of Case : New Case

4. Details of previous NOC : N/A5. Fire Safety directives letter No : N/A

6. Date of inspection : 10.03.2023

7. Name of the Inspecting Officers: M.K. Chattopadhyay, D.O (West)

8. Name and designation of officers

from the building side : Sh. Taranjot Singh, Owner

9. Year of Construction : 2000 (as per details upload on MHA portal)

10. Applicant's letter No. : Online ID- 2023030403162

The said restaurant is running at ground floor in a building comprised of basement, stilt, ground plus three floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as UBBL / NBC-IV	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	12 mts	Provided	MR		
	Gate width	4.5 mts	Provided	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	-	-	=		
	Upper Floors	02	02	MR -		
	Basements	N/A	N/A	N/A		
	b. Width of staircases	-:	-	M=		
	 Upper Floors 	1.5 mts each	Provided	MR -		
	 Basements 	N/A	N/A	N/A		
	c. Protection of exits • Fire check door	-	-	-		
		N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	02	Provided	MR		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	02 x 1.5 mts.	Provided	MR		
3	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	N/A	N/A		
	Upper floors	12 a/c per hour	Openable window	MR		







5	Fire Extinguishers				
	Total numbers	08 nos.	Provided	MI	
	• Types	CO ₂ , ABC type	Provided	MF	
	IS marking	ISI marked	Provided	MR	
6	First-Aid Hose Reels.				
	Total numbers on each floor	01	Provided	MR	
	Length of hose reel hoseNozzle diameter	30 m	Provided		
		5 mm	Provided	MF MR	
	Automatic fire detection and alarming system.				
	Type of detectors				
	 Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A		N/A	
		N/A	Ground floor N/A	N/A	
		N/A	N/A N/A	N/A	
		N/A	Provided Provided	N/A	
	MOEFA	Required	Provided	N/A	
	Public Address System.	N/A	N/A	MR	
0	Automatic Sprinkler System.		IN/A	N/A	
	Basement	N/A	Described		
	Entire Restaurant	N/A	Provided Provided	N/A	
	 Sprinkler above false ceiling 	N/A		N/A N/A	
1	Internal Hydrants				
	 Size of riser/down-comer Number of hydrants per floor Hose Box 	100 mm	Provided	MR	
		01	Provided		
		01	Provided	MR MR	
2	Yard Hydrants.				
	Total number of hydrantsHose Box	N/A	N/A	N/A	
		N/A	N/A	N/A	
3	Pumping Arrangements.				
	Ground Level				
	 Discharge of main Pump 	N/A	N/A	N/A	
	 Head of Main pump 	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head Standby Pump out put	N/A	N/A	N/A	
	- miles y ramp out put	N/A	N/A	N/A	
	Tanady rump ricau	N/A	N/A	N/A N/A	
	Auto Starting/ Manual stopping Pump House Access	N/A	N/A	N/A N/A	
	Terrace level	N/A	N/A	N/A	
	Discharge of pump				
	Head of the pump	450 LPM	Provided	MR	
	Power Supply	40 mts	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
	B or bamb	Required	Provided	MR	

*

N

4	Captive Water Storage for fire fighting.					
	 Underground tank capacity 	N/A	N/A	N/A		
	 Draw-off connection 	N/A	N/A	N/A		
	➤ Fire service inlet	N/A	N/A	N/A		
	➤ Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	20,000 lts	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	 Pressurization of Lift Shaft 	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	 Lift Signage 	N/A	N/A	N/A		
17	Standby power supply	Not Required	Provided	N/A		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	Not Required	Provided	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were randomly test checked at the time of inspection and found functional.

Note: 1. All the shortcomings issued by this department vide letter No. F6/DFS/MS/EH/WZ/2023/35 dated 19.01.2023 has been complied with by the management.

2. The upper floors in the building are being used as First Floor (Miraco Restaurant), Second Floor (SPA centre) and Third Floor (Offices).

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

DFA is put up for approval & signature please.

Divisional Officer (West)