

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F.6/DFS/MS/WZ/2023/EH 111

Dated: - 23/03 2023

FIRE SAFETY CERTIFICATE

Certified that the 2 Cubes (A Unit of DVSAA Hospitalities LLP) located at plot no A-37, Ground Floor, Vishal Enclave, Rajouri Garden, New Delhi -110027 running at Ground Floor only in a building comprised of Basement + Ground + 03 Upper Floor, Owned/Occupied by 2 Cubes A Unit of DVSAA Hospitality LLP) was inspected by the officers concerned of this department on 22/02/2023 in the presence of Sh. Tarun Kumar (Partners) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly" Group D (Ground Floor Only) with effect from 23/03/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions printed overleaf.

Issued on 23 103 12023 at New Delhi by.

Copy to: -

- 1. The owner/occupier, 2 Cubes (A Unit of DVSAA Hospitalities LLP) located at plot no 37, Ground Floor, Vishal Enclave, Rajouri Garden, New Delhi -110027. Online Application ID no. 2023020101387 dated 01/02/2023
- The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. (addlep.lic-dl@nic.in.)
- 3. The Dy. Health Officer, MCD, West Zone, Vishal Enclave, Rajouri Garden, New Delhi-
- 4. The Chief Electrical Inspector, Labour Department, GNCT of Delhi, 05, Shamnath
 - -The Owner/occupier of the 2 Cubes restaurant have sealed the lift in basement & ground floor by brick wall & the same may be verified time to time & intimate this deptt. if the brick wall is opened in future.
- 5. The Executive Engineer (Bldg), MCD, Vishal Enclave, Rajouri Garden, New Delhi.
 - -The Owner/occupier of the 2 Cubes restaurant have sealed the passage of staircase by brick wall opening to the restaurant at ground floor & submitted an undertaking that the basement floor will not be used for restaurant purpose. The same may be verified time to time & intimate this deptt, if the passage is opened & use the basement floor as

+ 03 upper floors. A Guest house in the name of Maharaja is running First floor (06 rooms), Second floor (06 rooms) & 3rd floor (04 rooms) was issued FSC by this department vide letter No. F6/DFS/MS/GH/2021/SZ/464 dated 08/10/2021.

S. No.		inimum Standards on fire ention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMI		
1	Access to building						
	•	roug wight	12 m	Provided	MR		
	•	oute main	4.5m	On Main Road	MR		
	•	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	•	Upper Floors	NA	At Ground floor	NA		
	•	Dasements	NA	NA	NA		
	b. Width of staircases						
	•	Upper Floors	NA	NA	NA		
		Basements	NA	NA	NA		
		tection of exits					
	•	Fire check door	NR	NR	NR		
	. N.	Pressurization	NA	NA	NA		
		of continuous staircases to terrace th of Corridor	NA	NA	NA		
		r Size	NR	NR	NR		
+	200		1.5m x 2	Provided	MR		
-	Comp	artmentation.					
	•	Fire check door	NA	NA	NA		
	•	Sealing of electrical shafts	NA	NA	NA		
	•	Fire Rating of shaft door	NA	NA	NA		
	•	Water Curtain	NA	NA	NA		
-	•	Fire Dampers	NA	NA	NA		
	Smoke Management System.						
	•	Basements	NA	NA	NA		
	•	Upper floors	NA E	Exhaust fan provided in kitchen	NA		
1	Fire Extinguishers						
	•	Total numbers	05	Provided	MR		
		Types	CO2, ABC type	Provided	-		
	•	IS marking	ISI marked	Provided	MR MR		

	2/12						
6	First-Aid Hose Reels.						
	 Total numbers on each floor 	01	Provided	MR			
	 Length of hose reel hose 	30m	Provided	MR			
Throng T	Nozzle diameter	5mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	 Type of detectors 	NR	Smoke & Heat Provided	NR			
	Location of Main Panel	NR	Provided	NR			
	Location of Repeater Panel	NR	NR	NR			
	 Alternate source of power Hooters' Location 	NR	Provided	NR			
		NR	Provided	NR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	NR	NR	NR			
10	Automatic Sprinkler System.						
	Basement	NA	Provided	NA			
	Upper Floor	NA	Provided	NA			
	 Sprinkler above false ceiling 	NA	NA	NA			
11	Internal Hydrants						
	 Size of riser/down-comer 	100 mm	Provided	MR			
	 Number of hydrants per floor 	01	Provided	MR			
	Hose Box	01	Provided	MR			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level	T					
	 Discharge of main Pump 	NR	NR	MD			
	> Head of Main pump	NR	NR NR	NR NR			
	Number of main pumps	NR	NR NR	NR			
	Jockey Pump out put	NR	NR	NR			
	Jockey pump head	NR	NR	NR			
	Standby Pump out put	NR	NR	NR			
	Standby Pump Head	NR	NR	NR			
	> Auto Starting/ Manual stopping	NR	NR	NR			
	Pump House Access	NR	NR	NR			
	Terrace level						
	Discharge of pump	450lpm	Provided	MR			
	Head of the pump	40 m	Provided	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
4	Captive Water Storage for fire fighting.						
	Underground tank capacity	NR	NR	NR			
	 Draw-off connection 	NR	NR	NR			
	> Fire service inlet	NR	NR	NR			
	Access to tank	NR	NR	NR			
	 Overhead Tank capacity 	20,000 ltrs	Provided	MR			
	Exit Signage.	Required	Provided	MR			
		,					

		NIS					
16	Provision of Lifts.						
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car 	NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
	Fireman's Grounding Switch	NA	NA	NA			
	Lift Signage	NA	NA	NA			
17	Standby power supply	NA	NA	NA			
18	Refuge Area.						
	> Total Area	NA	NA	NA			
140	Location	NA	NA	NA			
19	Fire Control Room						
	Detector System Panel	NA	NA	NA			
	Flow Switch Panel	NA	NA	NA			
	PA System Panel Batter backup Building Floor Plans	NA	NA	NA			
		NA	NA	NA			
73		NA	NA	NA			
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA			

* The Owner/Occupier has given undertaking that they closed the lift at basement & ground floor by brick wall. & basement floor shall not be use for restaurant purpose. Photo of the same is placed on opposite side. If it is used FSC shall be null & void. Photographs are enclosed.

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcoming issued by this department vide letter no. F6/DFS/MS/EH/WZ/2022/762 dated 28/12/2022 has been complied.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

- 9 6 h

Signature of the Inspecting Officer Name: - M. K. Chattopadhyay

Designation: - DO (West)

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

Ch (DPB)

018) 1020

10 30 3023

Dênedar Allo 103 173

Playlor

P. T.O.

50 6/2 CE