

OVER MENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No: F.6/DFS/MS/WZ/EH/2023/133

Dated: - 27/04/2023

## FIRE SAFETY CERTIFICATE

Certified that M/s. Pizza Express Restaurant (a unit of Gourmet Investment Pvt. Ltd.) located at Shop No. 01, Ground Floor, Vishal Cinema Building located at Plot No. 01, District Centre, Rajouri Garden, Shivaji Place, New Delhi, is running at ground floor in a building comprised of 02 basement, ground plus four upper floors, was inspected by the officer concerned of this department on 15.04.2023 in presence of Sh. Jagdish, V.P. (Project) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class Assembly (Group- D) (Restaurant only) with effect from  $\frac{27|04|2023}{2023}$  for a period of 03 (three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27/04/2023 at New Delhi by.

Copy to: -

- The Owner/Occupier, M/s. Pizza Express Restaurant, Shop No. 01, Ground Floor, Vishal Cinema Building, Plot No. 01, District Centre, Rajouri Garden, Shivaji Place, New Delhi.
- 2. The Deputy Health Officer, West Zone, MCD, Rajouri Garden, New Delhi.
- The Joint Commissioner of Police, Licensing Unit, 1<sup>st</sup> Floor, Defence Colony Police Station, New Delhi.

## NII

## **INSPECTION REPORT**

1.	Name & address of the building	<ul> <li>Pizza Express, GF-01, Vishal Cinema Building Plot No. 1, District Centre, Rajouri Garden, Shivaji Place, New Delhi</li> </ul>
2.	Type of Occupancy	: Assembly
3.	Type of Case	: New Case
4.	Details of previous NOC :	F.6/DFS/MS/2023/79 dated 14.02.2023- for Vishal Cinema Building
5.	Fire Safety directives letter No	: F.6/DFS/MS/BP/2017/222 dt. 21.07.2017
6.	Date of joint inspection	: 15.04.2023
7.	Name of the Inspecting Officers	s : M.K. Chattopadhyay, DO (West)
8.	Name and designation of officer from the building side	rs : Jagdish, V.P. (Project)
9.	Year of Construction	: 2021-22
10	Applicant's letter No.	: MHA ID-2023040405166

The said restaurant is running at Ground Floor in a building comprised of two basements, ground plus four upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ UBBL Requirement/ guideli dated 21.07.2017	nes Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	12 mts	Provided	MR		
	Gate width	06 mts	Provided	MR		
	• Width of internal road	06 mts	Provided as per Sanctioned Plan	MR		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	NA	Restaurant running at GF only	NA		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper Floors	NA	Restaurant running at GF only	NA		
	Basements	NA	NA	NA		
	c. Protection of exits					
	<ul> <li>Fire check door</li> </ul>	NA	NA	NA		
	<ul> <li>Pressurization</li> </ul>	NA	NA	NA		
	e. No. of continuous staircases to terrace	NA	NA	NA		
	g. Width of Corridor	NA	NA	NA		
	h. Door Size	2.0, 1.5 mts	2.03, 1.83, 0.94 mts	MR		
;	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
	Smoke Management System.		Provided	MR		
	Basements/ Lower Ground	Required Required	Provided	MR		
	Upper floors	Required		1		
	Fire Extinguishers	06.005	Provided	MR		
	Total numbers	06 nos.	Provided	MR		
	<ul><li>Types</li><li>IS marking</li></ul>	ABC, CO <sub>2</sub> type ISI marked	Provided	MR		

Prov	vided by build	ing management
each floor	01	Provided
	20	

First-Aid Hose Reels-

6

)	First-Ald Hose Reels-	lucu by building h	uanagement	•	
	Total numbers on each floor	01	Provided	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR	
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR	
,	Automatic fire detection and alarming	g system		MIX	
	Type of detectors	Smoke & Heat	Provided	MR	
	<ul> <li>Location of Main Panel</li> </ul>	Restaurant	Provided	MR	
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A	
4	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR	
	<ul> <li>Hooters' Location</li> </ul>	Required	Provided	MR	
3	MOEFA	Required	Provided	MR	
, )	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System	1			
	Ground Floor (Restaurant)	Required	Provided	MR	
	Upper Floor	N/A	N/A	N/A	
	<ul> <li>Sprinkler above false ceiling</li> </ul>	NA	NA	NA	
			INA	INA	
1	Internal Hydrants - Provided by buil • Size of riser/down-comer	100 mm	Provided	MR	
	<ul> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> </ul>	01		MR	
	<ul> <li>Number of nydrants per floor</li> <li>Hose Box</li> </ul>	01			
		01	Provided	MR	
12	Yard Hydrants.	27/4		N1/A	
	Total number of hydrants	N/A		N/A	
	Hose Box	N/A	1-0	N/A	
13	Pumping Arrangements- Provided b		agement		
	Ground Level		Provided by building managemen	- A Collopage and	
	<ul> <li>Discharge of main Pump</li> </ul>	2850 LPM 90 mts	Provided by building managemen	IVIIX	
	Head of Main pump	90 mts 02 +01 for water	Provided by building managemen	IVIA	
	Number of main pumps	curtain	P. 11.11. h. (blins managemen		
	<ul> <li>Jockey Pump out put</li> </ul>	02 x 180 LPM	Provided by building managemen Provided by building managemen	IVIIX	
	<ul> <li>Jockey pump head</li> </ul>	90 LPM	Provided by building managemen	IVIIX	
	Standby Pump out put	2850 LPM	Provided by building managemen		
	Standby Pump Head	90 mts	Provided by building managemen		
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	Required	Provided by building managemen		
	<ul> <li>Terrace level</li> </ul>	Required			
	<ul> <li>Tenace level</li> <li>Discharge of pump</li> </ul>	 NI/A	N/A	N/A	
	<ul> <li>Head of the pump</li> </ul>	N/A	N/A N/A	N/A	
	<ul> <li>Power Supply</li> </ul>	N/A N/A	N/A N/A	N/A	
	<ul> <li>Auto Starting of pump</li> </ul>	N/A N/A	N/A N/A	N/A	
14	N/A N/A				
14	Underground tank capacity	2,00,000 lts	Provided by building managemen	t MR	
	<ul> <li>Draw-off connection</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Fire service inlet</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Access to tank</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Overhead Tank capacity</li> </ul>	20,000 lts	Provided by building managemen		
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.			N/A	
	Pressurization of Lift Shaft	N/A	N/A	N/A N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A N/A	N/A	
	<ul> <li>Lift Signage</li> </ul>	N/A	N/A	/	

t

Res

8/

62

NB

1- F	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
-	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Fire protection system provided in Kitchen hood	MR	

The fire protection systems provided in the building were randomly test checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

DFA is put up for approval & signature please.

M.K. Chattopadhyay Divisional Officer (West Division)

CAS (DPG)

2003 28

Directo

T. letter is put up for Sign please Direc