

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE; CONNAUGHT PLACE NEW DELHI-110001

No. F 6/DFS MS/EH/2023/SZ/167

Dated 61/66/2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & Style of M/s McDonald's Family Restaurant located at Ground, Mezzanine & First Floor, 47, Basant Lok Vihar, New Delhi 110057 in the building comprised of Basement, Ground, Mezzanine plus Three upper floors (2nd & 3rd Floors are others property) owned/occupied by A Ms Connaught Plaza Restaurant Pvt Ltd WHS issued Fire: Safety Certificate by this department vide F 6/DFS/MS/EH/2020/SZ/116 dated 04/08/2020. The restaurant premise was re-inspected by the officer concerned of this department on 27/05/2023 in the presence of Mr. Tariq and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant running Ground, Mezzanine & First Floor only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 01 / 06 /2023 at New Delhi by

DIRECTOR DELHI FIRE SERVICE

Copy to
1 The Dy Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016
(Ref. MHA Portal ID 2023040505319 dated 16/05/2023)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting system.

4 The basement shall be used as per the provisions of BBL /NBC Part- IV.

5 The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010 The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

any

 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form "J" [sub-rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

| | | be link | 7/- | | | |
|-----|--|---|------------------------------|----------------|--|--|
| | INSPECTI | ON REPORT | - Perception | | | |
| | Name & Address of the Building | - | S FAMILY DECEME | गरोनाव | | |
| | Type of Occupancy | Mc DONALD'S FAMILY RESTURANT located a 47. Basant Lok, Vasant Vihar, New Delhi-110057 Group-D Assembly Building (Restaurant) B+G+Mezz+03 upper floors (2 nd & 3 nd floors are othe property) | | | | |
| | Building Comprised of | | | | | |
| | Dunding Comprised of | | | | | |
| | Type of Case | | | | | |
| 1 | Details of Previous NOC | Renewal | 3.0 | | | |
| | Fire Safety Directives Letter No | F 6/DFS/MS/EI | 1/2020/SZ/116 dated 0- | 1/08/2020 | | |
| | Date of Inspection | Cir No.F 6/DFS/EH/MS/ 2005/718 dated 04/04/2005 | | | | |
| | Name of the Inspecting Officers | 27/05/2023 | | | | |
| , | Name & Designation (COM) | DO (South) & ADO (BCP) | | | | |
| 100 | Name & Designation of Officers from the building side | Mr. Tanq | | | | |
| 0 | Year of construction | | | | | |
| 1 | Applicant letter No. | 1990 Eating h | ouse at GF, Mezz. & Firs | t Floor only \ | | |
| | | MHA Portal ID 2023040505319 dated 16/05/2023 | | | | |
| No. | Minimum standards on Fire Prevention | Old NOC | Provided at Site | Remarks | | |
| | and Fire Safety U/R 33 | requirements | | MR/NMR | | |
| 1 | Access to Building. | | | , ALIO IN THE | | |
| | Road width | Required | 9m | MR | | |
| | Gate width | N/A | N/A | N/A | | |
| | Width of internal road | N/A | N/A | N/A | | |
| 2 | Number, width, type & arrangement of ex | its. | 1 | AMOCA | | |
| | a) Number of Staircase | T | | | | |
| | > Upper floors | 02.87 | 1 2200 | | | |
| | Basement floor | 02 Nos | 02 Nos | MR | | |
| | b) Width of Staircase | 02 Nos | 02 Nos | MR | | |
| | > Upper floors | 1 08 & 1 18m | 1 1000 100 | | | |
| | > Basement floor | 1 08 & 1 m | MARKETAS (SESSION) | MR (old case | | |
| | c) Protection of exits | 1 08 & 1m | 1.08 & 1m | MR (old case | | |
| | > Fire check door | N/A | 1 37/4 | No. | | |
| | > Pressurization | N/A | N/A | N/A | | |
| | d) No. of continuous staircase to terrace | Required | N/A One | N/A | | |
| | e) Width of corridor | N/A | N/A | MR | | |
| | f) Door size | N/A | N/A | N/A N/A | | |
| 3 | Compartmentation. | | 49/4 | N/A | | |
| | | 51/4 | 1 2000 | | | |
| | Fire check door | N/A | N/A | N/A | | |
| | Sealing of electrical shafts. | N/A | N/A | N/A | | |
| | Fire rating of shaft door | N/A N/A | N/A | N/A | | |
| | Water curtain Fire description | | N/A | N/A | | |
| 4 | Fire dampers Smoke Management system | N/A | N/A | N/A | | |
| _1 | Smoke Management system. | | | and the second | | |
| | Basement | 30 ACPH | Exhaust Fans Provided | MR | | |
| | Upper floors | 12 ACPH | Exhaust Fans Provided | MR | | |
| 5 | | (MANAGE) | | | | |
| | Total numbers | 08 Nos | 08 Nos | MR | | |
| 6 | Types | ABC/CO ₂ | ABC-05 & CO ₂ -03 | MR | | |
| | ISI Marking | ISI marked | Provided | MR | | |
| | First Aid Hose Reels. | | | | | |
| | Total numbers on each floor. | One | One | MR | | |
| | Length of hose-reel hose. | 30m | 30m | MR | | |
| | Nozzle Diameter | 5mm | 5mm | MR | | |
| 7 | Automatic fire detection & alarming syst | em. | | | | |

| 7/- | |
|-------------------|-------|
| आजादी क अमृत म | होत्र |
| 20.5. | |

| | | | | | 100 | 411 |
|---|----------|--|------------------------------|----------------|---------|-----|
| | | | | N/A | N/A | 1 |
| | | | N/A | N/A | N/A | |
| | T | Type of detectors | N/A | N/A | N/A | |
| | 11 | Location of Main Panel | N/A | N/A | N/A | |
| | 100 | Location of Repeater Panel | N/A | | N/A | |
| l | | Alternate source of power | N/A | N/A | MR | 1 |
| ١ | - | Hooter's location | Required | Provided | N/A | 1 |
| 1 | 8 | MOEFA | N/A | N/A | 144.1 | 1 |
| - | 9 | Public Address System | | manufacture of | M/R | 1 |
| | 10 | Automatic Sprinkler System | Required | Provided | M/R | 1 |
| | 10 | Basement | Required | Provided | N/A | 1 |
| | | Ground floor. | N/A | N/A | N/A | 1 |
| 1 | | Sprinkler above false ceiling | | THE PERSON | 100 | 1 |
| 1 | 11 | Internal Hydrants. | Required | 100 mm | MR | 1 |
| | | Size of Riser/Down-comer | Required | One | MR MR (| 1 |
| h | | Number of Hydrant per floor | Required | One | MR C | - |
| | I THE IS | Hose box. | | | | + |
| | 12 | Yard Hydrants. | N/A | N/A | N/A | 1 |
| | | Total number of hydrants. | N/A | N/A | N/A | |
| | | Hose box. | | | | 1 |
| | 13 | Pumping arrangements. | and the second second second | | | |
| | | Ground Level | N/A | N/A | N/A | |
| | | > Discharge of main pump. | N/A | N/A | N/A | |
| | 12 | Head of main pump. Number of main pumps. | N/A | N/A | N/A | 1 |
| | 100 | Number of main pumps. Jockey Pump output. | N/A | N/A | N/A | 1 |
| | | > Jockey Pump head. | N/A | N/A | N/A | 1 |
| | | > Standby Pump output. | N/A | N/A | N/A | 1 |
| | 1 | > Standby Pump head. | N/A | N/A | N/A | 1 |
| | | Auto Starting/Manual Stopping. | N/A | N/A | N/A | 1 |
| | | > Pump house access. | N/A | N/A | N/A | 1 |
| | | | 19/24 | NA. | | + |
| | | Terrace Level Discharge of pump. | 450 LPM | 450 LPM | MR . | 1 |
| | | Head of pump. | 35m | 35m | MR | 1 |
| | | > Power supply. | Required | Provided | M/R | 1 |
| | | > Auto starting of pump. | Required | Provided | M/R | 1 |
| | 14 | Captive water storage for fire fighting. | | | | 1 |
| | | Underground tank capacity. | N/A | N/A | N/A | 1 |
| | | Draw-off connection. | N/A | N/A | N/A | 1 |
| | | Fire Service Inlet. | N/A | N/A | N/A | 1 |
| | | Access to tank. | N/A | N/A | N/A | 1 |
| | | Overhead tank capacity. | 5,000 Ltrs | 10,000 Itr | MR / | 1 |
| | 15 | | Required | Provided | MR | 1 |
| | 16 | Trovision of Little | | | | 1 |
| | | Pressurization of lift shaft. | N/A | N/A | N/A | 1 |
| | No. | Pressurization of lift lobby. | N/A | N/A | N/A | 1 |
| | 100 | Communication in lift car. Fireman's switch | N/A | N/A | N/A | 1 |
| | - | Fireman's switch. Lift signage. | N/A | N/A | N/A | 1 |
| | 17 | Standby Power Supply | N/A | N/A | N/A | 1 |
| | 18 | | Required | Provided | MR · | 1 |
| | | | * | | | 1 |
| | | Total area Location | N/A | N/A | N/A | - |
| | 19 | | N/A | N/A | N/A | + |
| | | , and the state of | | | NO. | 4 |
| | | | | | | |

आजादी का अमृत महोत्नाय ोत्सत N/A N/A N/A Detector system panel N/A N/A N/A N/A Flow switch panel N/A N/A N/A PA system panel. N/A N/A N/A Battery backup. N/A N/A N/A Building floor plan Special Fire Protection System for the N/A N/A 20 N/A Protection of special Risk, if any. M/s McDonald's Family Restaurant at 47, Basant Lok, Vasant Vihar, New Delhi-110057 Renewal The Fire protection systems provided in the building were checked / operated and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/ 2020/SZ/116 dated 04/08/2020, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended. Accordingly DFA is put up for approval and signature please. Signature of the Inspection Officer Signature of the Inspecting Officer Name Sh. Rajesh Kumar Name: \$h. Manoj Kumar Sharma Design ADO (BCP) Design DO (South)

NIA

N/

1

letter u prohip