

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F 6/DFS/MS/EH/2023/SZ/ 20 2

Dated 23/06/2023

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s AKUS The Burger Co located at G-02, Ground Floor, PVR Priya, Plot No 61, Basant Lok Vasant Vihar, New Delhi-110057 in the building comprised of Basement, Ground plus Two Upper Floors owned/occupied by 279 Restaurants and Foods Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 16/06/2023 in the presence of Mr. Pardeep Kumar and that the premise is fit for occupancy class Group-D Assembly Building (Restaurant at Ground Floor only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 33 / 6 6 /2023 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal ID 2023050308121 dated 11/06/2023)

## Conditions for the validity of Fire Safety Certificate: -

- All the means of escape/entry/exit shall be kept free from any obstruction. 1.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic in
- This fire safety certificate may not in any way be treated as regularization (Clause 2 8 of 2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

,	INSPECTI	ON REPORT	0		
ì	Name & Address of the Building	M/s AKUS The Burger Co. (279 Restaurants and Foods Pvt Ltd) located at G-02, Ground Floor, PVR Priya, Plot No 61, Basant Lok Vasant Vihar, New Delhi-110057			
2	Type of Occupancy		ilding "Group-D" Restaur	unt Floors	
3	Building Comprised of	Basement, Ground plus Two Upper Floors, Restaurant at Ground Floor floors only			
	Type of Case	New Case			
4	Details of Previous NOC	Nil			
5	Fire Safety Directives Letter No	F6/DFS/MS/2	2021/SZ/150 dated 05/02/2	2021 for PVR	
6		Priya Cinema. 16/06/2023			
7	Date of Inspection	1.171.540.05.000 v25.000 v25.000.00	ADO (RCP)		
8	Name of the Inspecting Officers		ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Pardeep Kumar			
10	Year of construction	2000			
11	Applicant letter No.	MHA Portal I	D 2023050308121 dated 1		
S. No.	Minimum standards on Fire Prevention and Fire Sufety U/R 33	Requirement/ Provided at Site Remark Existing Fire MR/NM		MR/NMR	
1	Access to Building, FSC No. F6/DFS/MS	/2021/SZ/150 d	ated 05/02/2021 for PVR P	riya Cinema.	
_	Road width	9m	Provided*	IVIK	
	Gate width	6m	Provided*	MR	
	Width of internal road	NA	Provided*	MR	
2	Number, width, type and arrangements o	f exits.			
2_	a. Number of Staircase Provided & Maintained by PVR Priya Cinema				
	• Upper floors	2 Nos	Provided*	MR	
	Basement floor	2 Nos	Provided*	MR	
	b. Width of Staircase	Provided in PVR Priya Cinema			
	• Upper floors	1.50 mtr each		MR	
	Basement floor	1.50 mtr each	1.4m, 2m & 1.5m	MR	
		Pro	ovided in PVR Priya Cinem	a	
	Fire check door	Required	Provided*	MR	
	Pressurization	Required	Provided*	MR	
		Required	Provided*	MR	
	The second second second second	N/A	N/A	N/A	
	f. Door size	2 x 1.50 mtr	1.50 mtr & 1.50 mtr	MR	
3	Compartmentation.		Maintained by PVR Priya	Cincula	
3	Fire check door.	Required	Provided*	MR	
	Sealing of electrical shafts.	Required	Provided*	MR	
	Fire rating of shaft door	2 hrs	Provided*	MR	
	Water curtain	N/A	N/A	N/A	
	Fire dampers	N/A	N/A	N/A	
	Smoke Management system.		Maintained by PVR Priya	Cinema	
4.	Basement	Required	Provided*	MR	
	Upper floors	Required	Exhaust fans provided	MR	
5.	Fire Extinguishers.				
33.8	• Total numbers	03 Nos	04 Nos.	MR	
	Types		ABC-02, W.CO <sub>2</sub> -02	MR	
	ISI Marking	ISI marked	Provided	MR	
6.	First Aid Hose Reels.	Provided &	Maintained by PVR Priya	a Cinema	
0.			01 in Restaurant	MR	
	Total numbers on each floor	Hose Reel	30m	MR	
	<ul> <li>Length of hose-reel hose.</li> </ul>			MR	

Hist	ret	ini		ĺ.
		महो	(31	1

7	Automatic Fire Detection and Alarmin	g system.			
	<ul> <li>Type of detectors</li> </ul>	Required	Smoke & Heat	M	
	<ul> <li>Location of Main Panel</li> </ul>	Required	Provided*	M	
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/	
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided*	Ni	
	<ul> <li>Hooter's location</li> </ul>	Required	Provided*	MI	
8.	MOEFA	Required	Provided*	MI	
9.	Public Address System	Required	Provided*	MI	
10.	Automatic Sprinkler System		& Maintained by PVR P	- F-540719	
	Basement	Required	Provided*	MF	
	Upper floors	Required	Provided in Restt.	MR	
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A		
11.	Internal Hydrants.			N/A	
201247	Size of Riser/Down-comer	Required	Maintained by PVR Pr		
	Number of Hydrant per floor			MR	
	Hose box.	Required	Provided*	MR	
12	Yard Hydrants.	Required	Provided*	MR	
	The second of th	Provided &	Maintained by PVR Pr		
	<ul> <li>Total number of hydrants.</li> <li>4. Hose box.</li> </ul>	Required	Provided*	MR	
11	The state of the s	Required	Provided*	MK	
15.		umping arrangements.			
9. 10. 11. 12.	Ground Level		Provided & Maintained by PVR Priya C		
	<ul> <li>Discharge of main pump.</li> </ul>	2280 LPM	Provided*	MR	
	Head of main pump.	70 mtr	Provided*	MR	
	Number of main pumps.	Two	Provided*	MR	
	Jockey Pump output.	180 LPM	Provided*	MR	
	Jockey Pump head.	70 mtr	Provided*	MR	
	Standby Pump output.     Standby Pump head	2280 LPM	Provided*	MR	
	Tanip nead.	70 mtr	Provided*	MR	
	<ul> <li>Auto Starting / Manual Stopping</li> <li>Access to pump house</li> </ul>	Required	Provided*	MR	
		Required	Provided*	MR	
	Terrace Level	Provided &	Maintained by PVR Priy	a Cinema	
	Discharge of pump.	900 LPM	Provided*	MR	
	Head of pump.     Power supply.     Auto starting of pump.	35 m	Provided*	MR	
		Required	Provided*	MR	
4	rate starting of pump.	Required	Provided*	MR	
•	Captive water storage for Fire Fighting.	Provided & Maintained by PVR Priva Cinema			
	Underground tank capacity.     Draw-off connection.	2,00,000 Ltrs	Provided*	MR	
	Brun-ott connection.	Required	Provided*	MR	
	Fire Service Inlet. Access to tank.	Required	Provided*	MR	
	Overhead tank capacity.	Required	Provided*	MR	
5.	Exit Signage.	20,000 Ltrs	Provided*	MR	
	Provision of Lifts.	Required	Provided	MR	
		Provided & N	Maintained by PVR Priya	Cinema	
	Treasure of the shart.	Required	Provided*	MR	
	Tressurization of fift lobby.	Required	Provided*	MR	
	Communication in lift car.	Required	Provided*	MR	
	Fireman's switch.     Lift signage.	Required	Provided*	MR	
7	Standby Power Supply	Required	Provided*	MR	
8.	Refuge Area	Required	Provided (DG Set)	MR	
			, 200,	with	
	Total area	N/A	N/A	N/A	
	• Location	N/A	N/A	N/A	
9.	Fire Control Room.	Provided & M	\$1000 may		
	Detector System Panel.	Required	aintained by PVR Priya	The second secon	
		Junea	Provided*	MR	

m



	Flow Switch Panel.     PA system Panel.	Required	Provided*	MR
	Battery backup	Required Required	Provided*	MR MR
20,	Building floor plan	Required	Provided*	MR
	Special Fire Protection System for the Protection of special Risk, if any:	Required	Provided*	MR

- \*Fire Safety arrangements Provided & Maintained by PVR Priya Cinema

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Office

Name Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

As approved, F.7 better in putup for your