

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001**

No. F.6/DFS/MS/Hospital/2023/SZ/ 392

Dated: 14 /08 /2023

FIRE SAFETY CERTIFICATE

Certified that the Max Super Speciality Hospital situated at Plot No. 2, Press Enclave Road, Saket, New Delhi-110017 comprised of Two Basements, ground and service floor plus six upper floors owned/occupied of A unit of Devki Devi Foundation was issued FSC by this department vide letter no. F6/MS/DFS/Hospital/SZ/2020/531 dated 21/12/2020. The premise was re-inspected by the officer concerned of this department on 26.07.2023 in the presence of Mr. Dharmender Kumar (Group Head /External Affairs) and found deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group C "Institutional (Hospital)" with effect 14 08 2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on 14 08 200 at New Delhi by.

Copy to:-

1. Sh. Dharmender Kumar, Group Head/ External Affairs, Max Super Speciality Hospital situated at Plot No. 2, Press Enclave Road, Saket, New Delhi-110017.

2. Executive Engg. (Bldg.), Municipal Corporation of Delhi 9th Floor, Civic Center, Minto Road, New Delhi 110002.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL /NBC Part- IV.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first available The form is 2010. Rules Service Fire of Delhi schedule www.dfs.delhigovt.nic.in.

6. This fire safety certificate may not in any way be treated as regularization of unauthorized

construction, if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



INSPECTION REPORT

1. Name & address of the building: Max Super Speciality Hospital (A unit of Devki Devi Foundation), 2 Press

Enclave Road, Saket, New Delhi-110017.

2. Type of Occupancy : Institutional "Group-C"

3. Type of Case : Renewal

4. Comprised of : 02 Basement, Ground & Service Floor plus Six Upper Floors

5. Details of Previous NOC : F6/MS/DFS/Hospital/SZ/2020/531 dated 21/12/2020

6. Fire Safety directives letter No : F6/DFS/MS/BP/Hospital/2008/3424 dated 15/12/2008

7. Date of inspection : 26/07/2023

8. Name of Inspecting Officer : DO South & ADO (BCP)

9. Name and designation of officer

S. No.	Minin	num Standards on fire prevention	or diary 3529 dated 05/07	Provided at site	Remarks			
		re safety U/R 33	Requirement	abuntari in in fronts i	MR/NMR			
1.	Access to building							
	-	Road width	9m	Provided	MR			
	•	Gate width	5m		MR			
	•	Width of internal road	6m	Provided	MR			
2.		er, Width, Type & Arrangement of	Exits	and the court of the	print E			
	a. Nu	mber of staircases		12/51 (1941)	1			
		Upper Floors	06 No's		MR			
		Basements	04 Nos	Provided	MR			
	h w	Ith of staircases	2 2001	 Inclusy Pamp an 				
	U. WI	itii oi staircases	bi	aligning values is				
		Upper Floors	02 mtr	Provided	MR			
	•	Basements	02 mtr	B2 to GF: 2 of 2 m & 2 of 1.5 m B1 to GF: Provided	MR(old Case			
	c. Pro	tection of exits	0.0	are to sensional in				
	•	Fire check door	Required	Provided	MR			
	•	Pressurization	Required	Provided	MR			
	d. No	. of continuous staircases to terrace	Six grang	Provided	MR			
	e. Wi	dth of Corridor	Required	Provided	MR			
	f. Do	or Size	2m & 1m	Provided	MR (old Case)			
3.	Compartmentation							
	•	Fire check door	Required	Provided	MR			
	•	Sealing of electrical shafts	Required	Provided	MR			
	•	Fire Rating of shaft door	NA NA	NA NA	NA			
	•	Water Curtain	NA	NA	NA NA			
4.	6 .	Fire Dampers	Required	Provided	MR			
-	Smoke Management System							
	•	Basements	30 ACPH	M. V. Provided	MR			
5.	•	Upper floors	12 ACPH	M. V. Provided	MR			
J	Fire Extinguishers							
	•	Total numbers	Required	280 Nos	MR			
	•	Types	ABC/W. CO ₂ /CO ₂	100/100/80 Nos	MR			
6.	E'	IS marking	ISI marked	Yes	MR			
		Aid Hose Reels	The same of the sa		galuH			
	•	Total numbers on each floor	5 Nos	Provided	MR			
	•	Length of hose reel hose	30m	Provided	MR			
	•	Nozzle diameter	5mm	Provided	MR			



)		
	Location of Main Panel	Basement-1	Provided	MR		
	Location of Repeater Panel	Security Control Room	Provided	NA		
	Alternate source of power	Battery Back Up	Provided	MR		
	Hooters' Location	All Floors	Provided	MR		
	MOEFA	Required	Provided	MR		
	Public Address System	Required	Provided	MR		
0.	Automatic Sprinkler System					
20850000	Basement	Required	Provided	MR		
	Upper Floors	Required	Provided	MR		
	Sprinkler above false ceiling	Required	Provided	MR		
1.	Internal Hydrants					
-	Size of riser/down-comer	150mm	Provided	MR		
	Number of hydrants per floor	4 Nos	Provided	MR		
	Hose Box	4 Nos	Provided	MR		
12.	Yard Hydrants		whoelens			
	Total number of hydrants	07 No's	Provided	MR		
	Hose Box	07 No's	Provided	MR		
13.	Pumping Arrangements	A consecutant of Laste.	å ser filitik //	dimov i		
	Ground Level		per minute y	IN E		
	Discharge of main Pump	2850 LPM	Provided	MR		
	> Head of Main pump	80m	Provided	MR		
	> Number of main pumps	Two	Provided	MR		
	> Jockey Pump out put	2 x 180 LPM	Provided	MR		
	➤ Jockey pump head	60m	Provided	MR		
	Standby Pump out put	2850 LPM	Provided	MR		
	> Standby Pump Head	60m	Provided	MR		
	Auto Ctanting Adamust Ctanning	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level	quii.eu	11011464	- Will		
	Discharge of pump	NA	NA	NA		
	> Head of the pump	NA	NA	NA NA		
	➤ Power Supply	NA NA	NA NA	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	➤ Auto Starting of pump		TO SECURE	NA		
	C. d. W. St. St. C. C. C. C.	NA	NA	NA		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	1,50,000 Lts	Provided	MR		
	 Draw-off connection Fire service inlet 	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
		20,000 Lts	Provided	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	Required	Provided	MR		
	 Pressurization of Lift lobby 	Required	Provided	MR		
	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch Lio Gi	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.		dath south	s revini		
18.			130 m ²	MR.		
	> Total Area > Location	6 th Floor	Provided	MR (Old Case		
		0 11001	1101100	(Old Case		
19.	Fire Control Room Required Provided					
	Detector System Panel	Required	Provided	MR MR		
	Flow Switch Panel	Acquired	-10,,000	IVIIC		



	PA System Panel	Required	Provided	MR
	Batter backup Building Floor Plans	Required	Provided	MR
		Required	Provided	MR
20.	Special Fire Protection System for Protection of special Risks, if any:	Required	CO ₂ flooding & trace tube system is provided.	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/Hospital/SZ/2020/531 dated 21/12/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of Inspection Officer

Name: S. K Dua Designation: DO South Signature of Inspecting Officer

Name: Rajesh Kumar Designation: ADO (BCP)

CFO (HC

inectar

cettel is portup too