

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/2023/SZ/ 490

Dated: 16/10 /2023

## FIRE SAFETY CERTIFICATE

Certified that M/s Lutyens located at Kh. No. 222/223, M.G. Road, Village Sultanpur, New Delhi-110030 comprised of Basement Ground and first Floor owned/occupied by Unit of Unique Innovation Pvt Ltd was issued FSC by this department vide letter F6/DFS/MS/Motel/SZ/2020/490 dated 13/11/2020. The premise was re-inspected by the officer concerned of this department on 10/10/2023 in the presence of Mr. Amit Khanna (Manager) and found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Class Assembly Building" (Motel) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on... J. 6 \ J. o. \ ... 2023 at New Delhi by

(ATUL GARG)

DELHI FIRE SERVICE

Copy to:-

 The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MHA Portal ID 2023092116246 dated 21/09/2023 & 2023091515982 dated 15/09/2023)

## Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



	INSPECTI	ON REPORT	आज़ादी अमृत	महोत्सव		
1	Name & Address of the Building					
-	The Assessment of the San Control of the San Contro	M/s Lutyens (Unit of Unique Innovation Pvt Ltd located at Kh. No. 222/223, M.G. Road, Village				
2	Type of Occupancy	Sultanpur, New Delhi-110030 Assembly Building (Motel)				
3	Building Comprised of	Basement, Ground floor + 1st floor				
4	Type of Case	Renewal	id Hoor + 1 Hoor			
5	Details of Previous NOC	F6/DFS/MS/Motel/SZ/2020/490 dated 13/11/2020				
6	Fire Safety Directives Letter No		2002/GH/856 dated 2			
7	Date of Inspection	F6/MS/DFS/BP/GH/99/808 dated 23/08/1999 10/10/2023				
8	Name of the Inspecting Officers	DO ( South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Amit Khanna (Manager)				
10	Year of construction	2005	pay 2 condition all days	100		
11	Applicant letter No.		MHA Portal ID 2023092116246 dated 21/09/202. & 2023091515982 dated 15/09/2023			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirement	Provided at Site	Remarks MR/NMR		
1	Access to Building.	and the same	all administration			
3.6	Road width	Assessable	30m	MR		
	Gate width	-NA-	5m -NA-	-NA-		
	Width of internal road     Number, width, type & arrangement of ex	-NA-	-NA-	-NA-		
2		distoration and agence	DUCASACY &			
	a) Number of Staircase	Required	02 Nos.	MR(old case)		
	<ul> <li>Upper floors.</li> <li>Basement floor.</li> </ul>	Alternate	05 Nos.	MR(old case)		
	b) Width of Staircase	W # 7 11	and mant Pro-			
	> Upper floor	Required	2.1 m & 1.2 m	MR(old case		
	> Basement floor	Required	2.1 m, 1.8 m, 1.4 m, 1.3 m & 1.2 m	MR(old case		
	c) Protection of exits	deanth scale ( %				
1	> Fire check door	Required	Provided	MR		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace	Required	One	MR		
	e) Width of corridor	-NA-	-NA-	-NA-		
	f) Door size	-NA-	1m (Final Exit)	-NA-		
3	Compartmentation.	55.90		1 MD		
	Fire check door.	Required	Provided	MR MR		
J. =	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	Provided	-NA-		
	Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
ri-	Fire dampers.	-NA-	THE STATE OF THE S			
4	Smoke Management system.	Natural &	STANIA CHINE ACUUM	) Am		
1000	Basement	Mechanical	Provided	MR		
	Linner floors		AT A	NIA.		
	Upper floors  Fire Extinguishers.	12 ACPH	-NA-	-NA-		
5	Fire Extinguishers.	12 ACPH	Appropriate Service	-NA-		
5	South Control of the		Total 20 nos. ABC-10 Nos. W.CO <sub>2</sub> -10 Nos.	MR MR		

Lutyens Motel, located at Kh. No. 222/223, M.G. Road, Village Sultanpur, New Delhi-110030

1





6	Di AAAA			409
0	First Aid Hose Reels.	2015 ( 1664 PM)	Service and the service and th	T 100
	<ul> <li>Total numbers on each floor.</li> </ul>	03 Nos. at	Provided	MR
	<ul> <li>Length of hose-reel hose.</li> </ul>	hasement, 2 Nos.  At ground floor &	Provided	MR
	Nozzle Diameter.	I No. at First Floor Hose Reels at each	Provided	MR
7	Automatic fire detection & alarming system.	level	Construct Contains	
	Type of detectors	Smoke & Heat	Provided	MR
	Location of Main Panel	-NA-	Ground Floor	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
_	Hooter's location	Required	All Floors	MR
8	MOEFA	Required	Provided	MR
9	Public Address System		Provided	
10		-NA-	-NA-	-NA-
-	Automatic Sprinkler System			Y
	Basement	Required	Provided	MR
	Ground & Upper floors	Required	Provided	MR
11	Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants.			
	<ul> <li>Size of Riser/Down-comer</li> </ul>	Required	Provided	) m
	Number of Hydrant per floor	Required	Provided	MR MR
	<ul> <li>Hose box.</li> </ul>	Required	Provided	MR
12	Yard Hydrants. http://doi.org/10.1000/10.1000/10.100/10.1000/10.100/10.100/10.100/10.100/10.1	1	1 TOVIGED	MIK
	Total number of hydrants.	Required	Provided	1.5
	Hose box.	Required	Provided	MR
13	Pumping arrangements.		TOTAL S	MR
	Ground Level		anamatan and	
	Discharge of main pump.	2250 LPM	Provided	) III
	Head of main pump.	54 m	Provided	MR
	Number of main pumps.	02 Nos.	Provided	MR MR
	> Jockey Pump output.	225 LPM	Provided	MR
	> Jockey Pump head.	54 m	Provided	MR
	<ul> <li>Standby Pump output.</li> <li>Standby Pump head.</li> <li>Auto Starting/Manual Stopping.</li> <li>Pump house access.</li> </ul>	2250 LPM	Provided	MR
		54 m	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
	Terrace Level	Pial	Applicant .	
	Discharge of pump.	-NA-	-NA-	-NA-
	Head of pump.	-NA-	-NA-	-NA-
	Power supply.  Auto starting of pump	-NA-	-NA-	-NA-
4	riate starting or pump.	-NA-	-NA-	-NA-
•	Captive water storage for fire fighting.	- imply as ith	ti limmi amas	
	Underground tank capacity.	1,00,000 Ltrs	Provided	MR
Ξί,	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
ď	Overhead tank capacity.	25,000 Ltrs	Provided	MR
5	Exit Signage.	Required	Provided	MR
5	Provision of Lifts.			





	<ul> <li>Pressurization of lift shaft.</li> <li>Pressurization of lift lobby.</li> <li>Communication in lift car.</li> <li>Fireman's switch.</li> <li>Lift signage.</li> </ul>	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		Required	Provided	MR
		-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area		The Land	77
	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19	Fire Control Room.		77	
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	<ul> <li>PA system panel.</li> </ul>	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
20	Building floor plan.  Special Fire Protection System for the I			-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 109 dated 16/05/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Motel/SZ/2020/490 dated 13/11/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

mell Signature of the Inspecting Officer

: M.K Sharma Name

Designation: DO (South)

Signature of the Inspecting Officer

Name : Sh. Rajesh Kumar Designation: ADO (BCP)

fetter in portrip

222/223 M.G. Road, Village Sultanpur, New Dell