GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ 1738

FIRE SAFETY CERTIFICATE

Dated: 18/10/2023

Certified that the Stanford British School, Najafgarh-Gurgaon Road, Chhawla, New Delhi comprised of Basement (sealed by brick wall), ground plus one upper floor, having total 22 rooms on ground floor and 12 rooms on First floor (Including Class rooms, Offices, Labs, Store & Staff room etc.), owned/occupied by Stanford British School. The school building was re-inspected by the officer concerned of this department on 11/10/2023 in the presence of Smt. Ruby Parashar (Principal) and found that the School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (Except-Basement & New Block having ground plus two upper floors) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 16/10/12023 at New Delhi.

(ATUL GARĞ) DIRECTOR DELHI FIRE SERVICE

Copy to:-

 The Principal, Stanford British School, Najafgarh Gurgaon Road, Chhawla, New Delhi

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub-rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- In case usage of Basement (which is sealed by brick wall) & New Block (which is under construction) having ground plus one upper floor for schooling purpose then FSC will be null and void.

INSPECTION REPORT

1. Name & address of the building: Stanford British School, Najafgarh Gurgaon Road, Chhawla, New Delhi

2. Building comprised of : Basement(sealed by brick wall), ground & first floor only

3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2020/SZ/449 dated 28/10/2020

6. Fire Safety directives letter No : N/A

7. Date of inspection : 11/10/2023 8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Smt. Ruby Parashar (Principal)

10. Year of Construction : Before 2005 & 2019

11. Applicant's letter No. : SBS/2023-24/FSC/239 dated 26/09/2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR			
1.	Access to building						
	Pod Std.	Accessible 06 mtrs	Provided	M/R			
	Road width	4.5 m	Provided	MR			
	Gate width Width of internal road	N/A	N/A	N/A			
	Number, Width, Type & Arrangement of Exits		•	F11 .			
	a. Number of staircases			` -			
	Upper Floors	02 No.'s	03 No.'s	M/R			
•	Basements	N/A	N/A	N/A			
			3.5%				
	b. Width of staircases Upper Floor	1.50M -	2X1.5 M & 1X1.18 M	MR			
	Basements	N/A	N/A	N/A			
	c. Protection of exits		4				
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	Required	Provided	M/R			
	terrace	1.50 M	2.40 M	M/R.			
	e. Width of Corridor		· · · · · · · · · · · · · · · · · · ·	MR (old			
	f. Door Size	1.0 M	.92 M on GF & 1.0 M on FF	accel			
	Compartmentation			.*			
•	No.	N/A	N/A	N/A			
	Fire check door Sealing of electrical shafts	N/A	· N/A	N/A			
	r: Parious of chaff door		N/A	N/A			
	Water Curtain	N/A					
	• Fire Dampers	N/A	N/A·	N/A N/A			
	N/A . N/A						
	Smoke Management System			N//A			
	Basements	N/A	N/A Natural ventilation	N/A			
	Upper floors	Required	provided	M/R			
	Fire Extinguishers						
_	To I have	07 no's	. Provided *	• MR			
	Types	ABC/CO ₂ type	Provided	·** MR			
	IS marking	ISI marked	Provided	MR			

	First-Aid Hose Reels		24	.*
	Total numbers (Basement)	N/A	Provided	N/A
828	Cl	N/A	Provided	N/A
	Length of hose rect hose Nozzle diameter	N/A	Provided	N/A
	152 * 57.554 (6.700.500.00.00.00.00.00.00.00.00.00.00.00.		/ ·	
7	Automatic fire detection and alarming system	N/A	N/A	N/A
	Type of detectors Location of Main Panel	N/A	→ N/A	N/A
	CD Donal	N/A	N/A	N/A
	Location of Repeater Panel Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
	(1997) (Part (1998) (1994) (1994) (1996)	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9. 10.	Public Address System Automatic Sprinkler System			
10.	Basement	N/A	N/A	N/A
	Ground Floor	N/A	. N/A ◆ .	Ń/A
	Sprinkler above false ceiling	N/A	N/A	→ N/A
11:	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	-N/A	N/A
	Hose Box	N/A ·	Ņ/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A .	N/A	N/A
	Hose Box	N/A	• N/A	N/A
13.	Pumping Arrangements			1
	Ground Level	n.		
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	 Number of main pumps Jockey Pump out put 	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A •	N/A
	> Standby Pump out put	N/A	N/A .	· N/A
*	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
_		N/A	·N/A	N/A
	> Pump House Access	3.7.53		1000
	Terrace level Discharge of pump	N/A	450 LPM Provided	N/A
	 Discharge of pump Head of the pump 	N/A	- 30 M Provided	N/A
	> Power Supply	N/A	Provided	N/A
	> Auto Starting of pump	N/A	Provided	N/A
14.	Captive Water Storage for fire fighting			
- "	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection .	N/A	N/A	N/A
	> Fire service inlet .	N/A	N/A	27/4
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	5000 ltrs.	MR
			Provided	
15.	Exit Signage.	N/A .	N/A	N/A
16.	Provision of Lifts.		No Lift	
	Pressurization of Lift Shaft	N/A	→ N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car Signature Society	N/A	N/A	N/A
	Fireman's Grounding SwitchLift Signage	. N/A	N/A	N/A
	T ■ LHU SI2HA2C			

15

17.	Standby power supply	4	N/A	N/A	N/A		
18.	Refuge Area.						
	> Total Area		N/A	N/A	N/A		
	> Location		N/A	· N/A	N/A		
19.	Fire Control Room						
	D. d.		N/A	- N/A	N/A		
	Detector System Panel Flow Switch Panel		N/A	N/A	N/A		
etc	PA System Panel Battery backup		N/A	N/A	N/A		
		N/A	N/A	N/A			
	Building Floor Plans		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:		N/A	N/A	Ŋ/A		
				<u> </u>			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/School/2020/SZ/449 dated 28/10/2020 renewal under the Circular No. F.16/Estate/CC/Fire safety/2011/3298 to 3398 dated 01/03/2011 is recommended.

Note:- Undertaking submitted by the principal placed at (C-85) school building is comprised of basement, ground plus first floor but school running at ground & first floor only. Basement is sealed by bricks wall which is not use for school purpose. A shortcomings letter was issued vide letter No. F6/DFS/MS/School/2022/SZ/680 dated 09/11/2022 for new block, comprised of ground plus two upper floors & not in use.

Signature of Inspecting Officer

Name: R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

413/10/2

\$15 In

Directa

3 (m)

MISTER