



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2023/332

Dated: 09 / 1/ /2023

FIRE SAFETY CERTIFICATE

Certified that M/s Aresko Restaurant Pvt. Limited, Adjoining Lodhi Garden Gate No. 1, Lodhi Road, Opposite Mausam Bhawan, New Delhi-110003, comprised of Ground plus one upper floor and the restaurant running at Ground & First floor was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/EH/2017/SZ/462 dated 29/03/2017 in the name of M/s "Lodi The Garden Restaurant" (Unit of Aresko Restaurant Pvt. Ltd). The premise was re-inspected by the officers concerned of this department on 30/10/2023 in the presence of Mr. Alok Kumar (Manager) and found that the said eating house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class "Group-D Assembly Building" (Eating House) as above with effect from 09/11/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010.

Issued on 09/11/223 at New Delhi by

DELHI FIRE SERVICE

Copy to:-

 The Joint Commissioner of Police (Lic.), First Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. MHA ID No. 2023102017524 dated 21/10/2023)

 Sh. Rajpal Singh Kochhar M/s Aresko Restaurant Pvt. Limited, adjoining Lodhi Garden Gate No. 1, Lodhi Road, Opposite Mausam Bhawan, New Delhi-110003

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangement provided therein shall be maintained in good working conditions at all times. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know correct method of operation of fire fighting system.

4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.Delhigovt.nic.in

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ė	INSPEC	TION REPOR	T					
	Name & Address of the Building	I adhi Gar	M/s Aresko Restaurant Pvt. Ltd, adjoining Lodhi Garden Gate No. 1, Lodhi Road, Opposite Mausam Bhawan, New Delhi-03					
	2 Type of Occupancy	Group-D "	Group-D, "Assembly" (Eating House) (Eating House at Ground & First Floor)					
	2 Puilding Committed of	Ground & C	ne uppo	r Floor.				
4	Building Comprised of	Renewal			ated 29/03/2017			
	4 Type of Case 5 Details of Previous NOC	E C/DES/MS	S/EH/20	17/SZ/462 da				
	5 Details of Frevious NOC	in the name	of M/s "	Lodi The Ga	rden .td)	Kestauran		
	6 Fire Safety Directives Letter No.			5/718 dated	04/04	/2003		
- 29	7 Date of Inspection	30/10/2023						
	Name of the Inspecting Officers		Santosh Kumar, ADO (SJ)					
,	Name & Designation of Officers from the building side	Mr. Alok Ku	Mr. Alok Kumar (Manager)					
1	0 Year of construction	1970						
1	1 Applicant letter / MHA ID No.	ID No. 2023	1020175	24 dated 21.	/10/20	123		
S	. Minimum standards on Fire Preventio	n Existing F Protection Sy		Provided a Site	it	Remark MR/NM		
1	Access to Building.		1.6			MR		
	Road width	Accessible	151			N/A		
	Gate width	N/A	N/A			N/A		
	Width of internal road	N/A	N/A	-		1071		
2		t of exits.						
	a) Number of Staircase	22/	IZN	los		MR		
	➤ Upper floors.	2 Nos	N/A	***************************************	_	N/A		
	> Basement floor.	N/A	IN/Z		-	1		
	b) Width of Staircase	Demind	112	m & 0.90m	IME	(old case		
	> Upper floors	Required	N/A		N/A			
	> Basement floor	N/A	INT	-	1107	•		
	c) Protection of exits	21/4	N/A		N/A			
	> Fire check door	N/A N/A	N/A		N/A			
	> Pressurization	N/A	N/A		N/A			
	d) No. of continuous staircase to terrace	N/A	N/A		N/A			
	e) Width of corridor		100000000	im & 1m	0.75	(old case)		
	f) Door size	Required 02 Nos.		al Exit)	IVIIN	(Old case)		
3	Compartmentation.	N/A	N/A			N/A		
	Fire check door.	N/A N/A	N/A			N/A		
	Sealing of electrical shafts.	DANIELE .	N/A		-	N/A		
	 Fire rating of shaft door. 	N/A	N/A			N/A		
	Water curtain	N/A						
	Fire dampers.	N/A	N/A			N/A		
	Smoke Management system.							
	Basement	30 ACPH	N/A	X .		N/A		
	Upper floor	12 ACPH	Exha	ust fan		MR		
	Fire Extinguishers.							
	Total numbers		10 Nos			MR		
	• Types	ISI marked		& CO ₂		MR		
	ISI Marking		Provi	ided		MR		
	First Aid Hose Reels.		T a	1) (D		
	 Total numbers on each floor. 		One			MR		
	 Length of hose-reel hose. 	Hose-reels	30m	b		MR		
- 1			5mm			MR		

17-18

7	Automatic fire detection & alarming	system.		
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
_	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System	1.071	IN/A	N/A
	Basement	N/A	N/A	N/A
	Upper floor.	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	
11	Internal Hydrants.		IVA	N/A
	 Size of Riser/Down-comer 	N/A	N/4	157/4
	Number of Hydrant per floor	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
12	Yard Hydrants.	IV/A	N/A	N/A
	 Total number of hydrants. 	N/A	L STEE	
	Hose box.	N/A N/A	N/A	N/A
13	Pumping arrangements.	IN/A	N/A	N/A
	Ground Level			
	Discharge of main pump.	N/4		
	➤ Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	> Pump house access.	IV/A	N/A	N/A
	Terrace Level	N/A	N/A	N/A
	Discharge of pump.	D	7 5 6	
	➤ Head of pump.	Boosting	450 LPM	MR
	➤ Power supply.	N/A	35m	N/A
	> Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	N/A	Provided	N/A
	 Underground tank capacity. 			7
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity	N/A	N/A	N/A
15	Exit Signage.	5,000 Ltrs	Provided	MR (old case)
16	Provision of Lifts.	Required	Provided	MR
	 Pressurization of lift shaft. 	NIA	Key and the last	
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
,	• Lift signage.	N/A	N/A	N/A
7	Standby Power Supply	N/A	N/A	
8	Refuge Area	Required	Provided	N/A
	Total area		Tarided	MR
	Location	N/A	N/A	- 14
	-ocation	N/A		N/A





19	Fire Control Room.			1
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Building floor plan. N/A N/A Special Fire Protection System for the Protection of special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the Protection of Special Risk, if any. Special Fire Protection System for the			

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/EH/2017/SZ/462 dated 29/03/2017 in the name of M/s "Lodi The Garden Restaurant" (Unit of Aresko Restaurant Pvt. Ltd), renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended in the name of M/s Aresko Restaurant Pvt. Ltd.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

DO (SE)

much

7/1/2022

Director

ir Could in his back by 1

ir, F. Tutter is public for your

Director All 2

09/11/83