



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F.6/DFS/MS/EH/SZ/2023/

Dated:0 8 /11 /2023

FIRE SAFETY CERTIFICATE

Certified that M/s Punjab Grill (A unit of Lite Bite Foods Pvt. Ltd.) at Plot No. D-16, Second Floor, Defence Colony, New Delhi-110024, comprised of Basement, Stilt, Ground & Three Upper floors but the restaurant at Second floor only, owned/occupied by M/s Punjab Grill (A unit of Lite Bite Foods Pvt. Ltd.) have complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 30/10/2023 in the presence of Sh. Rajesh Giri of the restaurant and observed that the that said premise is fit for occupancy class "Assembly Group D" (Eating House) with effect from 08/11/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

at New Delhi by

Copy to: -

- 1. The Deputy Health Officer, Central Zone, Municipal Corporation of Delhi, Jal Vihar, Lajpat Nagar, New Delhi-110024 (w.r.t. MHA ID: 2023102117595 dated 21/10/2023)
- 2. Mr. Rohit Aggarwal M/s Punjab Grill (A unit of Lite Bite Foods Pvt. Ltd.) at Plot No. D-16, Second Floor, Defence Colony, New Delhi-110024

Conditions for the validity of Fire Safety Certificate:

- All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety 2. measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule 3. of Delhi Fire Service Rules 2010. The from is available on www.dfs.delhigovt.nic.in 4.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any. 5.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry". 6.

N-8

1	Name & Address of the Building	ON REPORT M/s Puniab Grill (A unit of Lite Bite Foo	ods Pvt.	
•	The second of the Banding	Ltd.) at Plot No. D-16, Second Floor, Defence			
		Colony, New Delhi-110024			
2	Type of Occupancy	Group-D, "Assembly" (Restaurant at 2nd Floor)			
3	Building Comprised of	Basement, Stilt, Ground & Three Upper floors.			
4	Type of Case	New			
5	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	30/10/2023			
8	Name of the Inspecting Officers	ADO (SJ) Santosh Kumar			
9	Name & Designation of Officers	Mr. Rajesh Giri			
	from the building side				
10	Year of construction	2022			
11	Applicant letter No. MHA ID No.	MHA ID No. 2023102117595 dated 21/10/2023			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/NBC-2016 Provided at Site Remarks Requirement MR/NMI			
1	Access to Building.	l and be		Lvm	
	Road width	6m	Provided	MR	
	Gate width	4.5m	Abut on road	MR	
	 Width of internal road 	N/A	N/A	N/A	
2	Number, width, type & arrangement of	f exits.			
	a) Number of Staircase				
	➤ Upper floors.	2 Nos	Provided	MR	
	➢ Basement floor.	N/A	N/A	N/A	
	b) Width of Staircase				
	> Upper floors	1.5m (each)	1.5m (each)	MR	
	> Basement floor	N/A	N/A	N/A	
	c) Protection of exits			1	
	> Fire check door	N/A	N/A	N/A	
	> Pressurization	N/A	N/A	N/A	
		- Caracterian	Variable -	1.00	
	d) No. of continuous staircase to terrace	Required	Provided	MR	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	1.5m x 2 Nos	2m and 1.5m	MR	
3	Compartmentation.	3911	I Sec.	1500	
	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4.	Smoke Management system.	4	NAME OF THE PARTY	104034	
	Basement	N/A	N/A	N/A	
	Upper floor	N/A	N/A	N/A	
5.	Fire Extinguishers.			12	
	Total numbers	Required	08 Nos	MR	
	Types	ABC/CO ₂ /W.CO ₂		MR	
	ISI Marking	Required	Provided	MR	
6.	First Aid Hose Reels.				
	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
			I A LOTINOU	1 4144	



	Automatic fire detection & alarming system.				
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	 Hooter's location 	N/A	N/A	N/A	
	MOEFA	Required	Provided	MR	
	Public Address System	N/A	N/A	N/A	
0	Automatic Sprinkler System			TATIA	
	Basement	N/A	N/A	N/A N/A	
	 Upper floors. 	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
1	Internal Hydrants.	-	the second	I v (D	
	 Size of Riser/Down-comer 	100 mm	Provided	MR	
	Number of Hydrant per floor	Required	Provided	MR	
-	Hose box.	Required	Provided	MR	
2	Yard Hydrants.	SCHOOL STATE	Sec. 1	1577	
	 Total number of hydrants. 	N/A	N/A	N/A	
	Hose box.	N/A	N/A	N/A	
3	Pumping arrangements.		0.00		
	Ground Level		A Secretaria	Terre	
	Discharge of main pump.	N/A	N/A	N/A	
	Head of main pump.	N/A	N/A	N/A	
	Number of main pumps.	N/A	N/A	N/A	
	Jockey Pump output.	N/A	N/A	N/A	
	Jockey Pump head.	N/A	N/A	N/A	
	Standby Pump output.	N/A	N/A	N/A	
	> Standby Pump head.	N/A	N/A	N/A	
	> Auto Starting/Manual Stopping.		N/A	N/A N/A	
	> Pump house access.	N/A	N/A	N/A	
	Terrace Level	450 7 704	Provided	MR	
	Discharge of pump.	450 LPM	Provided	MR	
	> Head of pump.	40m	A STATE OF THE STA	MR	
	> Power supply.	Required	Provided	190000000000000000000000000000000000000	
	> Auto starting of pump.	Required	Provided	MR	
1.1	Captive water storage for fire fighting	g		LATIA	
14	Underground tank capacity.	N/A	N/A	N/A	
	Draw-off connection.	N/A	N/A	N/A	
	Fire Service Inlet.	N/A	N/A	N/A	
		N/A	N/A	N/A	
	The state of the s	20,000 Ltrs	Provided	MR	
	 Overhead tank capacity. 	Required	Provided	MR	
15	Exit Signage.	Required	100-5		
16	Provision of Lifts.	NI/A	N/A	N/A	
	Pressurization of lift shaft.	N/A	N/A	N/A	
	 Pressurization of lift lobby. 	N/A		N/A	
	Communication in lift car.	N/A	N/A	N/A	
	• Fireman's switch.	N/A	N/A		
	• Fifeliali S Switch.	N/A	N/A	N/A	
	T 'A alamaga	10000 (FRANCE)	D '1-4	MR	
	Lift signage.	Required	Provided		
17	Standby Power Supply	Required	Provided	1	
17 18		Required N/A	Provided N/A	N/A	



9	Fire Control Room.	N/A	N/A	N/A
	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. 	N/A	N/A	N/A
		N/A	N/A	N/A
i		N/A	N/A	N/A
		N/A	N/A	N/A
			N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	177.	1 1 1 1 1 1

The Fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The shortcoming issued by this department vide letter No. F6/DFS/MS/EH/SZ/2023/568 dated 16/10/2023 found complied.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate, under rule 35 of the Delhi Fire Service Rules-2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)

ADUK:

Hor by oceprati

Sir, Stilt floor is used for parking other floor except 2rd floor are conscipced under renardion. I show that pr. 1 spurman for h.

Direct for the officers of the principle of