GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELII HEADQUARTERS: DELIH FIRE SERVICE: NEW DELIH- 110001

No.F6/DFS/MS/NDZ/2023/CC 35

Dated: 01/12/2023

FIRE SAFETY CERTIFICATE

Certified that the M/s Aakash Institute located at Property No. 05, Gagan Vihar, Delhi110092, comprised of basement, stilt (Parking), upper ground plus three upper floors only, owned/occupied M/s Aakash Institute have complied with the Fire Prevention and Fire Safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 17/11/2023 in the presence of Mr. Shudir Kumar (Architect) and that the building /premises is fit for occupancy class "Educational" (Group-B) with effect from of 1/12/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued 01 12 2073 at New Delhi by.

DIRECTOR
DELIII FIRE SERVICE

Copy to: -

1. M/s Aakash Institute located at Property No. 05, Gagan Vihar, Delhi - 110092.

Condition for the validity of fire safety certificate

- 1 All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2 Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3 The trained fire fighting staff should be available round the clock.
- 4 Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5 This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7 The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8 Basement shall be used strictly as per Building By-Laws 1983.
- 9 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'I' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

N/3

| | | | INSPEC | TION REPORT | | | |
|------|---|--------------------------------|--|--|---------------------------|-------------------|--|
| | Name | e & | address of the building | M/s Aakash Institute located at Property No.05, Gagan Vihar, Delhi-110092 | | | |
| | Building is comprised of | | | Basement + Stilt (Parking) + Upper Ground + 03 | | | |
| | Type of occurren | | | upper floors only. | | | |
| | Type of occupancy | | | Educational Building | | | |
| | Type of case | | | New Case | | | |
| | Details of previous FSC Fire safety directives letter no. | | | Nil NBC Part IV | | | |
| | Date of inspection | | | 17.11.2023 | | | |
| | Name of the inspecting officers | | | Yashwant Singh Meena ADO (L.N) | | | |
| | Name of the designation of officer from the building side | | of the designation of officer | Mr. Shudir Kumar (Architect) | | | |
| 0 | | Year of construction 2004 | | | | | |
| 11 | App | lica | nt's letter no. | Outdoor dairy No. | 6548 dated 26.09.202 | 3 | |
| S.No | 11 1-20-2 | 1000000 | um standard of fire tion and fire safety U/R 33 | NBC Part IV Requirement | Provided at site | Remarks MR/NMR | |
| 1 | Acc | ess | to Building: | | | | |
| | A | | oad width | 6.0 mtrs. | 6.0 mtrs | MR | |
| | В | Ga | ate width | N/A | N/A | N/A | |
| | C | W | idth of internal road | N/A | N/A | N/A | |
| 2 | Number, Width, Type and Arrangement of Exits: | | | | | | |
| | A | | umber of staircases Upper floor | 02 nos. | 02 nos. | MR | |
| | | a b | Basement | 02 nos. | 02 nos. | MR | |
| | 1 | | | | | | |
| | В | a | /idth of staircases Upper floor | 1.50 mtrs. | 1.50 mtrs. | MR | |
| | | | | 1.50 mtrs. | 1.50 mtrs. | MR | |
| | | | Basement | | | N/A | |
| | C | P | rotection of exits | NA | N/A | | |
| | | a | Fire check door | N/A | N/A | N/A | |
| | | b | Pressurization | N/A | N/A | N/A | |
| | D | 132 | lo. of continuous staircases to | 01 no. | 01 no. | MR | |
| | E | E Width of corridor | | 1.50 mtrs. | 1.68 mtrs. | MR | |
| | F | F Door size | | 1.20 mtrs. X 02 | 1.20 mtrs | MR | |
| 3 | C | mn | artmentation: | | | | |
| | A Fire check door | | Control Contro | N/A | N/A | N/A | |
| | В | B Sealing of electrical shafts | | NA | NA | NA | |
| | С | C Fire rating of shaft door | | N/A | N/A | N/A | |
| | D | V | Vater curtain | N/A | N/A | N/A | |
| | E | F | ire dampers | N/A | N/A | N/A | |
| 4 | Sr | nok | e Management System: | | | | |
| | A | - | Basement | Required | Provided (Exhaust Fan) | MR | |
| | В | ı | Jpper floor | Required | Natural Ventilation | MR | |

Aakash Institute. Property No.05, Gagan Vihar, Delhi-110092.

| 5. | - | re Extinguisher: | 14 nos. | 14 nos. | M | | | |
|----|--------------------|--------------------------------|---|--|--------------|--|--|--|
| | A | Total numbers | ABC& CO ₂ | ABC& CO | M | | | |
| | B | Types | ISI Marked | ISI Marked | | | | |
| | C | ISI marking | 1SI Marked | 131 Market | | | | |
| 6 | - | rst-Aid-Hose Reel: | 01 no. | 01 no. | MI | | | |
| | A | Total numbers | | 7.076.918.22 | MF | | | |
| | В | Length of hose reel hose | 30 mtrs | 30 mtrs | 11 | | | |
| | C | Nozzle diameter | 05 mm | 05 mm | MR | | | |
| 7 | Α. | tomatic Fire Detection and A | Alarming System: | 1 | | | | |
| , | A | Type of detectors | Smoke | Provided | / N/A | | | |
| | В | Location of main panel | Ground floor | Provided | N/A | | | |
| | | | \$7000000000000000000000000000000000000 | | / N/A | | | |
| | C | Location of repeater panel | N/A | N/A | (DS330).6 | | | |
| | D | Alternate source of power | Required | Provided | MR | | | |
| | E | Hooters | Required G | Provided | MR | | | |
| 8 | M | OEFA: | Required _ MA | | MR | | | |
| | | | N/A | N/A | N/A | | | |
| 9 | | blic Address System: | IVA | IVA | 1 | | | |
| 10 | - | tomatic Sprinkler System: | Damina | Provided | MR | | | |
| | A | Basement | Required | A. The state of th | | | | |
| | В | Upper floor | Required | Provided / | MR | | | |
| | C | Sprinkler above false ceiling | N/A | N/A | N/A | | | |
| 11 | Internal Hydrants: | | | | | | | |
| | A | Size of riser/down-comer | 100 mm | 100 mm / | MR | | | |
| | В | Number of hydrants per floor | 01 no. | 01 no. | MR | | | |
| | | Hose box | 01 no. | 01 no. | MR | | | |
| | C | | 01 no. | 01 no. | MIK | | | |
| 12 | | rd Hydrants: | N/A | N/A | N/A | | | |
| | A | Total number of hydrants | -190000 | | TINCAPSIBINE | | | |
| | В | Hose box | N/A | N/A | N/A | | | |
| 13 | | mping Arrangements: | | | | | | |
| 1 | | Fround level | N/A | N/A | N/A | | | |
| | A | Discharge of main pump | | | | | | |
| | В | Head of main pump | N/A | N/A | N/A | | | |
| | С | Number of main pumps | N/A | N/A | N/A | | | |
| | D | Jockey pump out put | N/A | N/A | N/A | | | |
| | E | Jockey pump head | N/A | N/A | N/A | | | |
| | F | Standby pump out put | N/A | N/A | N/A | | | |
| | G | Standby pump head | N/A | N/A | N/A | | | |
| | Н | Auto starting /manual | WANGE 120 | N/A | N/A | | | |
| | | stopping | | | | | | |
| | I | Pump house access | N/A | N/A | N/A | | | |
| 2 | Terrace Level | | | | | | | |
| 2 | A | Discharge of pump | 450 LPM | 450 LPM X 02 | MR | | | |
| 2 | A | | | / | | | | |
| 2 | B | Head of the pump | 40 M | 10 M | MR | | | |
| | | Head of the pump Power supply | 750500 | 12224 | MR MR | | | |

00/

Aakash Institute. Property No.05, Gagan Vihar, Delhi-110092.

| 4 | Captive Water Storage for Fire Fighting: | | | | | | | |
|----|--|--|-------------|---------------|-----|--|--|--|
| | A | Underground tank capacity | N/A | N/A | N/A | | | |
| | В | Draw-off connection | N/A | N/A | N/A | | | |
| | C | Fire service inlet | Required | Provided | MR | | | |
| | D | Access to tank | N/A | N/A | N/A | | | |
| | E | Overhead tank capacity | 15,000 ltrs | 15,000 ltrs / | MR | | | |
| 15 | Exit Signage: | | Required | Provided | MR | | | |
| 16 | Pro | Provision of Lifts: | | | | | | |
| | A | Pressurization of lift shaft | - N/A | N/A | N/A | | | |
| | В | Pressurization of lift lobby | N/A | N/A | N/A | | | |
| | C | Communication in lift car | Required | Provided | MR | | | |
| | D | Firemen's grounding switch | Required | Provided | MR | | | |
| | E | Lift signage | Required | Provided | MR | | | |
| 17 | Sta | andby Power Supply: | Required | Provided | MR | | | |
| 18 | | | | | | | | |
| | A | Total area | N/A | N/A | N/A | | | |
| | В | Location | N/A | N/A | N/A | | | |
| 19 | Fire Control Room: | | | | | | | |
| | A | Detector system panel | N/A | N/A | N/A | | | |
| | В | Flow switch panel | N/A | N/A | N/A | | | |
| | C | PA system panel | N/A | N/A | N/A | | | |
| | D | Battery backup | N/A | N/A | N/A | | | |
| | E | Building floor plans | N/A | N/A | N/A | | | |
| 20 | | pecial Fire Protection systems for rotection of special Risks, if any: | N/A | N/A | N/A | | | |

As per direction of FP wing inspection of the building was carried out.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 37 of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name: Yashwant Singh Meena
Designation: ADO (L.N)

C.FO,

Mugs 20/11/23