

No. F.6/DFS/MS/EH/2023/SZ/356

Dated: 07 / 12 /2023

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Laidback Café Avenue located at Shop No 240, 241, 1st Floor, DLF Avenue Mall, Saket New Delhi -110017 in the building comprised of 03 tiers Basement, Ground plus Seven Upper floors owned/occupied by A Unit of Phoenix Restaurant Pvt. Ltd was issued FSC by this department vide letter F6/DFS/MS/EH/2021/SZ/55 dated 03/03/2021. The restaurant premise was re-inspected by the officers concerned of this department on 04/12/2023 in the presence of Sh. Dhiraj Arora and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D "Assembly Building" and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07 / 12 /2023 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2023111018420 dated 22/11/2023)

## Conditions for the validity of Fire Safety Certificate: -

- All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

2	INCRECT	TION REPORT	The state of the s	07 1 .		
		ION REPORT	G-Ct Assenta (A Linit	of Phoenix		
1	Name & Address of the Building	M/s Laidback Café Avenue (A Unit of Phoenix Restaurant Pvt. Ltd) shop No 240, 241, 1st Floor, DLF Avenue Mall, Saket New Delhi -110017				
2	Type of Occupancy	(Restaurant is run	ning at 1st Floor only)	.)		
3		03 tier Recements	Ground + 07 Upper Floo	rs		
4	Building Comprised of Type of Case	03 tier Basements, Ground + 07 Upper Floors Renewal				
5		F6/DFS/MS/EH/2021/SZ/55 dated 03/03/2021				
6	Details of Previous NOC	DI F Place Malla F.6	/MS/DFS/BP/2005/2073 dated	04/10/2005		
0	Fire Safety Directives Letter No	& F.6/MS/DFS/BP/	2019/135 dated 01/04/2019			
7	Date of Inspection	04/12/2023				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Sh. Dhiraj Arora				
10	Year of construction	2005	STATE OF THE SECOND			
11	Applicant letter No.	MHA Portal ID 20	023111018420 dated 22/1	1/2023		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR		
1	Access to Building. (DLF Ave	nue Mall - F.6/DFS/M	S/2022/Mall/SZ/266 Dt. 15	/06/2022) +		
	Road width	12 m	Provided*	MK		
	Gate width	7m	Provided*	MR		
	Width of internal road	6m	Provided*	MR		
2	Number, width, type & arrangement of ex	its.	Maintained by DLF Place	Saket		
	a) Number of Staircase	02 Nos	16 Nos Provided*	MR		
	<ul> <li>▶ Upper floors.</li> <li>▶ Basement floor.</li> </ul>	N/A	N/A	N/A		
	b) Width of Staircase		Maintained by DLF Place	, Saket		
	> Upper floors	1.50 mtr & 2m	9 x 1.50m & 7 x 2m	MR		
	> Basement floor	N/A	N/A	N/A		
	c) Protection of exits		Maintained by DLF Place			
	> Fire check door	Restt within Mall	Provided* Provided*	MR MR		
	Pressurization  d) No. of continuous staircase to terrace	Restt within Mall	-NA-	MR		
	d) No. of continuous staircase to terrace     e) Width of corridor	N/A	N/A	N/A		
	f) Door size	02 Nos	2 m & 1.50 m	MR		
3	Compartmentation.	Provided &	Maintained by DLF Place	, Saket		
	Fire check door.	Restt within Mall	Provided*	MR		
	Sealing of electrical shafts.	Restt within Mall	Provided*	MR		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A N/A	N/A N/A	N/A N/A		
_	• Fire dampers.		Maintained by DLF Place			
4	Smoke Management system.     Basement	30 ACPH	N/A	N/A		
	Upper floors	12 ACPH	Exhaust Fans Provided	MR		
5	Fire Extinguishers.		LU UI I			
	Total numbers	Required	08 Nos	MR		
	Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR		
	ISI Marking	Required	Provided	MR		
6	First Aid Hose Reels.		Maintained by DLF Place	7		
	Total numbers on each floor.  Leagth of base real base.	One near Restt 30m	Provided*	MR		
	Length of hose-reel hose.     Nozzle Diameter	5mm	Provided*	MR MR		
7	Automatic fire detection & alarming system		laintained by DLF Place,			
,	Type of detectors	Required	Smoke & heat	MR		
	Location of Main Panel	Required	Provided*	MR		
	Location of Repeater Panel	Required	Provided*	MR ·		
	Alternate source of power	Required	Provided*	MR		
	Hooter's location	•		IVIE		

2	5
	7

8	MOEFA	Required	Provided	MR	
9	Public Address System	N/A	As above	MR	
10	Automatic Sprinkler System	Provided & Maintained by DLF Place, Saket			
	Basement	Required		-	
	Ground floor.	-	Provided*	MR	
	- A Company of March 1995	Required	Provided*	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants.		Maintained by DLF Pla	ice, Saket	
	Size of Riser/Down-comer	Required	Provided*	MR	
	Number of Hydrant per floor	One near Restt	Provided*	MR	
	Hose box.	One near Restt	Provided*	MR	
12	Yard Hydrants.	Provided & N	faintained by DLF Pla	ce, Saket	
	Total number of hydrants.	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
13	Pumping arrangements.		faintained by DLF Place		
13	Ground Level		ing arrangements for		
	Discharge of main pump.	4500 LPM	4500 LPM	MR	
		70m			
	<ul> <li>Head of main pump.</li> <li>Number of main pumps.</li> </ul>		70m	MR	
	The second secon	02 Nos.	02 Nos.	MR	
		180 LPM	180 LPM	MR	
	Jockey Pump head.	70m	70m	MR	
	<ul><li>Standby Pump output.</li><li>Standby Pump head.</li></ul>	4500 LPM	2 X 4500 LPM	MR	
		70m	70m	MR	
		Required	Provided	MR	
	Pump house access.	Required	Provided	MR	
	Terrace Level		and the state of		
	Discharge of pump.	450 LPM	Provided*	MR	
	Head of pump.	40 m	Provided*	MR	
	Power supply.	Required	Provided*	MR	
	Auto starting of pump.	Required	Provided*	MR	
14	Captive water storage for fire fighting.		intained by DLF Place		
	<ul> <li>Underground tank capacity.</li> </ul>	Required	3,70,000 Ltrs	MR	
	Draw-off connection.	Required	Provided	MR	
	<ul> <li>Fire Service Inlet.</li> </ul>	Required	Provided	MR	
	> Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	Required	30,000 Ltrs	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.	Provided & Ma	intained by DLF Place,	Saket	
	Pressurization of lift shaft.	Required	Provided*	MR	
	Pressurization of lift lobby.	Required	Provided*	MR	
	Communication in lift car.	Required	Provided*	MR	
	Fireman's switch.	Required	Provided*	MR	
	Lift signage.	Required	Provided*	MR	
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area	Washing Containing			
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room.	10.80%/0487	ntained by DLF Place,	2000	
	Detector system panel.	N/A	Provided*	N/A	
	Flow switch panel.	N/A	Provided*	N/A	
	PA system panel.	N/A	Provided*	N/A	
		N/A	Provided*	N/A	
	Battery backup.      Building floor plan	N/A N/A	Provided*	N/A	
20	Building floor plan.  Special Fire Protection Senters for the		Provided	N/A	
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	Provided*	17/1	



The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention safety measures as required under the rules, the FSC issued vide letter no is recommended.

Accordingly, DFA is put up for approval and signature please.

nerst

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CAO Mugh 6 121 2023 Dineeta My

Any DCP

11/6/53