



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2023/ 380

Dated: 28 / 12 /2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s. Wilde Kitchen and Bar (A unit of Betterment Hospitality LLP.), located at Located at Plot No. - 17-A, Third Floor, North West Avenue, West Punjabi Bagh, New Delhi-110026, running at third floor only in a building comprised of Basement + Ground + 03 Upper Floors, Owned/occupied by M/s. Wilde Kitchen and Bar (A unit of Betterment Hospitality LLP.). The building/premises was inspected by the officer concerned of this department on 18/12/2023 in the presence of Sh. Vikram and found that the said premises/building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Assembly"(Group-D)) with effect from 38 12 202 3 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions Printed Overleaf.

Issued on 28. 12 2023. at New Delhi by.

Atul Garg)

Copy to: -

- The owner/occupier, M/s. Wilde Kitchen and Bar (A unit of Betterment Hospitality LLP.) located at Plot No.- 17-A, Third Floor, North West Avenue, West Punjabi Bagh, New Delhi-110026. Online Application ID no. 2023112918998 dated 29/11/2023 & 2023121919742 dated 19/12/2023.
- The Joint Commissioner of Police, Licensing Unit, 1<sup>st</sup> floor, Police Station, Defence Colony, New Delhi. (<u>addlcp.lic-dl@nic.in</u>.)
- 3. The Dy. Health Officer, MCD, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. (dhowest zone@gmail.com)

		<u>IN</u>	SPEC	TION REPORT	<u>L</u>									
1. 'N	Vame &	address of the building	M/s.Wilde Kitchen and Bar (A unit of Betterment Hospitalian LLP.), Located at Plot No 17-A, Third Floor, North Weak Avenue, West Punjabi Bagh, New Delhi-110026.											
2. Type of Occupancy			Eating House /Assembly Occupancy											
3. Type of Case			New											
Details of previous NOC     Fire Safety directives letter No			Nil 18/12/2023											
									-~-				(MN)	
									Name o	of the Inspecting Officers and designation of		jeet Singh ADO ( ikram	(IAIIA)	
.0,:		from the building side	×	SANTO SAN ASA										
9. Year of Construction			2012	(As per MHA Po	rtal)									
	8.55	ant's letter No.	01777.W.B.G.S.C.	/2023 & ID No. 2	2023121919742 dated 1	9/12/2023								
he S pper	aid Res	taurant is running at thin & it's both stairs (Iron) is	separa	r in a building c ated from the Gu	rest house.									
	Mir	imum Standards on fire	-	BBL /NBC Requirement	Provided at site	Remarks MR/NMR								
No.		tion and fire safety U/R 3 to building	55	Requirement	У	1								
		Road width		09 mtr	On Main Road	MR								
	•	Gate width		On Main Road	On Main Road	MR								
	•	Width of internal road		NA	NA	NA								
2	Numb	er, Width, Type & Arran	gemen											
	a. Nun	ber of staircases			No contract of the contract of	1/0								
	•	Upper Floors		2	Provided	MR								
	•	Basements		NA	NA	NA								
	b. Wic	th of staircases		2 X1.5 mtr   1	X2 mts, 1X 1.5 mts Provid	ed MR								
		Upper Floors Basements		NA NA	NA NA	NA NA								
	c. Pro	tection of exits		****	70.000									
	•	Fire check door		Required	Provided	MR								
	•	Pressurization		NA	NA	NA								
	C-977 - 740 150 50	of continuous staircases to to	errace	02	Provided	MR								
		th of Corridor		NA	NA	NA								
	g. Do	or Size	_	2 X 1.5mts	Provided	MR								
	Compartmentation.			N	N/A	NA								
3	Com	1 10. 8				INA								
3	• Com	Fire check door		NA NA	NA NA	NΔ								
3		Sealing of electrical shafts	5	NA	NA	NA NA								
3		Sealing of electrical shafts Fire Rating of shaft door		NA NA		NA NA MR								
3		Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant		NA NA Required	NA NA Provided	NA MR								
		Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant Fire Dampers		NA NA	NA NA	NA								
3	Smol	Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant Fire Dampers ke Management System.		NA NA Required	NA NA Provided	NA MR								
		Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant Fire Dampers  ke Management System.  Basements		NA NA Required NA	NA NA Provided NA	NA MR NA								
4	Smol	Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant Fire Dampers  ke Management System.  Basements Upper floors		NA NA Required NA NA	NA NA Provided NA NA	NA MR NA								
	Smol	Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant Fire Dampers  ke Management System.  Basements Upper floors  Extinguishers		NA NA Required NA NA	NA NA Provided NA NA	NA MR NA								
4	Smol	Sealing of electrical shafts Fire Rating of shaft door 04 hours Fire resistance wall to Guest house & Restaurant Fire Dampers  ke Management System.  Basements Upper floors  Extinguishers		NA NA Required NA NA Required	NA NA Provided NA NA Provided	NA MR NA NA MR								

6	First-Aid Hose Reels.	01	Provided	MR			
	Total numbers on each floor	30m	Provided	MR			
	Length of hose reel hose	5mm					
	Nozzle diameter		Provided	MR			
7	Automatic fire detection and alarming system.  Smoke & Heat Provided MR						
	Type of detectors	AND THE POST OF TH	11551 TO THE CONTROL OF THE CONTROL	1 mg 344334 577			
	Location of Main Panel	Required	Provided	MR			
	Location of Repeater Panel	NA	NA	NA			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Required	Provided	MR			
3	MOEFA	Required	Provided	MR			
9	Public Address System.	NA	NA	NA			
10	Automatic Sprinkler System.	II	50				
	Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants		_				
	Size of riser/down-comer	100 mm	Provided	MR			
	Number of hydrants per floor	01	Provided	MR			
	Hose Box	01	Provided	MR			
12	Yard Hydrants.						
_	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
13	Ground Level						
	Discharge of main Pump	2280 LPM	Provided	MR			
	Head of Main pump			MR			
	Number of main pumps	40 MH 01	Provided Provided	MR			
	> Jockey Pump out put	180 LPM	Provided	MR			
	> Jockey pump head	40 MH	Provided	MR			
	Standby Pump out put	2280 LPM	Provided	MR			
	Standby Pump Head	40 MH	Provided	MR			
	➤ Auto Starting/ Manual stopping	Required	Provided	MR			
	Pump House Access	Required	Provided	MR			
	Terrace level						
	<ul> <li>Discharge of pump</li> </ul>	450 lpm	Provided	MR			
	➤ Head of the pump	40 MH	Provided	MR			
	➢ Power Supply	Required	Provided	MR .			
	<ul> <li>Auto Starting of pump</li> </ul>	Required	Provided	MR .			
4	Captive Water Storage for fire fightin	g.		20 m 12			
	Underground tank capacity	1,00,000 ltr	Provided	MR			
	> Draw-off connection	NA	NA	NA			
	Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
i	Overhead Tank capacity	5,000 ltrs	Provided	MR			
1	• Overhead rank capacity			MR			
5	Exit Signage.	Required	Provided	IVIIX			

10	and,			
17	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	NA NA NA NA NA	NA NA NA NA	NA NA NA NA
18	Standby power supply Refuge Area.	Required	Provided	MR
19	Total Area Location Fire Control Room	NA NA	NA NA	NA NA
19	Fire Control Room  Detector System Panel Flow Switch Panel PA System Panel Batter backup	NA NA NA NA	NA NA NA	NA NA NA
	Building Floor Plans	NA NA	NA NA	NA NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

Note: 1. As per the Gazette notification no F(5) (189)/AO/LB/2016/4053-57 dated 27/05/2019, no kitchen will be allowed/used or rooftop/terrace of guest house & if it is used in future the FSC will be treated as null & void.

2. The Owner/Occupier has given undertaking that the restaurant management has provided 04 hours Fire resistance wall between Guest house & Restaurant.

The fire protection systems provided in the building were checked and found functional at the time of inspection. The Shortcomings issued by this department vide letter no F6/DFS/MS/EH/WZ/2023/635 dated 23/11/2023 have been rectified.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

2711/20

Name: Sarabjeet Singh Designation: ADO (MN)