



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F.6/DFS/MS/EH/SZ/2024/ 43

Dated: 07/02/2024

FIRE SAFETY CERTIFICATE

Certified that M/s Limit Less Loop (A unit of SVS Hospitality) Unit No-C-309,C-310, Third Floor, Ansal Plaza, Hudco Place, Khelgaon Marg, Andrews Ganj, New Delhi-110049, comprised of Two tier Basement, Ground, Mezzanine + 03 upper floors, but restaurant running at third floor only was issued fire safety certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2021/03 dated 01/01/2021. The premise was re-inspected by the office concerned of this department on 31/01/2024 in the presence of Sh Ishan (Manager)and observed that the said premise have deemed complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said premise is fit for occupancy class "Assembly Group D" (Eating House) up to 31/03/2027 in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 67/02/2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner, Licensing Unit, 1st Floor, Police Station, Defence Colony, New Delhi-110024 (w.r.t. MHA ID: 2024011200384 dated 13/01/2024)

2. M/s Limit Less Loop (A unit of SVS Hospitality) Unit No-C-309, C-310, Third Floor, Ansal Plaza, Hudco Place, Khelgaon Marg, Andrews Ganj, New Delhi-110049.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

- 4. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry.

1	Name & Address of the Building	ON REPORT	13.20 7.60		
	and the Building	M/s Limit Less Loop (A unit of SVS Hospitality) Unit No-C-309,C-310, Third Floor, Ansal Plaza, Hudco Place, Khelgaon Marg, Andrews Ganj, New			
2	Type of Occupancy	Delhi-110049			
3	Building Comprised of	Assembly "Group-D" (Eating House)			
	comprised of	Two tier Basement, Ground, Mezzanine + 03 u			
4	Type of Case	floors but Restt at running at third floor only. Renewal			
5	Details of Previous NOC	F.6/DFS/MS/EH/SZ/2021/03 dated 01/01/2021			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	31/01/2024			
8	Name of the Inspecting Officers	Santosh Kumar, ADO (SJ)			
9	Name & Designation of Officers from the building side	Sh. Ishan (Manager)			
10	Year of construction	1997–1999			
11	Applicant letter / MHA Portal ID No.	Online ID No. 2024011200384 dated 13/01/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirements/ Existing Fire Protection System	Provided at Site	Remarks MR/NMR	
1	Access to Building.	6			
	Road width	6 m	12 m	MR	
	• Gate width	4.5m	5 m	MR	
2	Width of internal road	6 m	6m	MR	
	Number, width, type & arrangement of exits. a) Number of Staircase Provided & Maintained by Aprel Plaza Marnet				
		Provided & M:	aintained by Ansal Plaz		
	> Upper floors.	2	2	MR	
	> Basement floor.	N/A	N/A	N/A	
	b) Width of Staircase	Provided & Maintained by Ansal Plaza Mgmt.			
	> Upper floors	1.50m	Provided	MR	
	➤ Basement floor	N/A	N/A	N/A	
	c) Protection of exits	Provided & Maintained by Ansal Plaza Mgmt.			
	> Fire check door	Required	Provided	MR	
	> Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	04 Nos(one in A Block, One in B Block & Two in c Block)	MR(Old case)	
	e) Width of corridor	1.5m	Provided	MR	
_	f) Door size	2.00m & 1.50m		MR	
3	Compartmentation.	Provided & M	aintained by Ansal Pla	za Mgmt.	
	 Fire check door. 	Required	Provided	MR	
	 Sealing of electrical shafts. 	Required	Provided	MR	
	 Fire rating of shaft door. 	Required	Provided	MR	
	 Water curtain 	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4.	Smoke Management system.	N. T.			
	Basement	30 a/c per hour	N/A	N/A	
	Ground floor	12 a/c per hour	Exhaust Fans Provided	MR	
5.	Fire Extinguishers.			1107.000	
	Total numbers		106 No.	MR	
	Types	ISI marked	06 Nos ABC/CO ₂ /WCO ₂	MR	
	ISI Marking	131 marked	Provided	MR	
6.	First Aid Hose Reels.	Drovid-10 3			
			aintained by Ansal Pla		
	rotal numbers on each moof.	02	02 (Near Restt)	MR	
	• Length of hose-reel hose.	30m	30m	MR	
	 Nozzle Diameter 	5mm	5mm	MR	



	_	2
r٧		

7	Automatic fire detection & -1	augton:		
-	Automatic fire detection & alarming Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A		N/A
	100	N/A		N/A
	Location of Repeater Panel	Required		
	Alternate source of power			MR
3	Hooter's location	Required	Provided	MR
)	MOEFA	Required	Provided	MR
0	Public Address System Automatic Sprinkler System	Required	Provided intained by Ansal Plaz	MR
-	Basement	N/A	N/A	N/A
	Ground floor.	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.		intained by Ansal Plaz	
	Size of Riser/Down-comer	150mm	150mm	MR
	Number of Hydrant per floor	02 (Near Restt.)	02 (Near Restaurant)	MR
	Hose box.	02 (Near Restt.)	02 (Near Restaurant)	MR
2	Yard Hydrants.		intained by Ansal Plaz	
	Total number of hydrants.	08 Nos	08 Nos	MR
	Hose box.	08 Nos	08 Nos	MR
13	Pumping arrangements.			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
9	Ground Level	Provided & Ma	intained by Ansal Plan	za Mgmt
	Discharge of main pump.	Required	4050 LPM	MR
	➤ Head of main pump.	Required	90m	MR
	Number of main pumps.	Required	02 Nos	MR
	➤ Jockey Pump output.	Required	450 LPM	MR
	➤ Jockey Pump head.	Required	90m	MR
	> Standby Pump output.	Required	8100 LPM	MR
	Standby Pump head.	Required	90m	MR
	Auto Starting/Manual Stopping.Pump house access.	Required	Provided -	MR
	27 December 1982 September 1982 Sept	Required	Provided	MR
77)	Terrace Level	27/4	I NY/A	137/4
	➤ Discharge of pump.	N/A	N/A	N/A
	➤ Head of pump.	N/A	N/A	N/A
	➤ Power supply.	N/A	N/A	N/A
	➤ Auto starting of pump.	N/A	N/A	N/A
4	Captive water storage for fire fighting.	Provided & M	aintained by Ansal Pla	za Mgm
	Underground tank capacity.	450,000 Ltrs	450,000 Ltrs	MR
	, > Draw-off connection.	Required	Provided	MR
	➤ Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	20,000 Ltrs	20,000 Ltrs (AB Blk) 30,000 Ltrs (C Blk)	II.
5	Exit Signage.	Required	Provided	MR
6	Provision of Lifts.			_
20	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
		Required	Provided	MR
	Communication in lift car.	Required	Provided	MR
	 Fireman's switch. 	-	A STATE OF THE STA	MR
	 Lift signage. 	Required	Provided	
7	Standby Power Supply	Required	DG Set Provided	MR
8	Refuge Area			
0	Total area	N/A	N/A	N/A
	• I Ulai aica		N/A	N/A



19	Fire Control Room.	Provided & Maintained by Ansal Mgmt.		
	Detector system panel.	Required	Provided	MR
	 Flow switch panel. 	N/A	N/A	N/A
	 PA system panel. 	Required	Provided	MR
	Battery backup.	Required	Provided	MR
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	CO ₂ and ABC type fire extinguisher provided near electrical panel		MR

Note- The Main File is not traceable in MS Cell and as Remarked, the file was sent to then Dy.CFO (SZ) SH. Sunil Choudhary on 30.09.2022. Further, as directed, the file is re-created with available and downloaded documents from the DFS website.

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/EH/SZ/2021/03 dated 01/01/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA/FT is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)

Minester Mingh 1 M Sirector My 1 M ST

Sir, F.T Letter is putup for your singulation pl

0.5/05/2A