

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No.F6/DFS/MS/GH/NDZ/2024/ 80

Dated: 04/04 /2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Flora Guest House situated at 4179-4181, Urdu Bazar, Jama Masjid, Delhi, comprised of ground + 02 upper floors, ground floor - (commercial use), 1st floor- (03 guest rooms + 01 dormitory for 08 beds), 2nd floor - (04 guest rooms). The guest house was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/119 dated 03.03.2021 for total 07 guest rooms and 01 dormitory for 08 beds. The premises was re-inspected by the officer concerned of this department on 21.03.2024 in presence of Mohd. Zafar (Manager) and found that the building is comprised of ground + 02 upper floors and now the floor wise occupancy is ground floor -(commercial use), 1st floor - (03 guest rooms and 01 dormitory for 05 beds), 2nd floor- (04 guest rooms). The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of class "Residential (Group-A-1)", 1st floor - (03 guest rooms and 01 dormitory for 05 beds) & 2nd floor - (04 guest rooms), total 07 guest rooms and 01 dormitory for 05 beds, with effect from ...04 04 2024... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fjre şerviçe Rules, 2010 printed below.

Issued on 04 04 2024 at New Delhi by

Delhi Fire Service Tel: 011-2341400

Copy to:-

1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2024031102824 dated 11.03.2024.

2. The Licensee, M/s Flora Guest House at 4179-4181, Urdu Bazar, Jama Masjid, Delhi - 110006.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

| 1 | Name & address of the building | 4 | M/s Flora Guest House located at 4179-4181 Urdu Bazar, Jama Masjid, Delhi. | | | |
|----------|--|--------------------------------------|--|------------------|-------------------|--|
| 2 | Building is comprised of Type of Occupancy | | (Ground + 02 upper floors) Ground floor -(commercial use) 1 st floor - (03 guest rooms + 01 dormitory for 05 beds) 2 nd floor - (04 guest rooms) Residential Group A-1 | | | |
| 3 | | | | | | |
| 4 | Type of Case | | Renewal (old case) | | | |
| 5 | Details of Previous FSC | | F6/DFS/MS/GH/NDZ/2021/119 dated 03.03.2021 | | | |
| 6 | Fire Safety direction letter No | | Nil | | | |
| 7 | Date of Inspection Name of the Inspecting Officers | | 21.03.2024 Sumit Kumar, ADO (SPM) | | | |
| 8 | | | | | | |
| 9 | Name of the designation of Office from the building side | ion of Officer Mohd. Zafar (Manager) | | | | |
| 10 | Year of Construction | | 1980 | | | |
| 11 | Applicant's letter No O | | Online ID No. 2024031102824 dated 11.03.2024 | | | |
| S.N o | PROPERTY STATE STATE STATE STATE | fire fety | Requirement/ Existing fire safety arrangements | Provided at Site | Remarks MR/NMR | |
| 1 | Access to building | 1.222 | | | | |
| | Road width | 06 | | 06 m | MR | |
| | Gate width | NA | | NA | NA | |
| 2 | Width of internal road Number, Width, Type and Arran | NA | | NA | NA | |
| 2 | A. Number of Staircases | gem | ent of Exits | | | |
| | | 01 | no | 01 no. | MR | |
| | Upper Floor Basement | 01 no. NA | | NA NA | NA | |
| | B. Width of Staircases | 132 | · | 1777 | INA | |
| | Upper Floor | 80 cms | | 90 to 1.15 cms | MR | |
| | Basement | NA | | NA | NA | |
| | C. Protection of exits | | | | | |
| | Fire check door | NA | | NA | NA | |
| | Pressurization D. No. of continuous staircases to terrace | NA NA | | NA NA | NA NA | |
| | E. Width of Corridor | NA | | NA | NA | |
| | G. Door size | 1 m | | lm | MR | |
| 3 | Compartmentation | | | | 11444 | |
| , | Fire check door | NA | V: | NA | NA | |
| | Sealing of electrical shafts | NA | | NA | NA | |
| | Fire rating of shaft door | NA | | NA | NA | |
| | Water curtain | NA | K. | NA | NA | |
| | Fire Dampers | NA · | | NA | NA | |
| 4 | Smoke Management System. | | | | | |
| | Basement | NA | | NA | NA | |
| | Upper floor | 12a/cper hour | | Natural | MR | |

| • | Fire Extinguisher | | | | | | |
|-------|---|-----------------------|---------------------------------|------|--|--|--|
| | Total numbers | 04 nos. | 04 nos. | MR | | | |
| | types | CO ₂ & ABC | CO ₂ & ABC | MR | | | |
| | IS marking | Required | Provided | MR | | | |
| 6 | First-aid-Hose Reels. | - Indanos | | | | | |
| | Total numbers of onch floor | 01 nos. | 01 no. at 2 nd floor | MR | | | |
| | Length of hose reel hose | 30 m | 30 m | MR | | | |
| | Nozzle diameter | 05 mm | 05 mm | MR | | | |
| 7 | Automatic fire detection and alarming system. | | | | | | |
| | Type of detectors (CO type) | Required | Provided | MR | | | |
| | Location of main panel | Required | Provided at reception | MR | | | |
| | Location of repeater panel | · NA | NA | NA | | | |
| | Alternate source of power | Required | Provided | MR | | | |
| | Hooters | Required | Provided | MR | | | |
| 8 | MOEFA | NA | NA | NA | | | |
| 9 | Public address System. | NA | NA | NA | | | |
| 10 | Automatic Sprinkler System. | | | 1 | | | |
| | Basement | NA | NA | NA | | | |
| | Upper floor | NA | NA | NA | | | |
| | Sprinkler above false ceiling | NA | NA | NA | | | |
| 11 | Internal Hydrants | | | | | | |
| | size of riser/down-comer | NA | NA 💌 | NA | | | |
| | Number of hydrants per floor | NA | NA | NA | | | |
| | Hose Box | NA | NA | NA | | | |
| 12 | Yard Hydrants. | | | | | | |
| PAI | Total number of hydrants | NA | NA | NA | | | |
| - | Hose Box | NA | NA | NA | | | |
| 13 | Pumping Arrangements. | | | | | | |
| 37,75 | Ground Level | | | | | | |
| | > Discharge of main Pump | NA | NA | NA | | | |
| | ➤ Head of Main Pump | NA | NA | NA | | | |
| | > Number of main pumps | NA | NA | NA | | | |
| | ➤ Jockey pump out put | NA | NA | NA | | | |
| | > Jockey pump head | NA | NA | NA | | | |
| | > Standby pump out put | NA | NA | . NA | | | |
| | > Standby pump Head | NA | NA | NA | | | |
| | Auto Starting /Manual stopping | NA | NA | NA | | | |
| | ➤ Pump House Access | NA | NA | NA | | | |
| | Terrace Level | | | | | | |
| | ➤ Discharge of pump | 180 LPM | 180 LPM | MR | | | |
| | > Head of the Pump | 30 m | 30 m | MR | | | |
| | > Power supply | Required | Provided | MR | | | |
| | > Auto Starting of pump | Required | Provided | MR | | | |

| 14 | Captive Water Storage for Fire Fight | NA | NA | NA | | | |
|----|--|-------------|------------|------|--|--|--|
| | Underground tank capacity | | SORGE F | NA | | | |
| | Draw-off connection | NA | NA NA | NA | | | |
| | Fire service inlet | NA | NA NA | NA | | | |
| | Access to tank | NA | 2500 lirs. | MR | | | |
| | Overhead Tank capacity | 2500 ltrs. | Provided | MR | | | |
| | | Required | Provided | 1,11 | | | |
| 15 | Exit Signage. Provision of Lifts. NA NA | | | | | | |
| 16 | Provision of Lifts. | NA - | NA | | | | |
| | Pressurization of Lift Shaft | NA | NA | NA | | | |
| | Pressurization of Lift lobby | NA | NA | NA | | | |
| | Communication in lift car | NA NA | NA | NA | | | |
| | Firemen's grounding switch | 0.4.00.11 | NA | NA | | | |
| | Lift Signage | NA | Provided | MR | | | |
| | Standby power supply | Required | 1107100 | | | | |
| 17 | The state of the s | | | | | | |
| 18 | Refuge Area. | NA | NA | NA | | | |
| | Total area | NA | NA | NA | | | |
| | Location | INA | | | | | |
| 19 | Fire Control Room | Ts.A | NA | NA | | | |
| 17 | Detector system panel | NA | NA | NA | | | |
| | Flow switch panel | NA | NA | NA | | | |
| | PA system panel | NA | NA | NA | | | |
| | Batter backup | NA | NA | NA | | | |
| | | NA | NA NA | NA | | | |
| 20 | Building Floor Plans Special Fire Protection systems for prospecial Risks, if any: | otection of | - 1 | | | | |

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. safety MS/GH/NDZ/2021/119 dated 03.03.2021 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar Designation ADO (SPM)

22/3/24

Dyceo (NO2)

28 m/20

sinceter / 20 00 m

Anyon