

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001**

F.6/DFS/MS/EH/2024/SZ/108 No.

Dated... | Q. / Q.4. / 2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s EBISU situated at Shop No.-11, 12, 13 & 14, Ground Floor, Salcon Tower, Rasvilas Saket, New Delhi- 110017 in the building comprised of 03 Tier Basement, Ground plus Five upper floors, owned/occupied by A Unit of VV Restaurant Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/SZ/2020/133 dated 18/09/2020 for the Name of M/s Laidback Café ITP. The restaurant premise was re-inspected by the officer concerned of this department on 03/04/2024 in the presence of Mr. Kanhaiya and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/04/2024 at New Delhi by

Copy to: -

The Joint Commissioner of Police, Lic Unit, 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MHA Portal ID 2024032203490 dated 22/03/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	7/
	आज्ञादी म
_	अमृत महोत्सव

1		N. C.		100	SM SM	TOTTE	री गा त मह
Company Company	1	INSPECTION	ON REPO	RT			
1	Nam	e & Address of the Building	M/s EBISU (Unit of VV Restaurant Pvt Ltd) (No11, 12, 13 & 14, Ground Floor, Salcon Rasvilas Saket, New Delhi- 110017				at She Tow
2	Туре	of Occupancy	Assembly	Buildi	ng "Group-D" Restaur	ant	40
3	Buile	ing Comprised of	Three tier basement, ground + 05 upper floors				•
4	Туре	of Case	Renewal	Name	Change	11001	
-5		s of Previous NOC			/SZ/2020/133 dated 18	2/00/2	020
181		dan a tekna a Leadig	the Name	of M/s	Laidback Café ITP		Trans
6	Fire	Safety Directives Letter No	F6/DFS/N	AS/Mix	ced/2024/SZ/96 dated	14/	02/20
7	Date	of Inspection	Building 1 03/04/202		- Francis	/ 1	167
8		of the Inspecting Officers			DO (BCP)	/ /	877
9		& Designation of Officers	Mr. Kan			N. C.	-1117
		the building side	WII. Rell	aaya	specifical and		
10		of construction	2008-09	of M	nurant running at G		
11	App	cant letter No.	MHA Por	tal ID	2024032203490 dated	22/03	/2024
S. No	Min	mum standards on Fire Prevention Fire Safety U/R 33	n Old NOC Provided at Site			M	emarl R/NM
185		ss to Building. F6/DFS/			Z/96 dated 14/02/2024	_	_
		Road width	12 m		Provided	M	R
		Gate width	Required	1	Directly accessible	M	
		Width of internal road	06 m		Provided in mall	N/	A
2	Nun of ex	ber, width, type and arrangements			(9.49.)		
90.	a. I	Tumber of Staircase		Restau	rant at Ground floor		
		Upper floors	NA		05 stair provided for n		MR
		Basement floor	N/A	1	05 stair provided for n	nati	MR
	b. \	Vidth of Staircase	ii <u>i</u>		sultur-diener legra		1
		Upper floors	NA N/A		1.5 m each for mall	1	MR
		Basement floor			1.5 m each for mall		MR
	c. I	rotection of exits			Described in sect	_	M
		Fire check door	Required		Provided in mall Provided in mall		N/
		Pressurization	N/A		Provided in mail		M
	100.00	o. of continuous staircase to	Required		System Landbell		
		Vidth of corridor	1.50 mtr		Provided		M
185		Door size	1.50 mtr		1.70m, 0.80m, 0.90m & 0.65m		Ca
3		partmentation.	300	uta i	edif(anl aprints same	9711	(Li)
-	Con	Fire check door.	Requi	red	Provided in mall		M
-11	- I	Sealing of electrical shafts.	Required		Provided in mall		MI
	- I	Fire rating of shaft door.	Required		Provided in mall		MI
	iii iii	Water curtain	N/A		N/A		N/A
	- 41	Fire dampers.	Required		Provided in mall		MF
4.	Smo	ke Management system.	9 -		Provided in mall		N/A
		Basement	30 ACPI		provided		MI
		Upper floors	12 ACPI	t It	provided	1	
5.	Fire	Extinguishers.	04	, All	Provided		M
	1	Total numbers	ABC/CO	, <u> </u>	Provided	F	M
1 - 1		Types ISI Marking	ISI Marke	-	Provided		M
6.	First	Aid Hose Reels.	II .	-	Brendad #	1 10	M
		Total numbers on each floor.	01		Provided	1	M
		Length of hose-reel hose.	30 m		Provided		M
		Nozzle Diameter	05 mm		Provided	- 1	IVI

7	Automatic Et.	1.87	gmiga at Saltan a 1967 2		
455	Automatic Fire Detection and Alarming system.				
	Type of detectors	Required	Provided in mall	T	MR
	Location of Main Panel	Required	Provided in mall		MR
	 Location of Repeater Panel 	N/A	N/A		N/A
	Alternate source of power	Required	Provided in mall	1	MR
	Hooter's location	Required	Provided in mall		MR
8.	MOEFA	Required	Provided in mall	\dashv	MR
9.	Public Address System	Required	Provided in mall	-1	MR
10.	Automatic Sprinkler System	i ici	MST DELEVER THE STATE OF THE	1	
	Basement	N/A	Provided in mall		N/A
	Upper floors	Required	Provided in Restt.	N. O	MR
1	Sprinkler above false ceiling	N/A	N/A	-	N/A
11.	Internal Hydrants.				. 17
	Size of Riser/Down-comer	Required	Provided in mall	I	MR
	Number of Hudrent per floor	Required	Provided in mall		MR
1.5	Hose box.	Required	Provided in mall	77	MR
12.	Yard Hydrants.		Ibla a bank	b	17114
Ţ.	Total number of hydrants.	Required	Provided in mall		MR
	• 2. Hose box.	Required	Provided in mall		MR
13.	Pumping arrangements.		The same of the same		WILL
750	Ground Level	7000	pperson has every delider and	IIIVE	
	Zing tign for more in the trade by	2200 I D) (Dec. 15.11		
	Discharge of main pump.	2280 LPM	Provided in mall		MR
	Head of main pump.	70m	Provided in mall		MR
	 Number of main pumps. Jockey Pump output. 	02	Provided in mall		MR
	> Jockey Pump head.	180 LPM 70m	Provided in mall		MR
line 3	Standby Pump output.	2280 LPM	Provided in mall Provided in mall		MR
	Standby Pump head.	70m	Provided in mail		MR MR
- 1	Auto Starting / Manual Stopping.	Required	Provided in mall		MR
	Access to pump house	Required	Provided in mall		MR
F 3	Terrace Level				.,,,,,
1.7	Discharge of pump.	450 LPM	Connected to mall &		
27	The second secon	430 LPM	restaurant (900 LPM)		h MR
	Trans or panish.	50m	Provided in mall		MR
- 3	- community	Required	Provided in mall		MR
	Auto starting of pump.	Required	Provided in mall		MR
4.	Captive water storage for Fire Fighting.	A 100 SECTION	,necksocyaea	Et G	1 -
1.1	Underground tank capacity.	1,50,000 ltr	Provided in mall 1,50,000	-	N/A
	> Draw-off connection.	N/A	Provided in mall		N/A
	➤ Fire Service Inlet.	N/A	Provided in mall		N/A
	> Access to tank.	N/A	Provided in mail	H	
	Overhead tank capacity	20,000 Ltrs	Connected to mall &	H	N/A
	Tomopto 1	20,000 Lus	restaurant (20000 Ltrs)	П	MR
5.	Exit Signage.	Required	Provided		MR
6.	Provision of Lifts.		Lighter, I		TATIL
	 Pressurization of lift shaft. 	Required	Provided in mall		N/A
	 Pressurization of lift lobby. 	Required	Provided in mall		
_ 1	Communication in lift car.	Required			N/A
1	• Fireman's switch.	- DAV	Provided in mall		N/A
	Lift signage.	Required	Provided in mall		N/A
17	Standby Power Supply	Required	Provided in mall		N/A
8.	Refuge Area	Required	Provided in mall		MR
	Total area	ATV.	and the second s	1	
	• Location	N/A	N/A		N/A
	A STATE OF THE STA	N/A	N/A		N/A



	PA system Panel. Battery backup	Required	Provided in mall	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	1 Totection of special Risk, if any :	roquited	01 CO ₂ type fire extinguishers found provided near electric	MR
2)	The fire protection system provided	in the built	panel	

the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 101 dated 12/03/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2020/133 dated 18/09/2020 for the Name of M/s Laidback Café ITP, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

Online portal case.

Any for approved, F=1. Fetter is prohip to your signature P1