

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/EH/2024/SZ/129

Dated: 07/05/2024

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Royal Eastern Hospitalities Pvt. Ltd at T-540/4, Maharishi Dayanand Marg, Malviya Nagar, New Delhi- 110017 comprised of ground floor only owned/occupied by Royal Eastern Hospitalities Pvt. Ltd was issued fire safety certificate by this department vide letter no F6/DFS/MS/EH/2021/SZ/221 dated 10/09/2021. The restaurant premise was reinspected by the officer concerned of this department on 25/04/2024 in the presence of Mr. Manoj Kumar and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to/ compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07/05/2024 at New Delhi by

Copy to: -

1. The Addl. Commissioner of Police (Lic/Brach), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024041204887 dated 12/04/2024)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the

3. All the staff members must know the correct method of operation of fire-fighting

4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

100			14/23 7/		
	INSPECTION	ON REPORT	आज़ार्द	TIELETA	
1	Name & Address of the Building	M/s Royal Eastern Hospitalities Pvt. Ltd at T-540/4, Malviya Nagar, New Delhi- 110017			
2	Type of Occupancy	Group-D Assembly Building.			
3	Building Comprised of	Ground floor only			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/EH/2	2021/SZ/221 dated 10	)/09/2021	
6	Fire Safety Directives Letter No	4/22/2004/H-III/356-359 dated 22/03/2005			
7	Date of Inspection	25/04/2024		1 101 121	
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Manoj Kumar			
10	Year of construction	1956		1010110001	
11	Applicant letter No.	MHA Portal ID 2	024041204887 dated	12/04/2024	
11/1	The Report of the Part of the	Old NOC	Provided at Site	Remarks	
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement	nemper has I man	MR/NMR	
1	Access to Building.	a premboul 1-	10 m	MR	
	Road width	Required	NT/A	N/A	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	The party of the same of the s	17/12	
2	Number, width, type & arrangement of ex	its. gaug man t	Calculation 2		
A.F	a) Number of Staircase	diamet ve	Tel Employee	N/A	
Kid	> Upper floors.	N/A	N/A	N/A	
-	> Basement floor.	N/A	N/A	IVA	
AW	b) Width of Staircase	sanda ore	NIA NICE	N/A	
	> Upper floors	N/A	N/A N/A	N/A	
	> Basement floor	N/A	N/A	1071	
AW	d) Protection of exits	N/A	N/A	N/A	
	> Fire check door	N/A N/A	N/A	N/A	
5117	> Pressurization		One	MR	
	d) No. of continuous staircase to terrace	Required N/A	N/A	N/A	
21.60	d) Width of corridor	(A-1049-00000)	Provided	MR (old case)	
SHV	1) Door size	1 ma (2 1103)			
3	Compartmentation.	N/A	N/A	N/A	
	• Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts.	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
XI.V	Water curtain	N/A	N/A	N/A	
244	Fire dampers.  Smoke Management system.	4.844	Jan In Its	1 11	
4		20 4 CDYY	N/A	N/A	
	Basement	30 ACPH	Provided in kitchen	MR	
	Upper floors	12 ACPH	Provided in kitchen	IVIK	
5	Fire Extinguishers.	wes 10: rese	total transaction of the		
1.7	Total numbers	06 Nos	08 Nos	MR	
	Types	ABC/CO <sub>2</sub>	Wco2, ABC & CO₂	MR	
31-	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.  • Total numbers on each floor.	One	Provided	MR	
47	TO RESPOND TO THE PARTY OF THE	30m	Provided	MR	
	Length of hose-reel hose.     Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming system		1 TO TIGOU	IVIIC	
	- addition of alarming system				
	Type of detectors	N/A	N/A	N/A	



		N. I.	ON PRINTER LA	V. III
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	NA NA	N/A
10	Automatic Sprinkler System		Sec. 1 Sec. 1	
1000	Basement	N/A	N/A	N/A
	Ground floor.	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	• Hose box. 9	One	Provided	MR
12	Yard Hydrants.		Car I Wade allered	
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.  hrungas	N/A	N/A	N/A
13	Pumping arrangements.		dig of 8	
dist	Ground Level	F-m 7 (6)	(v))m _ 28(326 - 1	52521970
	Discharge of main pump.	o lano N/A erra	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	<ul> <li>Auto Starting/Manual Stopping.</li> <li>Pump house access.</li> </ul>	N/A	N/A	N/A
		MANGARON		
	Terrace Level     Discharge of pump.	450 LPM	Provided	MR
	<ul> <li>Discharge of pump.</li> <li>Head of pump.</li> </ul>	39 m	Provided	MR
	> Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
11017	Captive water storage for fire fighting.	•	words out the date.	8-1
14	Underground tank capacity.	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltrs	10,000 ltr	MR
		Required	Provided	MR
15	Exit Signage.			
16	Provision of Lifts.     Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Pressurization of fit loopy.     Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
8	Refuge Area		Confliction Colored	i A
10		N/A	N/A	N/A
	Total area	N/A	N/A	N/A N/A
u II	• Location	IVA		IN/A
9	Fire Control Room.	N/A		
	Detector system panel.	IV/A	N/A	N/A
	Flow switch panel.	Ñ/A	N/A	Ň/Á
	PA system panel.	N/A	N/A	250000000000000000000000000000000000000
	N .	14/14	* 44.	N/A



	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/221 dated 10/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

explorance of testel in portup for synature of