

C-71

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2024/154

Dated: 22/05/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s. Mughal Mahal Restaurant located at lower ground floor of Sethi Bhawan, 7, Rajendra Place, New Delhi- 110008 in a building comprised of lower ground, upper ground plus six upper floors but restaurant is running at lower ground floor only, was granted FSC by this department vide letter No. F.6/DFS/MS/EH/SZ/2021/322 dated 01.11.2021. The premises was re-inspected by the officer concerned of this department on 14.05.2024 in presence of Sh. Rattanjoy Singh, Owner and found owner have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly (Restaurant) for Lower Ground Floor only with effect from 22/05/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 22/05/2024 at New Delhi by.


(Atul Gurg)
Director
Delhi Fire Service

Copy to:-

1. Sh. Rattanjoy Singh, Owner, M/s. Mughal Mahal Restaurant, Sethi Bhawan, 7, Rajendra Place, New Delhi- 110008.
2. The Deputy Health Officer, North Delhi Municipal Corporation, Public Health Department, Anand Parbat, Karol Bagh Zone, New Delhi- 110005, w.r.t. online id No. 2024042305865 dated 09.05.2024

Following Fire Safety Directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
3. The trained firefighting staffs should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of BBL.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : M/s. Mughal Mahal Restaurant, Sethi Bhawan, 7, Rajendra Place, New Delhi- 110008.
2. Type of Occupancy : Assembly (Restaurant)
3. Type of Case : Renewal
4. Details of previous NOC : F.6/DFS/MS/EH/SZ/2021/322, dated 01.11.2021
5. Fire Safety directives letter No : N/A.
6. Date of inspection : 14.05.2024
7. Name of the Inspecting Officers : Vedpal Chhikara Divisional Officer (SW)
8. Name and designation of officers from the building side : Sh. Rattanot Singh, Owner
9. Year of Construction : Before 1980
10. Applicant's letter No. : Online Id 2024042305865, dated 09.05.2024

The said restaurant is running at lower ground floor of Sethi Bhawan comprised of lower ground, upper ground plus six upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt.- 08.08.2018	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	09 mts	Provided	MR
	• Gate width	4.5 mts	Provided	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	-	Running at ground lower ground floor	--
	• Basements	N/A	N/A	N/A
	b. Width of staircases	-	-	-
	• Upper Floors	-	Running at ground lower ground floor	--
	• Basements	N/A	N/A	N/A
	c. Protection of exits	N/A	N/A	N/A
	• Fire check door	-	-	-
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
		N/A	N/A	N/A
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	02 exit door	1.86 mts & 1.03 mt	MR being old case
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	Sealed	----
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements	30 a/c per hour	N/A	N/A
	• Upper floors	12 a/c per hour	Provided in kitchen	MR
5	Fire Extinguishers			
	• Total numbers	08	Provided	MR
	• Types	CO ₂ , ABC type	Provided	MR
	• IS marking	IS I marked	Provided	MR

Provision of Lifts.				
16	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car			N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided independently	MR being old case
18	Refuge Area.			
	Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note:- The FSC issued to the Sethi Bhawan Building is also renewed. If agreed FSC to Mughal Mahal Restaurant may be issued as the restaurant management have installed requisite fire arrangements such as overhead fire water tank, fire pump, hose reel, down comer, standby power supply, MOEFA etc. independently. Further, it is mentioned that entry/exit of restaurant are separated from rest of the building

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/EH/SZ/2021/322, dated 01.11.2021, renewal under Rule 37 of the Delhi Fire Service rules 2010 is recommended. Accordingly, DFA is put up for approval & signature please.

(Signature)
 Vedpal Chhikara
 Divisional Officer (SW)

CFD (S2)
 Mughal Mahal
 15/5/2022
(Signature)
 Director
 Dd/SW

15 fire buds gat.
 No ?
(Signature)
 17/5/22

P.T.O