

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2024/School/ 516

Dated: 07/06/2024

FIRE SAFETY CERTIFICATE

Certified that the Mother's Womb Global School located at Khasra No. 357-358, Gali No-2, Kushak Road, J-Block, Swaroop Nagar, Delhi-110042 comprised of Ground & 02 upper floors only owned/occupied by the Mother's Womb Global School have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 28.05.2024 in the presence of Mr. Avinash Rana and that the building/premises is fit for occupancy Class "Group B Educational" with effect from .07.06.2024.... for a period of three years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07 06 2024 at New Delhi

Atul Gars)
6 Director
Ph:-011-23414000

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Mother's Womb Global School located at Khasra No. 357-358, Gali No-2, Kushak Road J-Block, Swaroop Nagar, Delhi-110042.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

: Mother's Womb Global School at Kh. No. 357-358, Gali No-2, Kushak Road, Name & address of the building

J-Block, Swaroop Nagar, Delhi-110042.

Composition of building

: Ground & 02 upper floors only

Type of Occupancy 3.

: Educational

4. Type of Case

: New

Details of previous NOC

: Nil

Fire Safety directives letter No 6.

: NBC Part-IV

7. Date of inspection

: 28.05.2024

: ADO (RN)

Name of the Inspecting Officers Name and designation of officers

from the building side

: Mr. Avinash Rana

10. Year of Construction

: 2022-23

11.		THE REPORT OF THE PARTY OF THE	E-mail dated 24.05.2024 NBC Part 4	Provided at site	Remarks MR/NMR	
	Minim	um Standards on fire prevention and fire safety U/R 33	Requirements		Tenno in	
	Access	to building		0/	MR	
			06m	06m) (n)	
	•	Road width	Directly Accessible	Directly Accessible	MR	
	•	Gate width		NA	NA	
	•	Width of internal road	NΛ			
	Number, Width, Type & Arrangement of Exits					
		per of staircases	02	02	MR	
		Upper Floors		NA	NA	
		Basements	NA			
	1			1.50m	MR	
	b. Wid	h of staircases	1.50m	NA	NA	
		Upper Floors	NA			
		Basements			NA	
	c. Prote	ction of exits	NA	NA	NA NA	
		Fire check door	NA	NA	A	
	•	Pressurization	02	02	MR	
	d. No.	of continuous staircases to terrace	NA NA	NA	NA	
	e. Widt	h of Corridor	1.20m	Provided	MR	
	f. Door	Size				
	Compa	rtmentation.		NA	NA	
		Fire check door	NA	NA	NA	
		Sealing of electrical shafts	NA	NA	NA	
		Fire Rating of shaft door	NA	555277	NA	
	•		NA NA	NA		
	•	Water Curtain		NA	NA	
		Fire Dampers	NA		7 314	
	Smoke	Management System.	NΛ	NA	NA	
		Basements	1250	Provided	MR	
	7.	Upper floors	Required			
				09nos	MR	
	Fire E	tinguishers	09nos		MR	
	•	Total numbers	ABC/CO2	ABC—09		
		Types		Yes	MR	
			ISI Marked			
		ISI marking				

5	First-Aid Hose Reels.	H 2					
	Total numbers on each floor	01 at each floor	Provided	MR			
	Length of hose reel hose	30m	30m				
	Nozzle diameter	5mm					
	Automatic fire detection and alarming sys	5mm	MR				
	Type of detectors	NA	NA	NA			
	 Location of Main Panel 	NA	NA	NA (
	 Location of Repeater Panel 	NA	NA	NA			
	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA					
	MOEFA	Required	NA .	NA			
	Public Address System.	NA	Provided	MR			
)	Automatic Sprinkler System.	INA I	NA	NA			
	Basement	NΛ					
	Upper Floor	NA NA	NA NA	NA NA			
	23-23-3	NA NA	NA NA	NA NA			
1	aprimine above laise celling	13/3	IVA	NA			
ı	Internal Hydrants Size of riser/down-comer		1 3				
		NA NA	NA	NΛ			
	Number of hydrants per floor	NA NA	NA NA	NA			
	Hose Box	INA	NA	NA			
2	Yard Hydrants.						
	Total number of hydrants	NA	NA	NΛ			
	Hose Box	NA'	NA	NA			
3	Pumping Arrangements.						
	Ground Level						
	 Discharge of main Pump 	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A				
	> Jockey Pump out put	SCA350		N/A			
	> Jockey pump head	N/A	N/A	N/A			
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A			
	> Auto Starting/ Manual	N/A	N/A	N/A			
	stopping	N/A N/A	N/A	N/A			
	Pump House Access	IN/A	N/A	N/A			
	Terrace level	Washington Co.					
	Discharge of pump	450 LPM	Provided	MR			
	➤ Head of the pump	40m	40m	MR			
	Power Supply	Required	Provided	MR			
14	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting.						
	Underground tank capacity	NA	NA	NA			
	Draw-off connection	NA NA	NA	NΛ			
	Fire service inlet	NA NA	NA	NΛ			
	Access to tank	NA	NA	NA 14D			
	Overhead Tank capacity	10,000 LTR	Provided	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.	ij išpi i					

	Pressurization of Lift Shaft	N/A	N/A	N/A		
	• Pressurization of Lift lobby	N/A	N/A	N/A		
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A		
		N/A	N/A	N/A		
	(1) 11	N/A	N/A	N/A		
7	Standby power supply	NΛ	NA .	NA		
8	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Centrol Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System PanelBatter backup	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by NBC Part-IV, it is recommended to grant Fire Safety Certificate

Dy. Chief Pire Officer (WZ)

Signature of the Inspecting Officer Name:-C.L. Meena

Designation:- Asst. Div. Officer (RN)

on the last

21/5/2000
21/5/2000
Denected My C 200

Aorten

conf. ... P.T.O.