

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2024/SZ/ 155

Dated: 22/05/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s **ROOH** located at **H-5/1 (LHS), First Floor, Kalka Das Marg Main Road, Mehrauli, New Delhi-110030** in a building comprised of Ground, 1st & 2nd Floor (one room only) owned/occupied by A Unit of Avenashi International Pvt. Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2021/SZ/113 Dated 13/05/2021. The restaurant premise was re-inspected by the officer concerned of this department on 16/05/2024 in the presence of Mr. Gaurav Singh (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** (Restaurant at FF only) and **validity upto 31/03/2027** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22 / 05 / 2024 at New Delhi by


(Atul Garg)
Director
Delhi fire service

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024042005652 dated 21/04/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
7. **The Fire fighting terrace level pump shall also be made /functional on auto made within 3 months of issuance of FSC issued. Else otherwise, this FSC may be treated as null & void.**

| INSPECTION REPORT | | | | |
|-------------------|---|--|-----------------------|---------|
| 1 | Name & Address of the Building | M/s Rooh (A Unit of Aveenashi Hospitality Pvt. Ltd) H-5/1, FF, Kalka Das Marg Main Road, Mehrauli, New Delhi | | |
| 2 | Type of Occupancy | Assembly 'Group-D' | | |
| 3 | Building comprised of | Ground, 1 st & 2 nd Floor (one room Only) (Restaurant at 1st Floor) | | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F6/DFS/MS/EH/2021/SZ/113 Dated 13/05/2021 | | |
| 6 | Fire Safety Directives Letter No | NA | | |
| 7 | Date of Inspection | 16.05.2024 | | |
| 8 | Name of the Inspecting Officers | DO (South) & ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Sh. Gaurav Singh | | |
| 10 | Year of construction/ date of conversion | 2010 | | |
| 11 | Applicant letter No. | MHA Portal ID 2024042005652 dated 21/04/2024 | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | UBBL/NBC-IV Requirement | Provided at Site | Remarks |
| 1 | Access to Building. | | | |
| | • Road width | 06m | 06 m | MR |
| | • Gate width | 4.5 m | 4.5 m | MR |
| | • Width of internal road | NA | NA | -NA- |
| 2 | Number, width, type & arrangement of exits | | | |
| | a. Number of Staircase | | | |
| | • Upper floors | 02 | 02 | MR |
| | • Basement floor | -NA- | NA | -NA- |
| | b. Width of Staircase | | | |
| | • Upper floors | 1.50 mtr each | 1.66m & 1.50 m | MR |
| | • Basement floor | N/A | N/A | N/A |
| | c. Protection of exits | | | |
| | • Fire check door | Required | Provided | MR |
| | • Pressurization | -NA- | NA | -NA- |
| | d. No. of continuous staircase to terrace | 02 | 02 Provided | MR |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | 2 Exits | 2m & 1.50m | MR |
| 3 | Compartmentation. | | | |
| | • Fire check door. | Required | Provided | MR |
| | • Sealing of electrical shafts. | Required | Provided | MR |
| | • Fire rating of shaft door. | Required | Provided | MR |
| | • Water curtain | N/A | N/A | N/A |
| | • Fire dampers. | N/A | N/A | N/A |
| 4 | Smoke Management system. | | | |
| | • Basement | 12 ACPH | N/A | N/A |
| | • Upper floors | 12 ACPH | Provided | MR |
| 5 | Fire Extinguishers. | | | |
| | • Total numbers | 04 Nos | 04 | MR |
| | • Types | ABC / CO2/W.CO2 | ABC -4/ CO2-4/W.CO2-4 | MR |
| | • ISI Marking | ISI marked | Provided | MR |
| 6 | First Aid Hose Reels. | | | |
| | • Total numbers on each floor. | One | Provided | MR |
| | | 30m | Provided | MR |

| | | | | |
|----|---|----------|----------|------|
| 17 | Standby Power Supply | | | |
| 18 | Refuge Area | Required | Provided | MR |
| | <ul style="list-style-type: none"> Total area Location | -NA- | -NA- | -NA- |
| 19 | Fire Control Room. | -NA- | -NA- | -NA- |
| | <ul style="list-style-type: none"> Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| 20 | Special Fire Protection System for the Protection of special Risk, if any : | -NA- | -NA- | -NA- |

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 154 dated 25/04/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/113 Dated 13/05/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Handwritten signature

Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

Handwritten signature
13/5/2024

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFD
Handwritten signature
18/5/2024

Director
Handwritten signature
20/5/24

FT PLS

Handwritten signature
20/5/24

As approved, F.T. letter is put up for your signature @

Director
Handwritten signature
22/5/24

Handwritten signature
22/5/24

Handwritten signature

Updated
22/05/24