## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2024/EH/WZ/ 24/ <u>FIRE SAFETY CERTIFICATE</u> Dated 25/07/2024

Certified that the M/s Bikanervala, Pvt. Ltd, located at 103, 104 & 105, 1<sup>st</sup> floor, Ring Road Mall, Sector-3, Rohini, Delhi-110085 in running at ground floor, Shop No.103, 104 & 105 in a mall building comprised of basement, ground and 08 upper floors owned/occupied by M/s Bikanervala Foods Pvt. Ltd was granted NOC by this department vide letter no. F.6/DFS/MS/2021/EH/WZ/149 dated 23.07.2021. The premises was re-inspected by the officers concerned of this department on 10.07.2024 in the presence of Mr. Puspender Altmas and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. Hence the NOC is renewed and premises is fit for occupancy Class (Assembly) for first floor only with effect from - 25 67 2024 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 25/07/2024 at New Delhi by

(Ata (Carly) DIRECTOR Ph; 011-23414000

Dr

Copy to:-

MHA Portal Id-2024070210258 dated 03.07.2024.
 Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

 Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.Delhigovt.nic.in">WWW.dfs.Delhigovt.nic.in</a>

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

7	1	INCDECT	TION REPORT		
1	8		anervala, Pvt. Ltd, located	at 103-105, 1st flo	or, Ring Road
FI.	Name & address of the buil	ding M/s Bika Mall, Se	ctor-3, Rohini, Delhi-1100	)85	
<u>_</u>	Type of Occupancy		(Restaurant running at		03, 104 & 105)
-	Type of Case	Renewal	(Restaurant running at /MS/2021/EH/WZ/149 da	ted 23 07 2021	
4	Details of Previous NOC		/MS/2021/EH/ W2/149 da OC- F.6/DFS/MS/2021/W	7/334 dated 16.07	.2021)
5.	Fire Safety directives letter			Zijji dalog zoto	
6.	Date of inspection	10.07.20	024 Kumar Sharma (ADO Ro	ohini)	
7.	Name of Inspecting Office			· · · · · · · · · · · · · · · · · · ·	
8.	Name and designation of of From the building side		pender Altmas.		
9.	Year of Construction	2007		10050 1-1-102 07	2024
10.	. Applicant's letter No.		application No. 20240702	Durwided at	Remarks
S.	Minimum Standards on	fire prevention	NBC	110,1202	MR/NMR
No	and fire safety U/R 33		Requirement	3160	A TOTAL PARTY CONT.
1.	Access to building Ring 16.07.2021	Road Mall issue	d FSC vide letter No. F	.6/DFS/MS/2021/\	VZI334 dated
	Road width				
	Gate width		D ( 121 1 1 1 1 1 1	As Above	MR
	Width of internal	road	Restaurant within Mall	As Above	WIIC
2.	Number, Width, Type &		Exits [Provided & Main	ntained by Mall ma	nagement
4.	d. Number of staircases		•		
	Upper Floors		Restaurant within Mall	As Above	NA
	Basements		Restaurant within Mall	As Above	NA
				110110010	
	e. Width of staircases		Restaurant within Mall	As Above	NA
	Upper Floor				
2.2	Basements		Restaurant within Mall	As Above	NA
	Service Security of Kennese Holes (September 1).				
	Fire check door		Restaurant within Mall	As Above	NA
	Pressurization		Restaurant within Mall	As Above	NA
	d. No. of continuous sta	ircases to terrace	Restaurant within Mall	As Above	NA
	e. Width of Corridor		Restaurant within Mall	As Above	NA
	f. Door Size		02 exit	1.80m & 1.70m	MR
3.	Compartmentation	4 4			
	Fire check door		Restaurant within Mall	As Above	NA
	Sealing of electrical shafts		Restaurant within Mall	As Above	NA
	Fire Rating of shaft door		Restaurant within Mall		NA
	Water Curtain	The second secon	Restaurant within Mal		NA
	Fire Dampers		Restaurant within Mal		NA NA
4.	Smoke Management System				
	a) Basements		[Provided & Maintained by Mall management  Restaurant within Mall		
			THE PLANT COMPANY OF THE PROPERTY		NA
5.	b) Upper floors		Restaurant within Mal		NA
Э.	Fire Extinguishers		[Provided & Maintained by Mall management		
143	Total numbers		04nos.	04nos.	MR
	• Types		ABC/CO2	ABC/CO2	MR
-	IS marking		ISI marked	Yes	MR
6.	First-Aid Hose Reels		[Provided & Maintained by Mall management		
	<ul> <li>Total numbers on each floor</li> </ul>		01nos.	As Above	MR
	<ul> <li>Length of hose reel hose</li> </ul>		30mm	As Above	MR

17 10

Cm-

- 1	И-		т
- 1		•	

	ž			M	
			As Above	IVI	
		5m	ined by Mall mana	gement	
	Nozzle diameter	5m  [Provided & Mainta	As Above	NA NA	
7.	Nozzle diameter  Automatic fire detection and alarming sys		As Above	1111	
<i>/</i> ·	a) Type of detectors		As Above	NA	
- 1	b) Location of Main Panel	want William Island	As Above	NA	
	c) Location of Repeater Panel	within with	As Above	NA	
	d) Alternate source of power	Restaurant within Mall	Provided	MR	
	e) Hooters' Location	Required	As Above	MR	
8.	MOEFA	-NA- [Provided & Maintaine	As Above	nent	
9.	Public Address System	[Provided & Maintaine	As Above	NA	
10.	Automatic Sprinkler System	Dectaurant within Mail	1.40.0001.0001	NA	
10.	Basement	Restaurant within Mail	As Above	NA	
	Ground & Upper Floors	Restaurant within Mall	As Above	ement	
	Sprinkler above false ceiling	Restaurant within Mall [Provided & Maintai	ned by Mall manag	MR	
11.	Internal Hydrants	100mm	715	MR	
11.	Size of riser/down-comer	Restaurant within Mall	As Above	MR	
	Number of hydrants per floor	Restaurant within Mall	As Above	IVIX	
	Hose Box	Kestaurant Within		NIA	
12.	Yard Hydrants	-NA-	-NA-	-NA-	
12.	Total number of hydrants		-NA-	-NA-	
	Hose Box	-NA-	Provided & Maintained by Mall management  NANA-		
13.	Pumping Arrangements	Provided & Manten	-NA-	and the same of th	
	Ground Level	-NA-	-NA-	-NA-	
	<ul> <li>Discharge of main Pump</li> </ul>	-NA-	-NA-	-NA-	
	Head of Main pump	-NA-	-NA-	-NA-	
	Number of main pumps	-NA-	-NA-	-NA-	
	Jockey Pump out put	-NA-	-NA-	-NA-	
	Jockey pump head	-NA-	-NA-	-NA-	
	Standby Pump out put	-NA-	-NA-	-NA-	
	> Standby Pump Head	-NA-	-NA-	-NA-	
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-	
	> Pump House Access	-NA-		746 22 4742	
	Terrace level [Provided & Maintained by Mall management]  NA As Above MR				
	Discharge of pump	-NA-	As Above	MR	
	> Head of the pump	-NA-	As Above		
	> Power Supply	Required	As Above	MR	
	Auto Starting of pump	Required	As Above	MR	
14.	Provided & Maintained by Mall management				
(A)	Underground tank capacity	-NA-	As Above	-NA-	
	> Draw-off connection	-NA-	As Above	-NA-	
	> Fire service inlet	-NA-	As Above	-NA-	
		-NA-	As Above	-NA-	
	> Access to tank				
	Overhead Tank capacity	-NA-	As Above	-NA-	
15.		Required	Provided	MR	
16.	Provision of Lifts.	[Provided & Maintained by Mall management			
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-	
	Pressurization of Lift lobby	-NA-	-NA-	-NA-	
	Communication In lift Car	-NA-	-NA-	-NA-	
	Communication				

Cm

Tagent 1	in Signage	-NA-	-NA-	-NA-	
到型	Lift Signage	-NA-	-NA-	-NA-	
PS	Standby power supply	tained by Mall man	by Mall management		
R	Refuge Area.  > Total Area	-NA-	-NA-	-NA-	
	> Location	-NA-	-NA-	-NA-	
	ire Control Room				
19. F	Detector System Panel	-NA-	-NA-	-NA-	
	Flow Switch Panel	-NA-	-NA-	-NA-	
	PA System Panel	-NA-	-NA-	-NA-	
-	Battery backup	-NA-	-NA-	-NA-	
-	Building Floor Plans	-NA-	-NA-	-NA-	
	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-	

The fire protection systems provided in the building were test checked and found functional

at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2021/EH/WZ/149 dated 23.07.2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma

Designation ADO(Rohini)

D.B Mukherjee DO (NW)

Dy 1/2 10

16/2

Dênela My

Any Rom

FT letter is fout up for kind | Sonature Dean.

incom sold on a blooded