



No. F6/DFS/MS/EH/SZ/2024/ 265

Dated: 19/08/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Haldiram Marketing Pvt. Ltd., located at TA-98, Upper Ground floor, Gali No. 1, Road No. 13, Okhla Estate Road, Tughlakabad Extn., New Delhi-19, running at Upper Ground floor only of the building which is comprised of Basement + Upper Ground + 04 upper floors (4th floor half built), owned & occupied by M/s Haldiram Marketing Pvt. Ltd has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by a team of officers concerned of Delhi Fire Service on 07.08.2024 in the presence of Mr. Alok (Manager) and found that the building/premises is fit for occupancy class Group 'D' (Assembly)- Restaurant (Upper Ground floor only) and valid upto 31.03.2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Director Delhi Fire Service

24

Reference: MHA Portal Online application no. 2024072611611.

Copy to:-.

 The Commissioner, Municipal Corporation of Delhi, 9th Floor, Dr. SPM Civic Centre, Minto Road, New Delhi-110002.

Conditions for the validity of Fire Safety Certificate

- 1. This Fire Safety Certificate is valid for Upper Ground floor only.
- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

Г		IN	SPECTION REPOR	T					
1		Name & address of the building			. Ltd., located				
				M/s Haldiram Marketing Pvt. Ltd., located TA-98, Upper Ground floor, Gali No. 1, Ros No. 13, Okhla Estate Road, Tughlakaba Extn., New Delhi-19.					
			Extn., New De						
2		Building is comprised of	Basement +Up	Basement +Upper Ground + 04 upper floors (4th floor half built)					
	- 1		floor half built)						
	Type of case Details of previous FSC Fire safety directives letter no. Date of inspection		Restaurant runni	Restaurant running at Upper Ground floor only					
3			Assembly Building (Group-D) New case Nil UBBL/NBC-2016 07.08.2024 Manoj Kumar Sharma, DO (SD) & Rajesh Kumar						
4									
5									
6									
7									
8									
U				Shukla, ADO (M. Road)					
9	1	Name of the designation of officer	The second company of the second	Mr. Alok (Manager)					
	From the building side								
10	1	Year of construction	2009 (as per MHA online application)						
11	1	Applicant's letter no.	MHA online appl	ication no. 2024072	2611611				
		Minimum standard of Fire	Requirements as		Remarks				
	9)(10)	Prevention and Fire Safety U/R 33			MR/NMR				
ı	_	Access to Building							
	A	The Control of the Co	6.0 mtrs	Provided	MR				
	В	Gate width	NA	NA	NA				
	C	Width of internal roads	NA.	NA	NA				
	Number, Width, Type & Arrangement of Exits (Restaurant running at Upper Ground)								
Π	A								
		a) Upper floor	NA	NA	NA				
		b) Basements	NA	NA	NA				
	В	Width of the staircase:	l lest-						
		a) Upper floors	NA	NA	NA				
		b) Basements	NA	NA	NA				
	C	Protection of Exits							
		a) Fire check door	NA	NA	NA				
		b) Pressurization	NA	NA	NA				
	D	No. of continuous staircase to	NA	NA	NA				
		terrace:							
	E	Width of the corridor	NA	NA	NA				
	F	Door size (Exits)	2.0 m & 1.50 m	2.0 m & 1.50 m	MR				
3	Co	mpartmentation:		7 70					
	A	Fire check doors	NA	NA	NA				
	В	Sealing of horizontal & vertical opening	NA	NA	NA				
	C	Fire rating of shaft doors	NA	NA	NA				
	D	Water curtain	NA	NA	NA				
		Fire dampers	NA	NA	NA				
	E	The dampers		Smoke Management System:					
4		oke Management System:		Thomas Survey	December 1974				
4		oke Management System: Basements	NA	NA	NA				
4	Sm	oke Management System:	NA NA	NA NA	NA NA				
	Sm A B	oke Management System: Basements							
	Sm A B	oke Management System: Basements Upper floors	NA						
4	Sm A B Fire	oke Management System: Basements Upper floors Extinguishers	NA	NA	NA				

6	First Aid Hose Reel							
	A	Total no. at each floor	01 no.	01 no.	MR			
	В	Length of hose reel	30 mtrs	30 mtrs	MR			
	C	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic Fire Detection and Alarm System (ADAS)							
	A	Type of detectors	Provided	NA				
	В	Location of main Panel	NA NA	Provided	NA NA			
	C	Location of repeater panel	NA	NA	NA NA			
	D	Alternate power source	NA	NA NA	NA NA			
	E	Hooter's location	NA	Provided	S24322			
8	М	OEFA	Required	Provided	NA			
9		ıblic Address System	NA	NA	MR			
10	Automatic Sprinkler System NA NA NA							
-	A	Basement	NA	NA	Lara			
	В	Upper floor	NA NA	Provided	NA			
	C	Sprinklers above false ceiling	NA NA	NA	NA			
11	-	ternal Hydrants	IMA	INA	NA			
	A	Size of the riser/down comer	100 mm	Provided	1.00			
	В	No. of hydrants per floor			MR			
		Hose box	1 no.	1 no.	MR MR			
12	. no. 1 no.							
14	A	Total no. of hydrants	1377					
	B	Hose box	NA	NA	NA			
13	1	Lateratives are source	NA	NA	NA			
13	A	Pumping Arrangements A Ground Level						
	A		1374					
	3	a) Discharge & head of main pump b) Number of main pump	NA	NA	NA			
			NA	NA	NA			
		c) Discharge & head of jockey pump	NA	NA	NA			
		d) Discharge & head of Standby pump	NA	NA	NA			
	D	e) Auto starting/ manual stopping	NA	NA	NA			
	В	B Terrace Level						
		a) Discharge of terrace pump	450 LPM	2 nos. of 450 LPM	MR			
		b) Head of terrace pump	40 m	Provided	MR			
		c) Alternate power supply	Required	Provided	MR			
14		d) Auto starting of pump	Required	Provided	MR			
4	Captive Water Storage for Fire Fighting							
	A B	Underground tank capacity Draw off connection	NA	NA	NA			
		Fire Service Inlet	NA	NA	NA			
	E	Access to tank	Required	Provided	MR			
	D		Required	Provided	MR			
5		Overhead tank capacity t Signage	20,000 ltrs	Provided	MR			
6			Required	Provided	MR			
v	Provision of lift: A Pressurization of lift shaft NA NA NA							
	B	Pressurization of lift shaft	NA	NA	NA			
		Pressurization of lift lobby	NA	NA	NA			
		Communication in lift car Fireman switch	NA	NA	NA			
	$\overline{}$	Sales of Contract Con	NA	NA	NA			
7		Lift signage	NA	NA	NA			
e.	Stal	ndby Power Supply	Required	Provided	MR			

M/s Haldiram Marketing Pvt. Ltd., located at TA-98, BSMT, Ground floor, Gali No. 1, Road No. 13, Okhla Estate Road, Tughlakabad Extn., New Delhi-19..





M/s Haldiram Marketing Pvt. Ltd., located at TA-98, BSMT, Ground floor, Gali No. 1, Road No. 13, Okhla Estate Road, Tughlakabad Extn., New Delhi-19.

18	Refuge Area					
	A	location	1311			
	B	Total area	NA	NA	NA	
19	Fir	e Control Room	NA	NA	NA	
110	A	Fire detection system panel	NA	1504	NIA	
	B	Flow switch panel	NA	NA	NA	
44	C	P a system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA NA	
	E	Building floor plan	NA	NA NA	NA NA	
20	Special Fire Protection for special risk if any					
	A Special fire protection system for protection of special risk, if any:			NA		

LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

Note:- A small portion of the basement (approx 50 m²) of the building is being used as storage by this restaurant management but this portion has no connection with the restaurant at upper ground floor and has an independent exit directly from the side street. This portion has not been considered as part of this restaurant in this inspection.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above & in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 35 of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Manoj Kumar Sharma
Designation DO (SD)

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M. Road)

Director 1 196 86K, This NOC18
Why we are would that use the sound I had use the sound I had use the sound as the sound sould be sould be

OUS milejon

900