

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आजादी र अमृत महोत्मव

No. F6/DFS/MS/School/WZ/2024/ S47

Dated: 30 08 20 24

### FIRE SAFETY CERTIFICATE

Park, Nangloi, Delhi-110041, comprised of Ground Floor only owned/occupied by J.S.M. Public School have complied with the fire prevention and fire safety requirements in accordance with D.O.E Circular No. 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on 13/08/2024 in the presence of Mrs. Sangeeta Yadav (Principal) and that the building/premises is fit for occupancy class "Educational Building" Group B with effect from

Issued on . 30.08 2024. at New Delhi by.

Director

Tel No. 011-23414000

#### Copy to:-

 The Deputy Director, Delhi Municipal Corporation, Civic Centre, Minto Road, Delhi-110002.

 The Principal, J.S.M. Public School, B-11 Street No. 2 and 3, Shiv Baksh Park, Nangloi, Delhi-110041.

# Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

 Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

## **INSPECTION REPORT**

1. Name and address of the building: J.S.M. Public School located at B-11 Street No. 2 and 3, Shiv Baksh Park, Nangloi, Delhi-110041

2. Type of Occupancy : Educational (Ground Floor only)

3. Type of Case : New

4. Details of previous NOC : Nil

: D.O.E Circular no.3298-3398 dated 01-03-2011 Fire Safety directives Letter No.

6. Date of inspection : 13/08/2024

: Aman Kumar Lathar, ADO (JWP) 7. Name of the Inspecting Officer

8. Name and designation of Officer

: Mrs. Sangeeta Yadav (Principal) from the building side

: 2022-23 9. Year of Construction

S No	Minimum standards on fire prevention and fire safety U/R	D.O.E. Cr. No. 3298 3398 dated 01.03.20	- Provided at 11 site	Remarks MR/NMF
1.	Access of building		Provided	MR
	Road width	06 m	Provided	MR
	Gate width     Width of internal road	4.5 m NA	NA NA	NA
2.	Number, width, Type & Arrangen	nents of exits		
۷.	a. Number of staircases		1274.7	
	Upper floors	01	Provided	MR
	Basements	NA	NA	NA
	b. Width of staircases		1 02 1	MR
	Upper floors	1.5 m	1.83 m x 1	NA
	Basements	NA	NA	INA
100	c. Protection of exits			NIA
	<ul> <li>Fire check door</li> </ul>	NA	NA	NA
	<ul> <li>Pressurization</li> </ul>	NA	NA	NA
	d. No of continuous staircase to terrace	01	Provided	MR
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	NA	NA	NA
2	Compartmentation		NA	
3.	Fire check door	NA	NA	NA
	Sealing of electrical shafts	NA	NA	NA
	Fire Rating of shaft door	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
4.	Smoke managements System			
	Basements	NA	NA	NA
	Upper floors	- NA	NA	NA
5.	Fire Extinguishers			
٠.	Total numbers	03 nos.	Provided	MR
	<ul> <li>Types</li> </ul>	ABC & CO <sub>2</sub>	Provided	MR
	ISI marking	ISI Marked	Provided	MR

	г	•	•	-	300
			•		-

	First – Aid Hose Reel			
	Total numbers on each floor	NA	NA	NA
	<ul> <li>Length of hose reel hose</li> </ul>	NA	NA	NA
	Nozzle diameter	NA	NA	NA
7.	Automatic fire detection and alarming sy		,	
	Type of detectors	NA	NA	NA
	<ul> <li>Location of Main Panel</li> </ul>	NA	NA	NA
- 1	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
8.	MOEFA	NA	NA	NA
9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System	A-100-1-1-1		IVA
	Basements	NA	NA	NA
	Upper Floor	NA	NA	
	Sprinkler above false ceiling	NA	NA NA	NA NA
11.	Internal Hydrants:		IVA	I NA
	Size of riser/down-comer	NA	NA	374
	Number of hydrants per floor	NA	NA NA	NA NA
	Hose Box	NA NA	NA NA	NA NA
12.	Yard Hydrants	INA	NA	NA
	Total number of hydrants	NIA	N	
	Hose Box	NA NA	NA	NA
13.	Pumping Arrangements:	NA	NA	NA
0.5	Ground Level			
	Discharge of main pump	NIA		
	> Head of main pump	NA NA	NA	NA
	> Number of main pumps	NA	NA	NA
	> Jockey pump out put	NA	NA	NA
	> Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	Standby Pump Head	NA	NA	NA
	> Auto Staring/Manual	NA	NA	NA
	stopping > Pump House Access	NA	NA	NA
	Terrace level	NA	NA	NA
	Discharge of pump			TAMES N
	> Head of the pump	NA	NA	NA
	> Power supply	NA	NA	NA
	> Auto starting of pump	NA	NA	NA
14.		NA	NA	NA
A T.	Captive water Storage for fire fighting:			
	<ul> <li>Under ground tank capacity</li> <li>Draw off connection</li> </ul>	NA	NA	NA
	> Fire service inlet	NA	NA	NA
	> Access to tank	NA	NA	NA
	ACCCSS TO TAUK	NA	NA	NA
15	Overhead Tank capacity	NA	NA	NA
15	Overhead Tank capacity     Exit Signage	NA NA	NA NA	NA NA
15 16.	Overhead Tank capacity     Exit Signage     Provision of Lifts	NA		NA NA
	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft	NA NA		NA
	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby	NA NA NA	NA	NA NA
	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car	NA NA NA	NA NA	NA NA NA
	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car     Fireman's Grounding Switch	NA NA NA NA	NA NA NA	NA NA NA NA
16.	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car     Fireman's Grounding Switch     Lift Signage	NA NA NA	NA NA NA	NA NA NA
16.	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car     Fireman's Grounding Switch     Lift Signage  Standby power supply	NA NA NA NA	NA NA NA NA NA NA	NA NA NA NA NA
16.	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car     Fireman's Grounding Switch     Lift Signage  Standby power supply Refuge Area	NA NA NA NA NA NA	NA NA NA NA NA	NA NA NA NA
16.	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car     Fireman's Grounding Switch     Lift Signage  Standby power supply Refuge Area     Total area	NA NA NA NA NA NA	NA NA NA NA NA NA NA	NA NA NA NA NA NA NA
16.	Overhead Tank capacity     Exit Signage     Provision of Lifts     Pressurization of Lift Shaft     Pressurization of lift lobby     Communication in lift Car     Fireman's Grounding Switch     Lift Signage  Standby power supply Refuge Area	NA NA NA NA NA NA NA	NA NA NA NA NA NA	NA NA NA NA NA

Fire control room  Detector system	NA	NA	NA
panel	NA	NA	NA
Flow Switch Panel	NA	NA	NA
> PA System Panel	NA	NA	NA
<ul><li>Battery backup</li><li>Building Floor Pla</li></ul>	NA ns	NA	NA
Special Fire Protection Systems for Protection of	NA	NA	NA

Against shortcoming issued vide letter no. F6/DFS/MS/2024/WZ/05 dated 04/01/2024, School management has given an affidavit that school falls under non confirming area, so map was not approved from MCD. Hence, shortcoming assumed rectified/Justified.

Fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view of substantial compliance of the minimum standards of fire prevention and fire safety requirements as per D.O.E. Cr. No. 3298-3398 dated 01.03.2011, grant of Fire safety Certificate is recommended under rule 35 of the Delhi Fire service Rules 2010 under the DFS Act 2007.

Accordingly DFA is prepared for approval & signature please.

p cro (yh)

Aman Kumar Lathar ADO (JWP)

Diretor /M/2/10/2019

Sie,
F. J. Letter is put-up for your signature pl.

1117 to W

18/08/24

Dieeth