

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/BNQT/2024/SZ/ 39 Dated: 30./08/2024

FIRE SAFETY CERTIFICATE

Certified that the Banquet Hall in the Name & Style of M/s JPS Catering Pvt. Ltd. located at Ground Floor only, B-10, DDA Community Centre, Triveni Complex, Saikh Sarai, New Delhi-110016 comprised of Ground plus Three upper floors was issued fire safety certificate by this department vide letter no. F6/DFS/MS/BNQT/SZ/2021/274 dated 23/06/2021. The Banquet Hall was re-inspected by the officer concerned of this department on 22/08/2024 in the presence of Mr. Manoj Kumar (Manger) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Banquet Hall at Ground Floor only) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule, 38, of the Delhi Fire Service Rules, 2010.

Issued on 30 /08 /2024 at New Delhi by

Copy to: -

1. The Joint Commissioner of Police, Lic/Branch, 1st floor PS Defence Colony, New Delhi 110049 (Ref. MHA Portal ID 2024073011837 dated 30/07/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first available 2010. The form Service Rules schedule of Delhi Fire www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



		me & Address of the Building	ON REPORT	eina Dut Ital at I	2 10 DDA		
77.6		A.F. TAN	M/s JPS Catering Pvt. Ltd at B-10, DDA Community Centre, Triveni Complex, Saikh Sarai				
2	Ту	pe of Occupancy	New Delhi-110016.				
3		The state of the s	Assembly 'Group-D' (Banquet Hall)				
HI		ilding comprised of	Ground Plus Three Upper Floors, Banquet hall is at Ground Floor.				
4		pe of Case	Renewal	and the state of the	dall		
5	De	tails of Previous NOC	0.1				
6		e Safety Directives Letter No	F6/DFS/MS/BNQT/SZ/2021/274 dated 23/06/2021				
7	Da	te of Inspection	Nil well belong any J. Fernon B.				
8		The second secon	22/08/2024				
550		me of the Inspecting Officers	DO (South) & ADO (BCP)				
9	fro	me & Designation of Officers m the building side	Mr. Manoj Kumar (Manger)				
10	Ye	ar of construction	2013				
1145	A	plicant letter No.	MHA Portal ID 2024073011837 dated 30/07/2024				
. No.	-	inimum standards on Fire Prevention	Old NOC	and the second s	Remarks		
. 110.		d Fire Safety U/R 33	requirements	Provided at Site	MR/NMR		
1 200		cess to Building.	KIND DOWNERS	A CO. No. of State and Associated in			
A ZHY		Road width	06 mtr	09 m	MR		
		Gate width	Required	3 mtr	MR		
		Width of internal road	NA	N/A	N/A		
2	Number, width, type & arrangement of exits						
1/51	a.	Number of Staircase	.g/cm	व पासा १० वर्षे असल्ला			
- 42	-	Upper floors	N/A	N/A	N/A		
-0.4	1	Basement floor	-NA-	N/A	N/A		
-A1	b.	Width of Staircase	12.0	Land Street	N/A		
1747		Upper floors	-NA-	N/A N/A	N/A		
		Basement floor	-NA-	Same and N/A lanete	14/11		
	c.		-NA-	N/A	N/A		
		Fire check door Pressurization	-NA-	N/A	N/A		
	d.	No. of continuous staircase to terrace	-NA-	N/A	N/A		
	e.	The state of the s	N/A	Auto N/A	N/A		
80	f.	the DX	2 mtr	Provided total 05 no of exits having width of 2.5 m, 1.37 m, 1.37 m, 0.88 & 0.88 mtr	MR		
3	C	mpartmentation.	and Fighting.	te nation sharings for t	arps 3		
7. 4 7.1		Fire check door.	-NA-	N/A	N/A		
- 16.7		Sealing of electrical shafts.	-NA-	N/A	N/A		
		Fire rating of shaft door.	-NA-	N/A	N/A		
		Water curtain	-NA-	N/A	N/A		
(4)		Fire dampers.	-NA-	N/A	N/A		
4	Sn	noke Management system.		o grang-	EMEN 7		
		Basement	30 a/c per hour	Provided	MR		
	8	Upper floors	-NA-	N/A	N/A		
5	Fi	re Extinguishers.) Jieus	the strategisters salt	D)		
		Total numbers	Padel	06 No's	MR		
3		• Types	ABC / CO2	ABC & Co2	MR		
		ISI Marking	ISI marked	Provided	MR		
6	Fir	st Aid Hose Reels.	D	0031 5 111			
		Total numbers on each floor.	Required 01 Nos	02 Nos Provided	MR		
. 1	1	Length of hose-reel hose.	30m	Provided	MR		
7	À.	Nozzle Diameter tomatic fire detection & alarming system.	5mm	Provided	MR		
	^						
	3.	 Type of detectors 	-NA-	-NA-	-NA-		

W/27

	Location of Main Panel			Tel Hell
780	Location of Repeater Panel	-NA-	-NA-	-NA-
Table 1	Alternate source of power	-NA-	-NA-	-NA-
	Hoofer's location	-NA-	-NA-	-NA-
	resolut s location	-NA-	-NA-	-NA-
8	MOEFA	Required	Provided) m
9	Public Address System			MR
10	Automatic Sprinkler System	Required	Provided	MR
			All an ingelling	
-	 Basement / Lower ground floor Upper floors 	Required	Provided	MR
		-NA-	-NA-	-NA-
11	Sprinkler above false ceiling Internal Hydrants.	-NA-	-NA-	-NA-
	A STATE OF THE STA	Else II	RCDs many best as for	
-	 Size of Riser/Down-comer 	-NA-	-NA-	NA
	 Number of Hydrant per floor 	-NA-	-NA-	-NA-
70.0	Hose box.	-NA-	-NA-	-NA-
12	Yard Hydrants.	waterway w	-IVA-	-NA-
77.77	Total number of hydrants.	-NA-	02.11	14
700	Hose box.		02 Nos provided	MR
13	Pumping arrangements.	-NA-	Provided	MR
A	Ground Level		(figure page) - a	
	***	re to memorary	to A and office asom	
	 Discharge of main pump. Head of main pump. 	-NA-	-NA-	-NA-
-	Number of main pumps.	-NA-	-NA-	-NA-
- 53	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
.4.3	Standby Pump head.	-NA-	-NA-	-NA-
- 21	 Auto Starting / Manual Stopping. Pump House Access 	-NA-	-NA-	-NA-
7.7	- milp House Access	-NA-	-NA-	-NA-
	Terrace Level	Company of Sec.	The Lager	-NA-
40	Discharge of pump.	450 LPM	900 & 180 LPM	MR
71	Head of pump.	40 mtr	46 m	
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for Fire Fighting.		And the decident	MR
- 1	 Underground tank capacity. 	-NA-	NA	
- 1	Draw-off connection.	-NA-	-NA-	-NA-
- 1-1	Fire Service Inlet.	-NA-	-NA-	-NA-
10.0	Access to tank.	-NA-	-NA-	-NA-
5	Overhead tank capacity. Exit Signage.	5,000 Ltrs	10,000 Ltrs	MR
	187 S	Required	Provided	MR
.0	Provision of Lifts.		Carrier	
	 Pressurization of lift shaft. 	-NA-	-NA-	1
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
11.6	 Communication in lift car. 	-NA-	-NA-	-NA-
- 21	 Fireman's switch. 	-NA-	-NA-	-NA-
	 Lift signage. 	-NA-	-NA-	-NA-
17	Standby Power Supply		TO THE STREET	-NA-
8	Refuge Area	Required	Provided (DG Set)	MR
	Total area	-NA-		



	Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	Detector System Panel.	-NA-	-NA-	-NA-
	Flow Switch Panel.	-NA-	-NA-	-NA-
	PA system Panel.	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building floor plan	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any:	-NA-	-NA-	-NA-

Note: - The Banquet hall as mentioned in the sanctioned building plan of DDA is show Lower Ground floor but tin fact the banquet hall is on ground floor from the rear side of the building. Hence the location of the banquet hall was considered as on ground floor and the same was approved & communicated vide letter of even no 1304 dated 18/06/2015. (Place at C/34) The Banquet is located at ground floor, whereas in earlier FSC dated 23/06/2021 it was mentioned at Lower Ground floor, which is a typographical mistake. Now the composition of the building is Ground floor and 03 upper floors.

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 69 dated 20/05/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/BNQT/SZ/2021/274 dated 23/06/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

nul

Name: Sh. Manoj Kumar Sharma

Design: DØ (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ)

Direct

11

30/2/24 0 blocages