

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2024/SZ/ 597

Dated: 30/09/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Training of Junior Youth Building A Block, LOTUS TEMPLE, (Bahai House of Worship Lotus Temple) New Delhi comprised of Lower Ground Floor & Upper Ground floors owner/occupied by M/s National Spiritual Assembly of the bahais of India at Kalkaji was issued FSC by this department vide letter no. F6/DFS/MS/2021/SZ/285 dated 28/06/2021. The premises was re-inspected by the officer concerned of this department on 21.09.2024 in the presence of Mr. Jayprakash Ambrale (Mantainace) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group "Assembly building with effect from  $\frac{30}{09}$  / 2024 for a period of three years in accordance with rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010.

Issued on  $\frac{90}{2024}$  at New Delhi by

(ATUL GARG)

HI FIRE SERVICE

Copy to: -

1. The Executive Engineer (Bldg) MCD, Central Zone Jal Vihar Lajpat Nagar, New

2. LOTUS TEMPLE, A Block, Training of Junior Youth Building (Bahai House of Worship Lotus Temple) New Delhi

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior 0)



	INSPECTIO	ON REPORT	According for detects		
1	Name & Address of the Building	LOTUS TEMPLE, A Block, For Training of Junior Youth Building For In Bahai House of Worship Lotus Temple New Delhi Assembly building			
2	Type of Occupancy				
3	Building Comprised of	Lower Ground Floor & Upper Ground Floor			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/2021/SZ/285 dated 28/06/2021			
6	Fire Safety Directives Letter No		016/68 dated 01.04.2016		
7	Date of Inspection	21/09/2024			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Jayprakash Ambrale (Mantainace)			
10	Year of construction	2016	4-19-17-18-18-18-18-18-18-18-18-18-18-18-18-18-		
11	Applicant letter No.	Outdoor diary no 6500 dated 13/09/2024			
. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	BBL / NBC requirements	Provided at Site	Remarks MR/NMF	
1	Access to Building.		Stockly Hard C	.53	
	Road width	Required	25 mtr = -	MR	
	Gate width	Required	6 mtr	MR	
	Width of internal road	Required	Pumpirth 6 mtriquius	MR	
	Number, width, type & arrangement of exits.	•	ers I banand .		
2		grand mar	ar (Junith Bryce of o		
		02 Nos	03 Nos	MR	
		-NALINING D	-NA-	-NA-	
7		5.097	graph reduced.		
	b) Width of Staircase		0.1 50	MR	
	> Upper floors	2 mtruglue	2 x 2 mtr & 1.50 mtr	LESSACT DE SEV	
	➤ Basement floor	-NA-	-NA-	-NA-	
	c) Protection of exits	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
	c) Protection of exits  > Fire check door	Required	Provided	MR	
		-NA-	-NA-	-NA-	
11/1	> Pressurization		2 Nos	MR	
	d) No. of continuous staircase to terrace	-NA-	-NA-	-NA-	
15/	e) Width of corridor	1.50 mtr	1.50 mtr each	MR	
A.V.	f) Door size (Exits in hall)	1.50 mu	7 Albi 1.50 inti cacii		
3	Compartmentation.	Required	Provided	MR	
30.	Fire check door.	-NA-10 MIL	I toming a -NA-	-NA-	
162	Sealing of electrical shafts.	-NA-	TIG-WAIL-NA-	-NA-	
3	Fire rating of shaft door.	-NA- <sup>20 (4)</sup>	-NA-	-NA-	
V	Water curtain	-NA-	-NA-	-NA-	
. 10	• Fire dampers.	Tuescale.	The beater 0		
4.	Control of the Contro	-NA-	-NA-	-NA-	
	Basement	12 ACPH	Natural ventilation	MR	
100	Upper floors	12819 1111 1	Chest Polenia	1 1 1 1	
5		Required	12 Nos	MR	
	Total numbers	ISI marked	Co2, ABC & DCP	MR	
100	• 1 ypes		Provided	MR	
	ISI Marking	ISI marked	nuent 10 mass	1	
1	6. First Aid Hose Reels.	20.37	Provided	MR	
1166	Total numbers on each floor.	02 Nos	Provided	MR	
	Length of hose-reel hose.	30m		MR	
1	Nozzle Diameter	5mm	Provided	MIK	

7 1	Automatic fire detection & alarming system.	PERSON	-NA-	-NA
7 A	Type of detectors	-NA-	-NA-	-NA
	Location of Main Panel	-NA-	-NA-	-NA
	Location of Iviain Later     Change Panel	-NA-		-NA
1-	Location of Repeater Panel	-NA-		-NA
1.1	Alternate source of power	-NA-		MF
The state of	Hooter's location	Required		-NA
	MOEFA	-NA-	-NA-	-
9.	Public Address System	14 7112	193 (189) (	-NA
10.	Automatic Sprinkler System	-NA-	1.6	-NA
	Basement	-NA-	The second secon	-NA
	Upper floors.	-NA-	-NA-	-11/2
(500)1	Sprinkler above false ceiling	-11/2		MR
11.	Internal Hydrants.	100	Provided	The Special Contracts
11.	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	02 Nos		MR
, Jil	9076 71520000 PULL	02 Nos		I
21.6				-NA
12.	Yard Hydrants.	-NA-	The second secon	-NA-
	Total number of hydrants.	-NA-	-NA-	1,42.2
	Hose box.	Lacette	emin in MaxW *	
13.	Pumping arrangements.	United the	Nambers of Research	S
13.	- Ground Level	-NA-	-NA-	-NA-
	Discharge of main pump.	-NA-	-NA-	-NA-
	Lead of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	> Tockey Pump output.	-NA-	-NA-	-NA-
	To alcore Dump head.	-NA-	-NA-	-NA-
6	Standby Pump output.	-NA-	-NA-	-NA-
	a II Dumn nead	-NA-	-NA- 0 1-	-NA-
do l	Auto Starting/Manual Stopping.	-NA-	-NA-	-IVA-
	> Pump house access.	-1112	0.00	MR
	Torrace Level	900 LPM	Provided	
No.	Discharge of pump.	40 m	Provided	MR
	> Head of pump.		Provided	MR
	Desiror SUPPLY	Required		MR
	> Auto starting of pullip.	Required	Total of the same of	
	targe for fire fighting.	7.1	-NA-	-NA-
14.	Captive water storage for fire fighting.  Underground tank capacity.	-NA-	-NA-	-NA-
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection.</li> </ul>	-NA-	-NA-	-NA-
	> Draw-on connection > Fire Service Inlet.	-NA-	-NANANANANANANANA-	-NA-
	> Access to tank.	-NA-		MR
	Overhead tank capacity.	15,000 Ltrs Required		MR
		Kequireu		
15.	Exit Signage		-NA-	-NA-
16.	Provision of Lifts.	-NA-		-NA-
10.		-NA-	Discovery (I to the second of	-NA-
	otion of lift lood.	-NA-		-NA-
37	Communication in int car.	-NA-	CHICAGO TO CONTRACT OF THE PROPERTY OF THE PRO	-NA-
M.	Fireman's switch.	-NA-		MR
N	Lift signage.	Required	Provided (DG Set)	IVAL
	Standby Power Supply	model in	added the set of	-NA-
17.	Refuge Area	-NA-	-AM- le Diame	
18.	Total area			

B



Location	-NA-	-NA-	-NA-
Fire Control Room.			
Detector system panel.	-NA-	-NA-	-NA-
Flow switch panel.	-NA-	-NA-	-NA-
PA system panel.	-NA-	-NA-	-NA-
Battery backup.	-NA-	-NA-	-NA-
Building floor plan.	-NA-	-NA-	-NA-
O. Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 527 dated 12/09/2024. Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2021/SZ/285 dated 28/06/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ) approved, F-1. Vetter i pulle your synature of 1/2/9/14