GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI

No. F6/DFS/MS/GH/NDZ/2024/390

FIRE SAFETY CERTIFICATE

Certified that the M/s Al-Tauheed Guest House located at 3371-72-73 & 3374, Netaji Subhash Marg, Darya Ganj, Delhi- 06, comprised of Ground + 04 upper floors: Ground floor - (other's property), 1st floor - (reception + 03 guest rooms), 2nd floor - (03 guest rooms), 3rd floor -(03 guest rooms) & 4th floor- (not in use), total 09 guest rooms upto 3rd floor was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2020/116 dated 01.04.2020. The building /premises was re-inspected by the officer concerned from this department on 25.09.2024 in presence of Mr. Dilip Kumar (Manager) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 25.09.2024 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of class "Residential" (Sub Division-A-1), (1st floor - (03 guest rooms), 2nd floor - (03 guest rooms) & 3rd floor - (03 guest rooms) for total 09 guest rooms upto 3rd floor only, with effect from ...03]10 | 2024... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 03/10/2024 at New Delhi by

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2024090713904 dated 12.09.2024.
- 3. The Licensee, M/s Al-Tauheed Guest House at 3371-72-73 & 3374, Netaji Subhash Marg, Darya Ganj, Delhi- 06.

Conditions for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of above 3rd floor not allowed as per clause 7.31 in UBBL-2016.

-N/20-

		INSPECTI	ON REPORT				
1.	Naı	me and address of the building:	M/s Al –Tauheed Guest House situated at 3371-72-73 & 3374, Netaji Subhash				
			Marg, Daryaganj	Delhi-06.			
2.	Tvi	oe of occupancy with details of	Residential Group	A-1			
	floo		(Ground + 04 upp	(Ground + 04 upper floors)			
- 1			Ground floor-(other's property)				
- 1			1st floor-(reception	$_1 + 03$ guest roc	ms)		
			2 nd floor- (03guest rooms),				
			3 rd floor- (03 guest rooms) 4 th floor- (not in use as per affidavit dated				
			4th floor- (not in us	e as per affidav	it dated		
			25.09.2024) RENEWAL (old case) F6/DFS/MS/GH/NDZ/2020/116 dated				
3.	Tw	pe of case:					
4.	Det	tails of previous FSC:	F6/DFS/MS/GH/N	DZ/2020/110 C	lated		
4.	Det	talls of previous 2500	01.04.2020				
-	E:-	e safety directives no.:	NA				
5.	Pir	te of inspection:	25.09.2024	25.09.2024			
6.	Da	me of the inspecting officer:	Sumit Kumar, AD) (SPM)			
	Na	me and designation of the officer					
8.	Na	m the building side:	Mr. Dilip Kumar (Manager)			
	iro	ar of construction:	1983 Online application ID No. 2024090713904				
9.	Ye	ference letter no.:					
10	Ke	ierence letter no	dated 12.09.2024		Remark		
	_	and of Fire	Requirements	Provide at	Kemair		
S,No	M	inimum standard of Fire evention and Fire Safety U/R 33	(Existing Fire &	site	MR/N		
	Pr	evention and Fire Salety	Safety Measures)	(PSS)	MR		
]	IVALC		
	-	cess to Building		70	NA		
1	+	Road width	NA	30 m	NA		
	A	Gate width	NA	NA			
	В		NA	NA	NA		
	C	Width of internal roads	ant of Frits				
2	Nu	mber, Width, Type & Arrangem	ent of Exits				
	A	No. Of Staircase:		01 No	MR		
	-	a) Upper Floor	01 No	NA	NA		
		b) Basements	NA	INA	10.2		
	<u>_</u>	Width of the Staircase:					
	В	Width of the Standard	and the second s		\ \m		
		a) Upper floors	80 cms.	90 cms.	MR		
			NA	NA	NA		
			1-3-3				
	C	Protection of Exits	NA	NA	NA		
		a) Fire Check Door		NA	NA		
		b) Pressurization	NA	IVA			
			01 No	01 No	MR		
	D	No. Of continuous staircase to	011.0				
		terrace:		NIA	NA		
-	F	Width of the corridor	NA	NA	INZ		
	•			1.0	MR		
	Е	Door size	1.0 mtr.	1.0 mtr	MIK		
-	34.1	mpartmentation:			1557		
3	-	Fire Check doors	NA	NA	NA		
	Α	Sealing of Electrical	NA	NA	NA		
	р	Shafts					
	В		NA	NA	NA		
		Fire rating of shaft	318.752.57v.				
	C	Doors	NA	NA	NA		
	D	Water curtain	NA NA	NA	NA		
		Fire dampers	INA				
-	0	acks management Sections					
4		Names floors	12 ACPH	Natural	MR		
	A	Upper floors Basements	NA NA	NA	NA		
	В		INA	144	IM		
5	Fir	e extinguishers					
		Total numbers	00 00	08 00	MD		

		Hose reel	المساول والمراج	Tat	TNA
-	irst Aid	Hose reel Total no. at each floor	NA	01 no.	NA
A		Length of Hose Reel	NA	30 m	NA
B		1 1'atam	NA	05 mm	NA
C		Fire Detection and Alarm System	(ADAS)		and the second second
_	utomatic	Type of Detectors (CO type)	Required	Provided	MR
A		Location of main Panel	Required	Provided at	MR
В		Location of manife and	·	reception	
_		diam of Paneater Panel	NA	NA	NA
Ç		Location of Repeater Panel	Required	Provided	MR
D	The second secon	Alternate power Source	Required	Provided	MR
E		Hooter's location	NA	NA	NA
M	IOEFA		NA	NA	NA
P	ublic Ac	ddress System	1471		
A	utomati	c Sprinkler System	NA	NA	NA
A		Basement	NA	NA	NA
В	3	Upper Floor		NA	NA
C	2	Sprinklers above false ceiling	NA	14/1	1
I	nternal l	Hydrants	N/A	NA	NA
P		Size of the riser/down comer	NA	NAME OF TAXABLE PARTY OF TAXABLE PARTY.	NA
E		No. Of hydrants per floor	NA	NA	NA
	2	Hose box	NA	NA	14/4
	Yard Hy	drants		1314	NA
_	A	Total no. of hydrants	NA	NA	NA NA
	В	Hose box	NA	NA	IAM
and the same of	Water and the same of the same of	arrangements			
_	A	Ground Level		1	BIA
		a) Discharge of main pump	NA	NA	NA
		b) Head of main pump	NA	NA	NA
		c) Number of main pump	NA	NA	NA
		d) Discharge of jockey pump	NA	NA	NA
		S, Distinge of , 1			274
-		e) Head of jockey pump	NA	NA	NA
		f) Discharge of Standby pump	NA	NA	NA
	360	g) Head of Standby pump	NA	NA	NA
		h) Auto starting/ manual stopping	NA	NA	NA
7	В	Terrace Level	-		
			NA NA	225 LPM	NA
		a) Discharge of terrace pump	A STATE OF THE STA	40 m	NA
		b) Head of terrace pump	NA	Provided	NA
v		c) Alternate power supply	NA	Provided	NA
14	Conti	d) Auto starting of pump	NA	Flovided	1
	A	e Water Storage for Fire Fighting		NA	NA
	B	Underground tank capacity	NA	NA NA	NA
	C	Draw off connection	NA	NA NA	NA
	E	Fire Service Inlet	NA	Provided	NA
	D	Access to tank	NA	4,000 ltrs.	NA
15		Overhead tank capacity	NA	Provided	MR
10	Exit Signage Provision of lift		Required	Frovided	1 21.00
	Α	Pressurization of lift shaft		NA	NA
	В	Pressurization of lift shaft	NA	NA NA	NA
	C	Pressurization of lift lobby Communication in lift car	NA	NA NA	NA
	D	I i chiali Switch	NA	NA NA	NA
-	E	Lift signes	NA	NA NA	NA
1	7 Stand	dby Power Supply	NA .	Provided	MI
		TP.	Required	Flovided	178.8

18	Refuge Area				
	Α	location	INIA	155	
	В	Total area	NA NA	NA	NA NA
19					
	Α	Fire Detection System panel	NA	NA	NA
	В	Flow switch panel	NA	NA NA	NA NA
	C	P A system panel	NA	NA NA	NA NA
	D	Battery backup	NA	NA	NA
	E	Building floor plan	NA	NA	NA
20	Special Fire Protection for special risk if any				NA

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2023/612 dated 19.12.2023 has been rectified.

The owner has submitted an affidavit on 25.09.2024 stating not to use any floor above third

floor for any purpose.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2020/116 dated 01.04.2020 is recommended to be renewed upto 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting Officer Sumit Kumar Name

1

ADO (SPM) Designation

DO (CD)

F.T. letter /s por up for Signature, Please.

Director (D)