Dated: 25./.10./2024

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2024 437

FIRE SAFETY CERTIFICATE

Certified that the Hotel Sehej Continental Guest House located at 53/1, D.B.G. Road, Karol Bagh, New Delhi in a building comprised of Basement + Ground + 03 Upper floor, Bank at (basement & ground floor (some portion), Ground floor (hotel reception), 1st floor to 3rd floor (06 guest rooms & 01 small store at each floor), total 18 guest rooms up to third floor only. The FSC was earlier granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/475 dated 22/10/2021 for the guest house only for total 18 guest room. Now, the premise was re-inspected by the officer concerned of this department on 16/10/24 in the presence of Mr. Durgesh and found that the said guest house premises has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception), 1st floor to 3rd floor (06 guest rooms) total - 18 guest rooms up to third floor only, and valid up to the period of three year from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued .25/10/2024at New Delhi by.

Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy in the building as detailed above and deviation if any .
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No 2024092914995 dated 29.09.24.
- 3. The Manager, Hotel Sehej Continental Guest House at 53/1, D.B.G. Road, Karol Bagh, New Delhi. Conditions for the validity of Fire Safety Certificate
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for guest house from ground to third floor only.
 - 2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned. Basement shall be used in conformity of BBL concerned.
 - 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
 - 7. The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
 - 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
 - 9. Any flammable material for interior decoration is prohibited.

H/24 <u>INSPECTION REPORT</u>

1. Name & address of the building

Hotel Sehej Continental located at 53/1, D.B.G.

Road, Karol Bagh, New Delhi.

B + Gr. + 03 Upper floors (total 18 Guest rooms) Bank at basement & some portion of ground floor and rest

portion of building for guest house 2. Type of occupancy

Residential- GH, Ground-reception, First to third floor

(06 room at each floor), total -18 guest room

3. Type of case:-Renewal 4. Details of previous FSC:-

No. F6/DFS/MS/GH/NDZ/2021/475 dated

22/10/2021.

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

N/A 16/10/24

Sh. Ravinder Singh(ADO/CC)

Mr. Durgesh Before 2010

online ID No.2024092914995 dated 29.09.24

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	Accessible	12 mtr. /	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases					
	1. Upper floors	01 No.	01 No.	MR		
	2. Basements	01 No.	01 No.	MR		
	B. Width of staircase	- V		1		
	1. Upper floors	1.25 mtr.	1.5 Mtr.	MR		
	2. Basements	1.25 mtr.	1.25 Mtr.	MR		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	01	01	MR		
	E. Width of corridor	1 mtr.	1.60 mtr.	MR		
	F. Door size	01 mtr.	80cms x2.44 mtr.	MR (Old Bldg.)		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
	Smoke Management System					
100	1) Basements	N/A	N/A	N/A		
	2) Upper floors	12 ACPH	Natural/exhaust fan	MR		
	Fire Extinguishers					
	1) Total numbers	10 nos.	10 nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		

		7		100	
6.	First-Aid Hose Reel	Lause	01 No.	MR	
	1) Total number of eachfloor	01 No.	30 mtr.	MR	
	2) Length of hose reel hose	30 mtr.	05 mm	MR	
	3) Nozzle diameter	05 mm		1171	
7.	Automatic Fire Detection &	Alarming Syst	Provided	MR	
	1) Type of detectors Co Type	Required	Provided	MR	
	2) Location of main panel	Ground floor	N/A	N/A	
	3) Location of repeater panel	N/A	Provided	MR	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	Each floor		MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	TAIK	
10.	Automatic Sprinkler System	NUA	N/A		
	1) Basement (less than 200 SQM)	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	11/2	
	ceiling				
11.	Internal Hydrants	21/4	N/A	N/A	
	1) Size of riser/down-comer	N/A	N/A N/A	N/A	
	2) Number of hydrants per	N/A	N/A	1	
	floor	NI/A	N/A	N/A	
10	3) Hose box	N/A	IVA	AVAL	
12.	Yard Hydrants 1) Total number of hydrants N/A		N/A	N/A	
	1) Total number of hydrants	N/A	N/A	N/A	
12	2) Hose box	INA	IVA	1	
13.	Pumping Arrangement 1) Ground level	N/A	N/A	N/A	
	The State of the S	N/A N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	17''	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A	N/A	N/A	
	stopping				
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 LPM	MR	
	b) Head of pump	40 mtr.	40 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	Under ground tank	N/A	N/A	N/A	
	capacity	STORE SA	2000 M	and the second	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank	5,000 ltr.	5,000 ltr.	MR	
15.	Capacity Frit Signage	-			
16.	Exit Signage.	Required	Provided	MR	
	Provision of Lifts.	1			
			7.0		
	a) Pressurization of lift	N/A	N/A		

P	١	26

	 b) Pressurization of lift lobby 	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
17.		Required	Provided	MR
18.	Stand by Power Supply	Required	Provided	MR
10.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	 a) Detector system panel 	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	111177 1716	
	d) Battery backup	N/A	N/A N/A	N/A N/A
	e) Building floor plan	N/A	N/A	N/A
0.	Special Fire Protection System for Protection of special Risk, if any:			NA NA

The fire protection systems provided in the guest house premises were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2021/475 dated 22/10/2021, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is prepared and put up for kind perusal/approval please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

1) / (a) 21/x/24

Diceo(2003)

XIV 9 24

23/10/18

Inectar # 10

Aroppoored per pourup forcew permalang

Sopostyn Place

Dreelor Holy me

Vylordel 2011/24 अंग्रिक