





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 393

Dated: 05/12/2024

FIRE SAFETY CERTIFICATE

Certified that M/s Imperfecto (A unit of Bel Cibo Hospitality Pvt. Ltd) located at Asset No. 5A, Ground Floor, Pride Paza Hotel, Aerocity, New Delhi-110037, comprised of 3 Tier Basement, Ground Floor, Service Floor + 7 Floors has already been issued FSC vide letter No. 28 dated 06/12/2023 and the restaurant running at ground floor was issued Fire Safety Certificate vide letter No. F6/DFS/MS/SZ/2021/EH/377 dated 23/12/2021. The premise was re-inspected by the officer concerned of this department on 26/11/2024 in the presence of Sh. Naresh Madan (Director) and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said premises is fit for occupancy class "Assembly Group D" (Restaurant) with effect from 05/12/2024 for a period upto 31/03/2027 in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

DIRECTOR F. No. 0111-23414000

Copy to: -

- The Joint Commissioner of Police, Licensing Unit, First Floor, Police Station Defence Colony, New Delhi-110037 (w.r.t. online ID No. 2024111917002 dated 20/11/2024)
- Authorized Signatory M/s Imperfecto (A unit of Bel Cibo Hospitality Pvt. Ltd) located at Asset No. 5A, Ground Floor in Pride Paza Hotel, Aerocity, New Delhi-110037

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

1	INSPECT	ON REPORT	Glait of Bel Cibo	Hospitality		
,	Name & Address of the Building	M/s Imperfecto (Unit of Bel Cibo Hospitality Pvt. Ltd), Asset-5A, Ground Floor, Pride Paza				
		Pvt. Ltd), Asset-5A, Ground 10037				
2	Type of Occupancy					
3		- Cround floor, Scivico inco-				
3	Building Comprised of	+ 7 Floors but Restt. is at ground floor on				
4	Type of Case					
- 5	Details of Previous NOC	ECIDECIMACIST	Z/2021/EH/377 Dt. 2	3/12/2021		
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2010/3290 Dt. 01/12/2010 (Bldg				
7	Date of Inspection	26/11/2024				
8	Name of the Inspecting Officers	ADO (SJ)				
9	Name & Designation of Officers	Sh. Naresh Madan (Director)				
,	from the building side					
10	Year of construction	2014		2004		
11	Applicant letter No. / Online MHA	ID No. 2024111917002 dated 20/11/2024				
S.	Minimum standards on Fire	Old FSC	Provided at Site	Remarks		
No.		Requirement	100 Di	MR/NMI		
1	Access to Building	F6/DFS/MS/GH	I/2023/SZ/HTL/28 Dt.	06/12/2023		
	Road width	Restt. within	As above	MR		
	Gate width	Pride Plaza	As above	NA		
	Width of internal road	Hotel	As above	NA		
2	Number, width, type & arrangeme	nt of exits.				
2	a) Number of Staircase	Provided an	d Managed by Hotel Mgmt.			
	> Upper floors.	N/A	As above	N/A		
	Basement floor.	N/A	As above	N/A		
	A CHANGE CO.		d Managed by Hotel Mgmt.			
	b) Width of Staircase	N/A	As above	N/A		
	> Upper floors	N/A N/A	As above	N/A		
	> Basement floor		A MIND OF CALL SALVED	2 W352		
	c) Protection of exits		nd Managed by Hotel Mgmt.			
	> Fire check door	N/A	As above	N/A		
	> Pressurization	N/A	As above	N/A		
	d) No. of continuous staircase to terrace	N/A	As above	N/A		
	e) Width of corridor	N/A	As above	N/A		
	f) Door size	02 Exits		per Gazette		
_	105003-550/048-551 105	Provided an	d Managed by Hote	n Dt. 24,02,2021 Momt		
3	Compartmentation.	N/A	As above	N/A		
	Fire check door. See line of electrical chaffs.	N/A	As above	N/A		
	Sealing of electrical shafts. Figure 1 and	N/A	As above	N/A		
	Fire rating of shaft door. Weter curtain.	N/A	As above	N/A		
	Water curtain Fire democra	N/A	As above	N/A		
	Fire dampers. Smoke Management System.	1,000,000,000	d Managed by Hote			
1.	District of the product of the second of the	N/A	As above	N/A		
	Basement	12 ACPH	Exhaust fans	MR		
	• Upper floor	12 ACFI	L'Aliquet Idile	IVIIC		
	Fire Extinguishers.	Desidend	06 Nos	MR		
	Total numbers	Required	2015/15/15/15/15	J. CHARLEST		
	Types	ABC / CO ₂	ABC & CO ₂	MR		
	ISI Marking	Required	Provided	MR		
	First Aid Hose Reels.	Provided and Managed by Hotel Mgmt.				
	Total numbers on each floor.	01 (Near Restt.)	As above	MR		
		30m	As above	MR		
	 Length of hose-reel hose. 		As above			
- 1	 Nozzle Diameter 	5mm	As above	MR		



-	Automatic fire detection & alarming	system. (Provide	d and Managed by He	otel Mgmt
7	Automatic tire detection & alarming	N/A	As above	N/A
	Type of detectors	N/A	As above	N/A
	Location of Main Panel	N/A	As above	N/A
	 Location of Repeater Panel 	N/A	As above	N/A
	 Alternate source of power 	N/A	As above	N/A
	 Hooter's location 	ACOMOR Sty.	Provided	MR
8	MOEFA	Required N/A	As above	N/A
9	Public Address System	N/A	d Managed by Hote	Mgmt.
10	Automatic Sprinkler System		As above	N/A
	Basement	N/A	As above	N/A
	Upper floors.	N/A	As above	N/A
	Sprinkler above false ceiling	N/A		
11	Internal Hydrants.		Managed by Hotel	N/A
**	Size of Riser/Down-comer	N/A	As above	N/A
	Number of Hydrant per floor	N/A	As above	N/A
	Hose box.	N/A	As above	1,70000
12	Yard Hydrants.	Provided and	Managed by Hotel	Mgmt. N/A
12	Total number of hydrants.	N/A	As above	
	Hose box.	N/A	As above	N/A
12	Pumping arrangements.			N/
13	Ground Level		Managed by Hotel	N/A
	> Discharge of main pump.	N/A	2850 LPM x 2 88m	N/A
	➤ Head of main pump.	N/A	Two	N/A
	> Number of main pumps.	N/A N/A	180 LPM	N/A
	Jockey Pump output.Jockey Pump head.	N/A	88m	N/A
	> Standby Pump output.	N/A	2850 LPM	N/A
	> Standby Pump head.	N/A	88m	N/A
	Auto Starting/Manual Stopping.	N/A	Provided	N/A
	➤ Pump house access.	N/A	Provided	N/A
	Terrace Level		Managed by Hotel	MR MR
	Discharge of pump.	450 LPM	900 LPM Provided	MR
	➤ Head of pump.	40m	15.5.5	
	➤ Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14	Captive water storage for firefighting.		Managed by Hotel	
	Underground tank capacity.	N/A	1,50,000 Ltrs	N/A
	 Draw-off connection. Fire Service Inlet. 	N/A N/A	Provided Provided	N/A
	Access to tank.	N/A N/A	Provided	N/A
	Overhead tank capacity.	10,000 Ltrs	20,000 Ltrs	N/A MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		Managed by Hotel	Momt
	 Pressurization of lift shaft. 	N/A	As above	N/A
	 Pressurization of lift lobby. 	N/A	As above	N/A
	Communication in lift car.	N/A	As above	N/A
	Fireman's switch.	N/A	As above	
	Lift signage.	N/A		N/A
17	Standby Power Supply	25/4/19/03	As above	N/A
18	Refuge Area	Required	Provided	MR
	Total area	Provided and	Managed by Hote	l Mgmt.
- 1	Total alca	N/A	103 m ²	
	 Location 	N/A	105 111	N/A

De son

19	Fire Control Room.	Provided and Managed by Hotel Mgmt		
	Detector system panel.	N/A	As above	IN/A
		N/A	As above	N/A
	Tion switch panel.		As above	N/A
	PA system panel.	N/A	As above	N/A
	Battery backup.	N/A	As above	N/A
	Building floor plan.	N/A	5/6-25	N/A
20	Special Fire Protection System for the Protection of Special Risk, if any.	N/A	As above	14.

The fire protection systems provided in the premises were checked, tested at random and found functional at the of inspection. The main building i.e. M/s Pride Plaza Hotel, Asset No. 5A, Hospitality District, Aerocity, IGI Airport, New Delhi has already been issued FSC by this department vide letter No. F6/DFS/MS/GH/2023/SZ/HTL/28 Dated 06/12/2023.

In view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/SZ/2021/EH/377 Dated 23/12/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar

Designation: ADO (SJ)