

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 127

Dated: 04/03/2021

To,

The Principal,
S.D.M.C Pratibha Vidyalaya,
Hari Nagar, Ghanta Ghar, New Delhi-110064.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o
S.D.M.C Pratibha Vidyalaya, Hari Nagar, Ghanta Ghar, New Delhi-110064.

Sir,

This has reference to your letter no. Nil dated 08/02/2021 on the subject captioned above. In this connection, it is to inform you that the school was inspected by the officer concerned of this department on 19/02/2021 in the presence of Smt. Alka Sood (Teacher) to verify the compliance of shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/2020/SZ/444 dated 30/04/2020 and observed that shortcomings are still not rectified.

Yours faithfully

(Sunil Chawdhary)
Dy.Chief Fire Officer

Copy to:-

1. The Director of Education,
S.D.M.C Civic Centre, Minto Road,
New Delhi-110001.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ /444

Dated: 30/4/2020

To,

The Dy. Director of Education,
West Zone, SDMC, Education Department,
New Delhi

Sub: - Regarding issuance of Fire Safety Certificate in r/o S.D.M.C Pratibha Vidyalaya, Hari Nagar, Ghanta Ghar, New Delhi-110064.

Sir/Madam,

This has reference to your Letter No. Nil dated 20.07.2017 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 08.08.2017 to see the compliance of the requisite fire safety measures. Smt. Pushpa (Principal) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus two upper floors. The upper floors are served by three staircases having width 150 cms each. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. Fire extinguishers are not provided. Eleven fire extinguishers of ABC type/CO₂ type 2.5 Kg Capacity each are require to be provided.
2. First aid hose reel system is not provided.
3. Fire pumps having capacity 450 LPM is not provided.
4. Overhead Water storage tank of 10000 ltrs capacity is not provided.
5. Exit signs are not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. Director of Education,
S.D.M.C, Civic Centre, Minto Road,
New Delhi – 110001
(with a request to take further action as school does not have fire NOC)
2. The Principal,
S.D.M.C Pratibha Vidyalaya, Hari Nagar,
Ghanta Ghar, New Delhi-110064

Decem
22/4/2020