

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/School/2021/ 137

Dated: 12 /03/2021

To

The Vice Principal,
Baba Sahib Ambedkar Secondary School,
Rani Jhansi Road, Paharganj, New Delhi.

Sub: Regarding issuance of FSC in r/o Baba Sahib Ambedkar Secondary School at Rani Jhansi Road Paharganj , New Delhi

Sir,

This has reference to your letter No. BSA/SS/2021/1320 dated 09/02/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by officer concerned of this department on 02.03.2021 in the presence of Sh Rajbeer Singh Bhandari and the following shortcomings were observed.

1. First hose reel is not provided in the building
2. Terrace pump of 220 LPM capacity is not provided.
3. Fire water tank on terrace 2,500 liter capacity is not provided
4. Exit signages is not provided.
5. PA system is not provided.
6. Stand by power supply is not provided in the building.

In view of above shortcomings, fire safety certificate (FSC) cannot be issued at this stage.

Yours faithfully



(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

The Director (Education),
Govt. of NCT, Old Sectt.
Delhi - 54.

