GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

No. F6/DFS/MS/School/WZ/2021/148
To,

Dated: 18/93/2021

Yours faithfull

The Principal, N.D.M.C. School, G.P. Block, Pitampura, Delhi-110034,

Sub. :-Regarding issuance of Fire Safety Certificate in r/o North Delhi Municipal Corporation Pratibha Vidyalaya School, G.P. Block, Pitampura, Delhi-110034.

Sir,

Please refer to your letter no. Nil dated 11.02.2021 on the subject cited above. In this connection it is to inform you that the said school building have been inspected by the officer concerned of this department on 04.03.2021 in presence of Ms. Nirmala Yadav (In-charge) to check compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/School/2020/223 dated 13.04.2020

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above shortcomings, Fire safety Certificate cannot be grant at this stage. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action.

Copy to:-

1. The Director, (Education), SDMC, 23rd floor, Civic Centre, Minto Road, New Delhi.

0/17

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No-f6/Dfs/ms/school/2020/223

D9te-13/04/2020

To,

The Principal, Nigam Pratibha Vidyalaya, GP Block, Pitampura, Delhi – 110034.

Sub:- Regarding issuance of NOC from fire safety point of view in respect of Nigam Pratibha Vidyalaya located at New Block, GP Block, Pitampura Delhi – 110034.

Sir.

Please refer to your letter no. Nil dated 19/02/2020 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by officers concerned of this department on 17/03/2020 to see the functioning of fire safety equipments provided in the building.

The following shortcomings were observed:-

- 1. Two stairs of 1.5m clear width remotest to each other are not provided.
- 2. One Exits of 1.2 m clear width remotest to each other are not provided.
- 3. Two fire extinguishers of ABC type 5kg capacity at each floor are not provided.

 In view of the above FSC from fire safety point of view cannot be considered at this stage.

You are requested to comply the shortcomings under intimation with this department for further consideration in the matter.

Yours Falthfully

Director Delhi Fire Service

Copy to:-

1. The Principal, Nigam Pratibha Vidyalaya at GP Block, Pitampura, Delhi – 110034.

2. Directorate of Education Old Secretariat Delhi - 110054