

c-19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/2021/SZ/ 164

Dated: 26/03/2021

To,-

The Manager,
New sainik international School,
Plot no-14,15&28 to 37, Vikas Vihar,
Near Vikas Kunj, Vikash Nagar, New Delhi-110059.

Subject: Grant of Fire Safety Certificate in r/o New sainik international School plot no-14,15 & 28 To 37, Vikas Vihar, Near Vikas Kunj, Vikash Nagar, New Delhi-110059.

Sir,

Please refer to your letter no. Email Dated 22-02-2021 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 03/03/2021 to see the compliance of the shortcomings communicated vide this office letter no. F.6/DFS/MS/School/2019/SZ/6304 dated 22/10/2019 and found that the shortcomings are still not complied. You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,



(Sunil Chaudhary)
Dy. Chief Fire Officer,
Delhi Fire Service.

Copy to:- 1. The Joint Directorate of Education Old Secretariat Delhi - 110054

12/03/21
16/3

C/11

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ / 6304
To,

Dated: 22/10/19

The Principal,
New Sainik International School, Plot No. 14, 15 & 28 to 37,
Vikas Vihar, Near Vikas Kunj, Vikas Nagar, New Delhi-110059

Sub: - Regarding issuance of Fire Safety Certificate in r/o New Sainik International School, Plot No. 14, 15 & 28 to 37, Vikas Vihar, Near Vikas Kunj, Vikas Nagar, New Delhi-110059.
Sir,

This has reference to your Letter No. Nil dated 27.08.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 19.09.2019 to see the requisite fire safety measures. Smt. Shaifali (Incharge) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of basement, ground plus two upper floors & one room on terrace. The upper floors are served by two staircases having width 140 to 130 cms & 120 cms and the basement is served by single staircase having width 146 cms. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

1. The building is not approachable through 4.5 meter wide main gate.
 2. The upper floors are served by two staircases having width 140 to 130 cms & 120 cms and the basement is served by single staircase having width 146 cms against required two staircases having width 150 cms & 135 cms each from basement to terrace.
 3. Door width is 96 cms against required 120 cms.
 4. Fire check door is not provided in the basement.
 5. Hose reel system is provided in entire building except basement & is not functional.
 6. Fire pump having capacity 450 LPM (02 no.'s) Not provided.
 7. Overhead water storage tank of 15,000 ltrs capacity not provided.
 8. Exit signs are not provided.
- If student capacity is more than 45 in any class room then double door having width 120 cms is required.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054

(with a request to take further action as school does not have fire NOC)

ATUL GARG
16/10/19