

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE:
NEW DELHI – 110001

No.F6/DFS/MS/School/MN/2021 / 155

Dated: 26/03/2021

To

The Vice Principal,
SD Secondary school (GUJRAT)
Kirti Nagar, New Delhi -110015.

Sub:- Inspection report in r/o of SD Secondary School(GUJRAT) Located at Kirti Nagar New Delhi -110015.


Sir,

Please refer to your letter dated 14.01.2021 on the subject cited above. In this connection it is informed that the premise was inspected by the officer concerned of this department on 10.02.2021 in the presence of Sh. Rakesh Babu (Vice principal) to check the workability of existing Fire safety arrangements. During inspection, it has been observed that the said building is comprised of basement, Ground plus one upper floor. The Basement is served by two staircases. Ground & upper floor are served by three staircases. Fire safety arrangements such as Fire Extinguishers, Hose reels, Sprinkler system etc. are provided. However the following shortcoming was observed:-

1. Width of main gate is less than the required width 3.8m (as per letter dated 23/07/2018)


You are requested to comply the above mentioned shortcoming under intimation to this department for further necessary action.

Yours Faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire officer
Delhi Fire service

Copy to: -

1. Directorate of Education Old Secretariat Delhi – 110054

o/c

24/03/2021