GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2021/ 184

Dated: 05 04 202

To,

The Principal, Govt. Sr. Sec, School Sector-22, Phase-III, Rohini Delhi-85.

**Sub:** Renewal of Fire Safety Certificate in r/o Govt. Co-ed Sarvodaya Vidyalaya at Sector-22, Phase, Rohini, Delhi-85.

Sir,

Kindly reference to letter No. GCSV/22/RHN/1713 dated 03.03.2021, received in this department in outdoor diary no. 11766 on 09.03.2021 on the subject cited above. In this connection it is to inform you that the shortcoming already issued by this department letter of even No. 694 dated 20.10.2020 (Copy enclosed) in favor of Govt. Sr. Secondary school. Therefore, you are advised to submit point-wise compliance of shortcomings issued vide this department letter dated 20.10.2020 along with clarification on name change of the school for further consideration in this matter.

Yours faithfully

(Dharmpal Bhardwaj) Dy. Chief Fire Officer Tel;-01123414250

DIL

Encl: As above

The Director of Education, GNCT of Delhi Old Secretariat, Delhi-110054.

e/12

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001.

No. F6/DFS/MS/WZ/2020/ 694 To, Dated: 20/10/2020

The Principal, Govt. Sr. Sec, School Sector-22, Phase-III, Rohini Delhi-85.

Sub: Renewal of Fire Safety Certificate in r/o Govt. Sr. Sec, School, Sector-22, Phase-III, Rohini, Delhi-85.

Sir,

This is in reference with your letter No. nil dated july 2020 received in outdoor diary no. OD no.6685 Dated 17.08.2020 on the subject cited above. The premise was inspected by the concern nominated authority of this department in presence of Mr. Ashok Dabas (Estate Manager) on 15.09.2020 to verify the compliance of fire prevention and fire safety measures required under the rules. The renewal of FSC is rejected under sub rule (3) of Rule 37, in the view of reasons mentioned below:

- 1. Fire fighting system is not in working condition.
- 2. Floor landing signage's in stair found removed at some staircases.
- 3. Exit signage found removed at some places.
- 4. Staircase door of basement is opening in opposite direction as required in NBC-2011.

In this regard as stipulated in sub Rule (1) of Rule 37 of DFS Act-2007 & Rules 2010 you are advised to apply again in Form "J" along with a declaration from owner/occupier on Form "K" as required under Rule 38 that all the fire prevention and fire safety measures provided in the building/premise are in best repairs. The web links for DFS Act-2007/ Rules 2010 & Form "J" & "K" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

Yours Faithfully

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123412050

My