GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/2021/NDZ/School/ 312

Dated: 28/06/2021

To,

The Principal (Single Shift), E.D.M.C. Primary School, Chand Mohalla-1, Gandhi Nagar, Delhi-110031

Sub:- Regarding issuance of Fire Safety Certificate (NOC).

Sir,

With reference to email ID hos1051132@gmail.com dated 30/03/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school building on 16/06/2021, it was noted that the shortcomings issued vide letter No. F6/DFS/MS/2017/1354 dated 23/05/2017 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours Faithfully,

(Dr. S. K. Tomar) Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC, 419, Udyog Sadan, Patparganj Industrial Area, Delhi-110092

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No. F6 | DFS | ms | 2017 | 1354

Dated: 23/05/2017

To.

The Principal (1st Shift) EDMC Primary School, Chand Mohlla Gandhi Nagar, Delhi-93.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o EDMC Primary School, Chand Mohlla Gandhi Nagar, Delhi-93.

Madam,

Please refer to your letter dated 22/02/17 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the NBC Part IV. Smt. Usha Rani (Teacher) was present at the time of inspection and it was observed that the school building is now comprised of ground plus Two upper floors and have following shortcomings:-

- 1. The width of second staircase is less than required width of 1.50 m.
- 2. Only three fire extinguishers provided in place of six.
- 3. First Aid Hose reels not provided.
- 4. Fire pump having 450 LPM output at 40 m head not provided.
- Overhead water tank of 10,000 ltrs.capacity not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

(Vipin Kental) Chief Fire Officer

Copy to:-

- The Director of Education, East Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi-92
- The Principal EDMC Primary School (2nd Shift) Chand Mohlla Gandhi Nagar, Delhi-93.