

e-11

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE : NEW DELHI - 110001**

No. F 6 / DFS / HQ/ 2021/ 331

Dated 05/07/2021

To,

The Principal  
M.C. Primary Girls School,  
Burari, Delhi-110084.

Sub: - Issuance of Fire Safety Certificate in r/o M.C. Primary Girls School, Burari, Delhi-110084.

Sir,

This has reference to your letter no. Nil dated 03.04.2021 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 10.06.2021 in presence of Sh. R.P. Singh (Principal) and verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no. 4268 dated 18.07.2019 and observed that the shortcomings have not been removed so far.

Keeping in view of above, Fire Safety Certificate can not be considered at this stage.

Yours faithfully,

  
(Atul Garg)  
Director

Ph: 011-23414250

o/c p

C-6

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/HQ/2019/ *School/4268*

Dated *18/07*/2019

To,

The Principal  
M.C. Primary Girls School,  
Burari, Delhi-110084.

**Sub:** - Regarding issuance of fire safety certificate in r/o M.C. Primary Girls School, Burari, Delhi- 110084.


Sir,

Please refer to your letter no.01 dated 18.01.2019 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department to verify the fire safety measures installed in the building as per NBC Part 4 and observed that the school premise is comprised of newly constructed 03 blocks (150 sq.y x 02 blocks & 300 sq.y x 01 blocks) of having ground and two upper floors. At the time of inspection Sh. Rajeshwar Parshad Singh, Principal was also present at site. During the course of inspection observations/ shortcomings made are as under:-

1. Hose reel hose provided in each blocks but not functional.
2. Pump capacity of 450 LPM with 40 mtr head provided in each blocks but not functional.
3. Overhead tank capacity of 5,000 ltr provided in each blocks found empty.

Keeping in view of above, fire safety certificate cannot be considered at this stage

Yours faithfully



(Atul Garg)  
Chief Fire Officer  
Ph: 011-23414250

