

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI -110001**

No.F6/DFS/MS/NDZ/2021/ 338

Dated:- 12/07/2021

To

The Principal,  
EDMC Primary School No.1,  
New -1, WB-Block, Delhi - 92.

**Sub:- Regarding issuance of Fire Safety Certificate in r/o EDMC Primary School No.1, New -1, WB-Block, Delhi - 92.**

Sir,

This has reference to your email dated 07/04/2021 on the subject cited above. In this regard, it is to inform you that the site was re-inspected by the officer concerned of this department on 03/07/2021 in the presence of Mr. Arun Bhadle (H.O.S) & Mrs. Jai Shree Bharati (Teacher) and observed that the shortcomings already communicated by this department vide letter No. F6/DFS/MS/2015/2171 dated 26/10/2015 (photocopy enclosed) has not been rectified.

Hence, the Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under the intimation to this department for further necessary action in this regard.

Yours faithfully



**(Dr. S.K. Tomar)**  
Dy. Chief Fire Officer  
Delhi Fire Service



Encl: as above

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. F6/DFJ/MS/2015/2171

Dated 26/10/15

To,

The Principal  
EDMC Primary School, Shakarpur No. 1,  
New-1, WB-Block, Delhi-92.

Sub: - Regarding issuance of Fire safety certificate/NOC from fire safety point of view in r/o EDMC Primary School, Shakarpur No. 1, New-1, WB-Block, Delhi-92.

Madam,

With reference to your letter no. nil dated 21.05.2015 on the subject cited above it is to inform you that officer concerned of this department has inspected the School to ensure the fire safety arrangements on 14.07.2015, in presence of Mrs. Renu Sharma (Principal). During course of inspection the following short comings were observed in school building comprising of ground plus two upper floors.

1. Main gate is provided 3.70 meter wide in place of required 4.5 meter.
2. Three fire extinguishers are provided in place of six fire extinguishers as required.
3. First aid hose reel not provided.
4. A fire pump having 450 LPM not provided.
5. An overhead water tank having 10,000 liters capacity not provided.
6. Exit signs not provided.

Keeping in view of above, the school building cannot be considered for issuance of fire safety certificate, at this stage. Therefore you are advised to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours faithfully

  
(Rajesh Panwar)  
Dy.Chief Fire Officer  
Ph:-011-23412025

90 R6

Copy to:-

The Director of Education, EDMC,  
Udyog Sadan, Plot No.419, 1st Floor, FIE,  
Patparganj Industrial Area, Delhi-110092.