

329

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No. F6/DFS/MS/WZ/2021/ 341

Dated: 12/07/2021

To,

The Principal,  
Government Sarvodaya Bal Vidyalaya,  
Ramesh Nagar, New Delhi – 110015(I.D.1516002)

Subject: Inspection Report in r/o of Government Sarvodaya Bal Vidyalaya, Ramesh Nagar,  
New Delhi – 110015


Sir,

This is in reference to your Email dated 10/06/2021 on the subject cited above. In this connection it is to inform you that the premises was inspected by officer concerned of this department on 30/06/2021 in the presence of Sh. Dr. Sabya Sachin (Principal) to check the fire safety arrangements. During inspection it was observed that the Said Building/premises Comprised of Ground plus Three Upper Floors. Fire Safety arrangements Such as Fire Extinguishers, Hose reels, Fire Pump, Overhead water storage Tank, etc. are provided. However, following shortcomings were observed.

1. Hose reel Hose are provided but found leakage.
2. Fire pump of 450 lpm with 40m head automatic in operation found not functional.
3. Exit Signage's are found removed.

In view of above Shortcomings the application for renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety Arrangements Shall be at the risk and liabilities of the Owner/occupier. The Licensing authority /statutory authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
(Dharampal Bhardwaj)  
Dy. Chief Fire Officer,  
Delhi Fire Service

Copy to:-

The Directorate of Education Old Secretariat Delhi – 110054

o/c  
Shudh  
09/07/2021