

G19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 344

Dated: 14/07/2021

To,


The Dy. Director (Edn.),
West Zone, SDMC, Education Department,
New Delhi.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o S.D.M.C Primary School, Hastal Village No.-I-II, New Delhi-110059.

Sir,

This has reference to your letter no. Nil dated 09/06/2021 on the subject captioned above. In this connection, it is to inform you that the premises was inspected by the officer concerned of this department in the presence of Principal to verify the compliance of Shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/5702 dated 20/09/2019 & F6/DFS/MS/School/2020/SZ/435 dated 30/04/2020 which is still not complied. The management will be held responsible for any untoward incident for the period if compliance is not made. Hence the case for NOC from fire safety point of view is rejected.

Yours faithfully



(Sunil Chawdhary)
Dy.Chief Fire Officer

9/45

Copy to:-

Director of Education,
S.D.M.C, Civic Centre, Minto Road,
New Delhi-110001.

The Principal,
S.D.M.C. Primary School,
Hastal Village No.-I-II, New Delhi-110059.

e/2

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ/ 435

Dated: 30/4/2020

To,

The Dy. Director (Edn.),
West Zone, SDMC, Education Department,
New Delhi.

Sub: - Regarding issuance of Fire Safety Certificate in r/o S.D.M.C. Primary School, Hastal Village No.-I-II, New Delhi-110059.

Sir,

This has reference to your Letter No. D/6384/DDE/WZ dated 03.02.2020 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 05.03.2020 to see the shortcomings already communicated by this department vide letter no. F.6/DFS/MS/School/2019/SZ/5702 dated 20.09.2019 in the presence of Sh. Om Prakash Meena (In-charge) & it was observed that shortcomings have not been fully complied so far.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.


Yours Faithfully,


(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. Director of Education,
S.D.M.C, Civic Centre, Minto Road,
New Delhi – 110001
(with a request to take further action as school does not have fire NOC)
2. The Principal,
S.D.M.C. Primary School,
Hastal Village No.-I-II, New Delhi-110059


Atul Garg
30/4/2020

98

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ/ 5702

Dated: 20/9/19

To

The Principal,
S.D.M.C Primary School,
Hastsal Village No.-I-II, New Delhi-110059.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. S.D.M.C Primary School, Hastsal Village No.-I-II, New Delhi-110059.

Madam,

This has reference to your letter No. Nil dated 31.05.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 20.08.2019 to see the compliance of the requisite fire safety measures. Sh. Mukesh Kumar (Principal) was present at the time of inspection.

During the course of inspection it was observed that the School building is comprised of ground plus three upper floors. The upper floors are served by two staircases having width 135 cms each. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. School building is not approachable through 4.5 meter wide main gate.
2. The upper floors are served by two staircases having width 135 cms each against required two staircases having width 150 cms each.
3. Required fire extinguishers are not provided. Nine fire extinguishers of DCP type/CO₂ type 2.5 Kg Capacity each are require to be provided.
4. Hose Reels system not provided.
5. Fire pump of 450 LPM capacity not provided.
6. Overhead water storage tank of 10,000 ltrs capacity not provided.
7. Exit signs are not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for renewal of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)

CHIEF FIRE OFFICER

Copy to:-

Director of Education,
S.D.M.C, Civic Centre,
Minto Road, New Delhi-110001