GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 373

Dated: 27/07/2021

To,

The Principal, M.C. Bharti Public School, S-69,Param Puri, New Delhi-110059.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o M.C. Bharti Public School, S-69,Param Puri, New Delhi-110059.

Sir,

This has reference to your letter no. Nil dated 30/06/2021 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 12/07/2021 in the presence of Principal to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/2656 dated 07/05/2019 and observed that shortcomings are still not complied. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully

(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

 The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

015

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ/ 26 576

Dated:

7/5/18

To,

The Principal,

M.C. Bharti Public School,

S-69, Param Puri, New Delhi-110059

Sub: - Regarding issuance of Fire Safety Certificate in r/o M.C. Bharti Public School, S-69, Param Puri, New Delhi-110059.

Sir,

This has reference to your Letter No. Nil dated 19.03.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 04.04.2019 to see the compliance of the requisite fire safety measures. Smt. Payal (Care taker) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground plus one upper floor in a three storied building. The upper floor is served by single staircase having width 90 cms. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

- 1. The upper floor is served by single staircase having width 90 cms against required width of 150 cms. The width of staircase shall be increased to 150 cms or an additional staircase having width not less than 75 cms is to be provided.
- 2. Door width is 90 cms against required width of 100 cms.

3. Required fire extinguishers are not provided. Four fire extinguishers of DCP type/CO₂ type 2.5 Kg Capacity each are require to be provided

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully

(A JUL GARG) CHIEF FIRE OFFICER

Copy to:-

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054