300

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/NDZ/2021/399

Dated:- 05/08/2021

To

The Principal, EDMC Primary Pratibha co-ed School, J&K block, Laxmi Nagar, Delhi-92.

Sub: Regarding grant of FSC in r/o EDMC Primary Pratibha co-ed School at J&K block, Laxmi Nagar, Delhi-92.

Sir,

This has reference to your email dated 23/07/2021 on the subject cited above. In this regard, it is to inform you that the site was re-inspected by the officer concerned of this department on 29/07/2021 in the presence of Mrs. Kalpna Raj (Principal) and observed that the shortcomings already communicated by this department vide letter No. F6/DFS/MS/School/2016/1483 dated 08/06/2016 (photocopy enclosed) has not been rectified.

Hence, the Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under the intimation to this department for further necessary action in this regard.

Yours faithfully

(**Dr. S.K. Tomar**)
Dy. Chief Fire Officer

Delhi Fire Service

8 C

Encl: as above

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

F6/073/ms/scharl/2016/1482

Dated: 08/06/16

To,

The Principal,

EDMC Primary Pratibha co-ed School,

J&K block, Laxmi Nagar, Delhi-92.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o EDMC Primary Pratibha co-ed School J&K block, Laxmi Nagar, Delhi-92. Sir/Madam,

Please refer to your letter dated 05/05/2016 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection Smt. Kalpna Raj (Principal) was present and it was observed that the school building is comprised of ground plus Two upper floors and have following shortcomings:-

- An additional staircase width of 1.5 m required in place of provided .80 m.
- 2. First Aid Hose reels not provided.
- Fire pump having 450 LPM out put at 40 m head not provided. 3.
- 4. Overhead water tank 10,000 ltrs.capacity not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully.

(Rajesh Panwar) Dy. Chief Fire Officer Ph.011-23412025

Copy to:-

1. The Director (Education) East Delhi Municipal Corporation, 419, Udyog Sadan, Patpargang, Industrial Area Delhi-92.