

E 29

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 409

Dated: 10/08/2021

To,


The Principal,
SDMC Primary School,
Rajouri Garden Extension, New Delhi-110027.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o SDMC Primary School, Rajouri Garden Extension, New Delhi-110027.

Sir,

This has reference to your letter no. Nil dated 24/07/2021 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 26/07/2021 in the presence of Smt. Sonia Arora (Principal) to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2020/SZ/417 dated 30/04/2020 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully



(Sunil Chawdhary)

Dy. Chief Fire Officer

0/0/0

Copy to:-

1. The Director of Education,
S.D.M.C. Civic Centre, Minto Road, New Delhi-110001.

C/26.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ/ 417
To

Dated: 30/4/2020

The Dy. Director of Education,
West Zone, SDMC, Education Department,
New Delhi.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. S.D.M.C Primary School, Rajouri Garden Extn., New Delhi-110027.

Sir,


This has reference to your letter No. D-6384/DDE/WZ dated 03.02.2020 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 19.03.2020 to see the compliance of the requisite fire safety measures. Smt. Seema Arora (Principal) was present at the time of inspection.

During the course of inspection it was observed that the School building is comprised of Ground plus two upper floors & MP Hall is at Ground floor only. The upper floors are served by two staircases having width 200 cms and 125 cms. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The upper floors are served by two staircases having width 200 cms and 125 cms against the required three staircases of 150 cms (02 no.'s) each and an additional staircase of 135 cms on the end of the MP hall side to meet the travel distance.
2. Doors having width of 02 meters (02 no.'s) are not provided in MP Hall.
3. Hose reel system not provided in MP hall.
4. Fire pump having capacity 450 LPM (02 no.'s) is not provided.
5. Overhead water storage tank of 10,000 ltrs capacity provided against required 15,000 ltrs. capacity.
6. Illuminated exit signs are not provided in MP hall.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,


30/4

(S.S. TULI)
Dy. CHIEF FIRE OFFICER
SOUTH ZONE

Copy to:-

1. Director of Education,
S.D.M.C, Civic Centre,
Minto Road, New Delhi-110001
(With a request to take further action as school does not have fire NOC)
2. The Principal,
S.D.M.C Primary School,
Rajouri Garden Extn., New Delhi-110027

S/C
30/4/2020