GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 4/1

Dated:

13/08/2021

To,

The Principal, Supreme Model School, D-1-29, OM Vihar Phase-5 Extension, Uttam Nagar, New Delhi-110059.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Supreme Model School, D-1-29,OM Vihar Phase-5 Extension,Uttam Nagar, New Delhi-110059.

Sir,

This has reference to your letter no. Nil dated 03/08/2021 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 04/08/2021 in the presence of Sh. Rajender Yadav to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/3848dated 26/06/2019 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully

(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

C12

No: F.6/DFS/MS/School/2019/SZ / 3848

Dated: 26/6/19

To,

The Principal, Supreme Model School, D-1-29, Om Vihar Phase-5 Ext., Uttam Nagar New Delhi-110059.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Supreme Model School, D-1-29, Om Vihar Phase-5 Ext., Uttam Nagar New Delhi-110059.

Sir,

This has reference to your Letter No. Nil dated 28.03.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 01.05.2019 to see the compliance of the requisite fire safety measures. Sh. Dixit Kumar (Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus one upper floor was issued FSC by this department vide letter F.6/DFS/MS/2006/2484 dated 13.09.2006. The school is now comprised of Ground plus two upper floors. The upper floors are served by two staircases having width 110 & 100 cms each. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

- 1. The upper floors are served by two staircases having width 110 & 100 cms each against required two staircases having width 150 cms & 135 cms each.
- 2. Doors having width 90 cms provided against required 120 cms on second floor.
- 3. Required fire extinguishers are not provided. Seven fire extinguishers of DCP type/CO₂ type 2.5 Kg Capacity each are require to be provided.
- 4. First aid hose reel system is not provided.
- 5. Fire pump of 450 LPM capacity is not provided for hose reel system.
- 6. Overhead water storage tank of 10000 ltrs. capacity is not provided for hose reel system.
- 7. Exit signs are not provided.
- If student capacity is more than 45 in any class room then double door having width 100 cms on ground floor & first floor and 120 cms on second floor are required.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Eaithfully

(APUL GARG

CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi – 110054
(with a request to take further action as school does not have fire NOC)