

E6

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2021/SZ/ 420

Dated: 17/08/2021

To,


The Principal,
B.D. Public School, RZ-B-1,
Jeevan Park, Uttam Nagar, New Delhi-110059.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o B.D. Public School, RZ-B-1, Jeevan Park, Uttam Nagar, New Delhi-110059.

Sir,

This has reference to your letter no. Nil dated 21/07/2021 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 06/08/2021 in the presence of Sh. Brijesh Kumar to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2017/SZ/261 dated 27/01/2017 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully


(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

1. The Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi-110054.

03

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2017/SZ

261

Dated: 27/01/17

To,

The Manager,
B.D. Public School, RZ/B-1,
Jeevan park, Uttam Nagar,
New Delhi-110059

Sub: - Regarding renewal of Fire Safety Certificate in r/o B.D. Public School, RZ/B-1, Jeevan park, Uttam Nagar, New Delhi-110059.

Sir/Madam,

This has reference to your Letter No. Nil dated 20.11.2016 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 20.12.2016 to see the compliance of the requisite fire safety measures as per Delhi Fire Service Rules 2010. Smt. Neetu (Teacher) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus two upper floors of a four storied building. The upper floors are served by two staircases having width 77 & 122 cms. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The upper floors are served by two staircases having width 77 & 122 cms, against required width of 150 cms and 75 cms.
2. Door width in each class room is 96 cms against required 100 cms.
3. One CO₂ type Fire Extinguishers of 4.5 kg/2.2 kg capacity each and five ABC type Fire Extinguishers of 04 kg capacity each or WCO₂ type Fire Extinguishers of capacity 09 ltrs each are not provided.
4. Hose Reel System not provided.
5. Terrace fire pump having capacity 450 LPM not provided.
6. Over head water storage tank having capacity 10000 ltrs. not provided.
7. Exit signs not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

u
27/1

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054

o/c Secy
27/17