

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. F.6/DFS/MS/EH/2020/SZ/ 69

Dated: 11/01/2021

To

The Medical Officer
Health & Licensing Authority,
Health Department, NDMC,
Parliament Street, New Delhi-110001

Sub: Regarding renewal of Fire Safety Certificate in r/o The Foreign Correspondents Club of South Asia located at AB-19, Mathura Road, New Delhi-110001


Sir,

This is with reference to your Email dated 28/12/2020 received in this department on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection on 05/01/2021 in the presence of Mr. Sanjeev Kumar Verma (Asstt. Manager). During inspection following shortcomings have been observed:

1. First Aid Hose Reel found nonfunctional.
2. MOEFA found nonfunctional.
3. Fire Pump on terrace found nonfunctional.
4. Overhead tank of capacity 10,000 ltrs found empty.
5. Exit Signage missing at some place.

Keeping in view of above, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully


(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to: -

1. The Manager, M/s The Foreign Correspondent's Club of South Asia, AB-19, Mathura Road, New Delhi