

C27

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/School/2021/SZ/ 448

Dated: 01/09 /2021

To

The Principal,
SDMC Primary School,
Pul Pehladpur- II, New Delhi 110044.

Sub: Regarding issue of Fire Safety Certificate (FSC) in r/o SDMC Primary School, Pul Pehladpur- II, New Delhi 110044

Sir,

This is in reference to Gmail dated 12/08/2021 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 17/08/2021 in the presence of Sh. Ram Prasad Meena (Principal) and observed that the shortcoming intimated vide letters of even nos 2648 dated 18/12/2015 has yet not been complied. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Encl: As above

Yours faithfully

(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)

DM

Copy to:-

1. The Director of Education, South MCD, Civic Centre, Minto Road, New Delhi 110002

e/10

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

E-mail: gargatul@hotmail.com, Tel:- 011-26189168

No. FG/DFS/MS/School/2015/2648

Dated: 18/12/15

To,

Principal,
SDMC Primary School,
Pul Pehladpur-II, New Delhi-110044.

Sub: - Inspection report in r/o SDMC Primary School, Pul Pehladpur-II, New Delhi-44, from fire safety & means of escape point of view.

Sir,

With reference to your letter No. nil dated 03-12-2015 on the above cited subject, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department on 10.12.2015 in your presence to check the fire safety arrangements in the school building.

During inspection, it has been observed that the said school building was granted Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2012/4844 dated 31.12.2012 for ground floor (Block-1 & Block-2). But now the management has constructed one more block comprised of ground plus two upper floors served by 02 staircase having width 1.45 mts. & 1.50 mts.. The following fire safety & means of escape arrangements are required: -


1. Overhead water tank capacity 10,000 liters.
2. Hose reel at each floor.
3. Terrace pump capacity 450 LPM.
4. Exit signages at places mentioned during inspection.
5. Fire extinguishers at places mentioned during inspection.

In view of the above, 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the shortcomings under intimation to this department for taking further action as necessary for issuance of fire safety certificate.

Yours faithfully


(ATUL GARG)

DY.CHIEF FIRE OFFICER

9c 
18/12/15