

C25

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2021/ 461

Dated: 02/09/2021

To,

Sh. Vipin Bhatia (Secretary),
Delhi International Junior School,
Pocket- H-3, Sector-11,
Rohini, Delhi-110085.

Sub: Issuance of Fire Safety Certificate in r/o Delhi International Junior School, Pocket- H-3, Sector-11, Rohini, Delhi-110085.

Sir,

Kindly reference to online mail dated 24.06.2021, received in this department on the subject cited above. In this connection it is to inform you that the shortcoming already issued by this department letter of even No. 4837 dated 30.11.2018 (Copy enclosed). Therefore, you are advised to submit point-wise compliance of shortcomings issued vide this department letter dated 30.11.2018 and building plans drawn on scale of 1:100, for further consideration in this matter.

Yours Faithfully

(Atul Gang)

DIRECTOR

Ph; 011-23414000

o/c
my

C/14

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/ 2018/ *School/4837*

Dated *30/ 4* /2018

To,

The Principal
Delhi International Junior School,
Pocket-H-3, Sector-11,
Rohini, Delhi-110085.

Sub: - Regarding issuance of fire safety certificate in r/o Delhi International Junior School,
Pocket- H-4, Sector-11, Rohini, Delhi-110085

Sir,

This has reference to your letter no. nil dated 29.05.2018 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department to verify the fire safety measures in accordance with the provision contained in NBC Part 4 and observed that the school building is comprised of basement, ground and 03 upper floors on a total plot area measuring 800 sqm. At the time of inspection Mrs. Juhi Chopra, Principal was also present at site and the observations made are as under:-

1. There are two staircases in the building having width of 1.50m & 1.35m respectively, communicating from basement to ground and upper floors. The second staircase shall be increased to 1.50 mtr. wide as per NBC Part IV.
2. Exit Signage not provided.

Keeping in view of above, fire safety certificate cannot be considered at this stage.

Yours faithfully

(Signature)
(Atul Garg)

Chief Fire Officer
Ph: 011-23414250

(Signature)