

C 25

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001**

No. F6/DFS/MS/School/2021/SZ/ 467

Dated: 03/09/2021

To,


The Principal ,
S.D.M.C Primary Boys School,
Tilak Nagar No.-4 II, New Delhi-18.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o S.D.M.C Primary Boys School, Tilak Nagar No.-4 II, New Delhi-18.

Sir,

This has reference to your letter no. Nil dated 07/08/2021 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 21/08/2021 in the presence of Smt. Rajni Sahni (Principal) to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2020/SZ/434 dated 30/04/2020 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully



(Sunil Chawdhary)

Dy. Chief Fire Officer

o/c

Copy to:-

1. The Director of Education,
SDMC Civic Centre, Minto Road,
New Delhi-110001.

c-22

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ /434

Dated: 30/4/2020

To,

The Dy. Director of Education,
West Zone, SDMC, Education Department,
New Delhi.

Sub: - Regarding fire inspection in r/o S.D.M.C Primary Boys School, Tilak Nagar No.-4 II, New Delhi-110018.

Sir,

This has reference to your Letter No. D/6384/DDE/WZ dated 03.02.2020 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 05.03.2020 to see the compliance of the requisite fire safety measures. Sh. Ashok Kumar (In-charge) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus two upper floors. The upper floors are served by two staircases having width 150 cms each. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The upper floors are served by two staircases having width 150 cms each but second exit is not usable.
2. Overhead water storage tank of 9000 ltrs. capacity provided against required 10,000 ltrs.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(Signature)
(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. Director of Education,
S.D.M.C, Civic Centre, Minto Road,
New Delhi - 110001
(with a request to take further action as school does not have fire NOC)
2. The Principal,
S.D.M.C Primary Boys School,
Tilak Nagar No.-4 II, New Delhi-110018

07/3/20
22/4/2020