GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. FG|DFS|MS|2021 1889

Dated: 16/09/2021

To.

ACP / HQ For Dy. Commissioner of Police, IGI Airport Unit, 1st Floor PS IGI Airport (T-3), New Delhi-110037.

Subject:- Inspection report in r/o M/s Police Station cum DCP Office at IGI Airport, Near Terminal-3, New Delhi-110037, from Fire Safety and means of escape point of view. Sir,

Please refer to your letter No. 1850/Genl. Br./IGIA Dated 30/07/2021 on the subject noted above, in this connection, it is to inform you that the said premises was visited by the officer concerned of this department on 26/08/2021 in the presence of Mr. Kirit Parmar (Crew Commander GMR) & Mr. Sanjay (Delhi Police) and observed that the building comprised of Basements, Ground & Four Upper Floors.

However following shortcomings were observed during the time of inspection:-

- Hose Reel Hose provided but found nonfunctional.
- 2. Detectors found removed in the corridors in all floors & in some office rooms.
- 3. Internal Hydrant provided but found nonfunctional.
- 4. Fire pumps are not on auto mode / system is not integrated.
- 5. Pressurization at lift lobby & lift shaft were provided but found nonfunctional.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected.

The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Copy to:- for information.

 The Executive Vice President, DIAL, New Udaan Bhawan, Terminal-3, IGI Airport, New Delhi-110037.