

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI – 110001**

NO. F6/DFS/MS /SZ/2021/ CGHS/ 1836

DATED: 10 /09/2021

To,

Mr. Tushar Sharma
The Sleuth's CGHS Ltd.
Plot No 6, Sector – 19B, Pocket –A,
Dwarka, New Delhi – 110075

Subject: Renewal of Fire Safety Certificate iro The Sleuth's CGHS Ltd. Located at Plot No 6, Sector – 19B, Pocket –A, Dwarka, New Delhi – 110075.

Sir,

Please refer to your LETTER (Form J) Dated 05/08/2021 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 27/08/2021 to see the compliance of the shortcomings communicated vide this office letter no. F6/DFS/MS/SZ/2021/CGHS/1649 dated 19/08/2021 and found that the shortcomings are still not complied.

You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

Atal Garg)
Director,
Delhi Fire Service.

Copy to; - The Chairman, DDA, Vikas Sadan, INA, Delhi-110023

10/09/21
o/c

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI – 110001**

No.F.6/DFS/MS/SZ/2021/ *CGHS/1649*

Dated: *19*/08/2021

To,

Mr. Pankaj
The Sleuth's CGHS Ltd.
Plot No 6, Sector – 19B, Pocket –A,
Dwarka, New Delhi – 110075.

Subject: Renewal of Fire Safety Certificate iro The Sleuth's CGHS Ltd. Located at Plot No 6, Sector – 19B, Pocket –A, Dwarka, New Delhi – 110075.

Sir,

Please refer to your Email dated 13/07/2021 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by the officer concerned from this department on 29/07/2021 for fire safety point of view.

The following shortcoming was observed during the time of inspection:-

1. The stairs are found locked at terrace same may be kept open.
2. Hoses and Couplings are found missing at some places.
3. MOEFA found nonfunctional.
4. Terrace pump found nonfunctional in auto mode.

You are requested to comply the above mentioned shortcomings under intimation to this department for further necessary action.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,



(Atul Garg)
Director,
Delhi Fire Service.

Copy to; - The Chairman, DDA, Vikas Sadan, INA, Delhi-110023

12/8/21